

MASTER INDEX

MFG/TITLE/VOLUME/ISSUE

Misc Understanding Processors 1 1
Williams Contact-Disco Fever-Aristocrat 1 1
Exidy Star Fire 1 1
Gottlieb Prom Tester 1 1
Bally Stern Solenoid Problems 1 1
Gottlieb Power-Up Problems 1 1
Atari Video Football 1 1
Stern Pin Games With Electronic Sound 1 1
Misc Understanding Processors 1 2
Gottlieb Memory Modification 1 2
Williams Disco Fever ROM Modification 1 2
Stern Wild Fyre Operator's Manual Addition 1 2
Gottlieb Modifying Cleo/Sinbad/Joker Poker for Electronic Sound 1 2
Bally Stern Display Module Theory of Operation 1 2
Misc Customer Service Numbers 1 2
Misc Understanding Processors 1 3
Allied Leisure Cocktail Pin Modification 1 3
Atari New Solenoid Circuitry 1 3
Atari Modifications for Improving Older Videos 1 4
Misc T'shooting I.C. Power Supplies 1 4
Atari Steering Board Assemblies 1 4
Atari Football - Bruce Amusements Corp 1 4
Atari Superman Memory Characteristics 1 5
Stern ROM Interchangeability 1 5
Atari Drag Race 1 5
Gottlieb Power Supply + 5v and +60v Adjustment 1 5
Atari Superman Driver Transistors 1 5
Bally Modifying PS/SD Tester to Accommodate Sound Modules 1 5
Midway Space Invaders 1 5
Misc Solid State Pinball - Remember the Playfield 1 6
Rock-Ola #478 Modifications 1 6
Gremlin How to Tune 49MHz Receivers & Transmitters 1 6
Rock-Ola Output Transistor Replacements 1 6
Allied Leisure Cocktail Pin PWR Supply 1 6
Midway RAM/ROM Self Testing 1 6
Bally Kiss Option Error 1 6
Misc Transistor Testing 1 7
Rock-Ola #478 Protective Retrofit Assembly 1 7
Rock-Ola #478 Turntable Motor Noise Suppressor Components 1 7
Misc Video Test Cable - A T'shooting Aid 1 7
Atari Superman Add-A-Ball Modification 1 7
Cinematronics Starhawk 1 7
Atari Quack & Outlaw Gun Harness Diagrams 1 7
Atari Subs Modification 1 7

Exidy Crash Option 1 7
Stern Hot Hand Modification 1 7
Misc Understanding Processors 1 8
Atari Baseball Rom Modification 1 8
Stern Dynamic Self Test 1 8
Rock-Ola Amp Repairs-Models 454 to 474 1 8
Rock-Ola Amp Repairs-Models 477 & 478 1 8
Midway Space Invaders Modification 1 8
Misc New Customer Service Numbers 1 8
Williams Flash Roms & Poms 1 8
Exidy Star Fire Power Supply Schematic 1 8
Atari X-Y Monitor Adjustment 1 9
Cinematronics Hi-Voltage Modification 1 9
Atari Submarine Maintenance Bulletin #Nav 648795610 1 9
Gottlieb Transformer Modification 1 9
Misc Fluorescent Lamps Reference Chart for Phonographs 1 9
Cinematronics Service Report 1 9
Midway Seawolf II Custom Chip I.D. 1 9
Midway Space Invaders Upright & Cocktail Table 1 9
Bally Stern High Voltage Regulator 1 10
Rock-Ola Filter Capacitors for 477-478 (52280-A) Amps 1 10
Rock-Ola Amplifier Filter Capacitors 1 10
Stern Meteor Front Door Programming 1 10
Gottlieb Match Feature Test 1 10
Atari Lunar Lander Modification 1 10
Vectorbeam Warrior Service Note 1 10
Midway Sea Wolf/Space Invader Power Supplies 1 10
Gottlieb Game Proms 1 11
Stern Meteor Rom Modification 1 11
Rock-Ola 477 & 478 Phonographs Credit Modification #52225-A/1A 1 11
Rock-Ola 473-474-468-1 Phonographs Out of Production 1 11
Cinematronics T'shooting Hints 1 11
Misc Coin Switch Sensing 1 11
Midway Space Invader Tips 1 11
Midway Submarine 1 11
Gottlieb T'shooting Power Supplies (Part 1) 1 12
Williams Pin Game Pricing Schemes 1 12
Atari Asteroids Modifications 1 12
Misc Identifying Resistors and Capacitors 1 12
Gottlieb Personality Prom I.D. 1 12
Rock-Ola Static Kits #2308 & #2309 1 12
Atari Basketball Modification 1 12
Misc Speaker Volume Control 1 12
Gottlieb T'shooting Power Supplies (Part 1) 2 1
Cinematronics Sundance Schematic Changes 2 1
Bally Playboy Transformer Schematic Misprint 2 1
Quadrascan Monitor Repair (Part 1) 2 1

Rock-Ola Constant Scan Condition 2 1
Midway Super Speed Race & Sea Wolf II Color Monitor Conn 2 1
Quadrascan Monitor Repair (Part 2) 2 2
Atari Asteroids Switch Settings 2 2
Rock-Ola Changing Carriage Housings 2 2
Misc New Customer Service Numbers 2 2
Midway Service Bulletin 2 2
Midway Space Invaders Deluxe Eproms 2 2
Midway Deluxe Space Invader Custom Chip 2 2
Atari Asteroids PCB Revisions 2 2
Taito Space Invader 2 3
Gottlieb System 80 Service Tips 2 3
Midway Galaxian Logic Board Program ROMS 2 3
Stern Big Game ROM Mod 2 3
Stern Galaxy ROM Mod 2 3
Williams Gorgar Special Adjustments 2 3
Exidy Bandito Modification 2 3
Rock-Ola Mech Overload Problems 477-480 2 3
Bally Display Tester Blanking Modification 2 3
Williams Strobe Light Hook-up for Flash 2 3
Rock-Ola Gripper Reverse Problems 477-480 2 3
Midway Galaxian Credit Mod 2 4
Atari Sprint 4 Rom Modification 2 4
Rock-Ola Anti-Static Kits 2 4
Midway New Z-80 3-Card System 2 4
Misc Guide for Monitor Repair 2 4
Midway Galaxian Monitor Service Notes 2 4
Stern MPU-100/200 Jumper Combinations 2 4
Atari Superman-Potential Amnesia Victim 2 4
Stern Galaxy Rom Mod 2 4
Midway Space Invaders How-to Book 2 4
Atari Quadrascan Monitor Change 2 5
Atari Asteroids E-prom Kit 2 5
Midway Space Invader PWR Supply Modification% 2 5
Midway Galaxian Program I.D. 2 5
Williams R ROM and PROM Summary 2 5
Vectorbeam Monitors Demystified - Part One 2 5
Stern Solenoid Driver Cross Reference Chart 2 5
Rock-Ola Wallbox Repairs-Model 506 2 5
Atari Asteroids PCB MOD 2 5
Midway Galaxian Test Mod 2 5
Misc Quadrascan Monitor Repair Correction 2 5
Vectorbeam Monitors Demystified - Part Two 2 6
Williams New Drop Target Design 2 6
Williams Solenoid Cross Reference Chart 2 6
Midway Galaxian Service Notes 2 6
Williams Gorgar Credit Label 2 6

<http://www.startechjournal.com>

Bally Space Invaders Rom Modification 2 6
Rowe Model 447 Vendor Coin Mech 2 6
Rock-Ola CCA-5 & CCC-6 Vendors Adjustments 2 6
Bally New Spring Terminals 2 6
Taito Space Chaser & Lunar Rescue Modification 2 6
Stern Introduces Star Gazer Pinball Game 2 6
Gottlieb James Bond 007 Pin Game 2 7
Vectorbeam Monitors Demystified - Part Three 2 7
Midway Galaxian T-shooting tips 2 7
Atari Asteroids PCB Lock-up 2 7
Exidy Targ Freeze-up Modification 2 7
Cinematronics High Speed Analog Switch 2 7
Misc I.C. Removal Technique 2 7
Rock-Ola Lead Configurations for Transistors 2 7
Midway Extra Bases Ball Control Unit 2 7
Atari Asteroids Rate Multiplier Schematic 2 7
Cinematronics Monitor Ribbon Cable Orientation 2 8
Atari 2-Player Football Retrofit Kit 2 8
Allied Leisure Clay Champ Service Data 2 8
Gottlieb System 80 Control Board Interchangeability 2 8
Bally Space Invader Pin Kit # 571 2 8
Misc S*TJ Reader Survey Results 2 8
Bally Score Display T' Shooting 2 8
Bally Display Driver Module Modification 2 8
Cinematronics PROM Board to ROM Conversion 2 8
Rock-Ola Erratic Phonograph Behavior when using non-Rock-Ola Accessories 2 8
Rowe R-84 125 Watt Amplifier Service Tips 2 8
Atari Monte Carlo Support Modification 2 8
Midway Galaxians Service Notes 2 8
Stern Electronics Introduces Flight 2000 2 8
Atari Missile Command Cocktail Modification 2 9
Midway Galaxian Problems and Solutions 2 9
Cinematronics Monitor Notes & Mods: Rip Off Test Pattern 2 9
Cinematronics Monitor Notes & Mods: Contrast Adjustment on Rip Off 2 9
Cinematronics Monitor Notes & Mods: DAC-80 Modification 2 9
Cinematronics Monitor Notes & Mods: Burned Resistors in Current Amp 2 9
Cinematronics Monitor Notes & Mods: High Voltage Section Regulators 2 9
Rock-Ola Low and Lost Voltages 477-478 2 9
Bally MPU and Sound Module Memory Combinations 2 9
Rock-Ola Wrong Selections and Displays 476-480 2 9
Atari Asteroids & Missile Command IC Part # Change 2 9
Rowe AMI R-84 Phono External (Aux) Sound Sources 2 9
Midway Space Zap Interface PCB 2 10
Stern Astro Invader ROM MOD 2 10
Universal Magical Spot Audio Modification 2 10
Midway Space Encounters Monitor Adjustment 2 10
Centuri Eagle Pricing Mod 2 10

Cinematronics Modification of Vectorbeam CPU Boards 2 10
Midway Galaxian Video Cable Diagrams 2 10
Sega Gremlin Carnival & Digger Credit Modification 2 10
Centuri Eagle Monitor Notes 2 10
Misc Service Tip from Novel Pinball Company 2 10
Midway Space Encounters Upright and Mini Game Board 2 10
Exidy Targ Monitor Harness Mod 2 10
Midway Space Encounters Power Supply Mod 2 10
Williams Mechanics Maintenance Tips for Pin Games 2 11
Stern 9Ball Rom Mod 2 11
Midway Space Encounters Strobe Lite Unit 2 11
Midway Pac-Man static Kit 2 11
Midway Space Encounters Trigger Switch Kit 2 11
Centuri Targ Cocktail & Maxi Eagle Monitor Modification 2 11
Misc Microprocessor T'shooting (Part One) 2 11
Midway Pac-Man Option Switches 2 11
Atari Battlezone Warning 2 11
Rock-Ola 477-478-480 Profit Setter Mod 2 11
Williams Flipper Notes 2 12
Cinematronics Analog Switch Substitution Board 2 12
Centuri Service Notes 2 12
Bally Xenon Speech PCB 2 12
Misc Microprocessor T'shooting (Part Two) 2 12
Seeburg Service Information 2 12
Midway Space Encounters Strobe Unit Modifications 2 12
Midway Pac-Man Reset CKT 2 12
Midway Space Zap Test Equipment 2 12
Rock-Ola Loss of Displays 476-484 2 12
Midway Galaxian Substitute +5v Regulator 3 1
Atari Battlezone Control Handle Mod 3 1
Gottlieb New System 80 Service Manual 3 1
Midway Pac-Man Ram/Rom Location Code 3 1
Atari Missile Command Power Interrupt Mod 3 1
Atari Battlezone Random Score Problem 3 1
Gottlieb Auxiliary Lamp Driver Board 3 1
Misc Microprocessor T'shooting (Part Three) 3 1
Midway Pac-Man Degree of Difficulty Mod 3 1
Atari Battlezone Aux PCB Mod 3 1
Stern Berzerk Service Notes 3 1
Cinematronics Star Castle V3 Roms 3 1
Atari Asteroids Switch Maintenance 3 1
Rowe Ami Turntable Maintenance Tips 3 1
Midway Rally-X Test Mode 3 2
Misc Big Computer in One Chip 3 2
Seeburg SMC 1 & SMC 2 Potential SPKR Damage 3 2
Williams General Illumination Mod 3 2
Midway Pac-Man Cocktail Table Static PCB 3 2

<http://www.startechjournal.com>

Midway Rally-X Monitor Fuse Rating 3 2
Misc Early Warning (Field Maintenance Tips) 3 2
Rowe AMI Number Conversions 3 2
Exidy Spectar Program Update Mod 11A-1 to 11A-2 3 2
Williams C8363 Master Display Board T'shooting Procedures 3 2
Atari Missile Command Color Monitors 3 2
Williams Service Notes 3 3
Midway Rally-X Static PCB 3 3
Centuri Phoenix Options 3 3
Exidy Color Board Ribbon Cables 3 3
Rowe Ami Updating Older Phonos to Contemporary Prices 3 3
Midway Pac-Man Joystick Modification 3 3
Misc Signature Analysis (Part 1) 3 3
Atari Missile Command Diagnostic Tests 3 3
Rowe Bill Changer Modifications 3 3
Gottlieb Coil Chart 3 3
Rock-Ola Repair of Dollar Bill Programmers 3 4
Midway Galaxian & Pac-Man Substitute +5VDC Power Transistor 3 4
Centuri Phoenix Modifications 3 4
Midway Gorf Program Change 3 4
Misc Early Warning #2 (Field Maintenance Tips) 3 4
Misc Signature Analysis (Part 2) 3 4
Stern Berzerk Credit Accumulation Checklist 3 4
Stern Berzerk Joystick Mod 3 4
Misc Suggested Game Improvements 3 4
Misc Color to B&W Converter CKT 3 4
Texas Instruments Power Semiconductor Catalogs 3 4
Atari Asteroids Deluxe Program Change Kit 3 5
Stern Berzerk Joystick Adjustment 3 5
Rowe 447 Product Upgrading 3 5
Stern Scramble Power Supply Modification 3 5
Gremlin Astro Blaster Audio Modification 3 5
Wico Wiring Diagram for Manual/Remote Volume Control 3 5
Gottlieb Reset Modification 3 5
Taito Crazy Climber Joysticks 3 5
Misc Signature Analysis (Part 3) 3 5
Williams Defender System Summary 3 5
Midway Pac-Man/ Rally-X & Gorf Anti Static Cleaner Application 3 5
Williams Black Knight Service Notes 3 5
Bally Loss of All Coils 3 5
Atari Asteroids T'shooting Tips 3 5
Stern Joystick PCB T'shooting Tips 3 5
Midway Gorf Mission Self Test 3 6
Seeburg Updating older SHP Amps 3 6
Bally MPU Screening Error 3 6
Bally Lost and Found Flippers 3 6
Midway Rally X RAM Test Message Code 3 6

Stern Scramble Joystick Notes 3 6
Atari Centipede/Battlezone/Warlords/Asteroid Deluxe Notes 3 6
Bally Fireball II Clamping Diode 3 6
Game-A-Tron Space Bugger CPU Modification 3 6
Bally Fireball II Fuse Modification 3 6
Misc Early Warning #3 3 6
Misc Signature Analysis (Part 4) 3 6
Exidy Service Notes 3 6
Gottlieb Display Problems 3 6
Bally Tech Quiz (Part One) 3 6
Midway Pac-Man & Rally X Brightness Adjustment 3 6
Atari Asteroid Deluxe New Program Feature 3 6
Centuri Phoenix Upright Modification 3 6
Midway General Illumination 3 7
Bally 7 Digit MPU Modification 3 7
Centuri Hot Service Tip 3 7
Midway Wizard of Wor Maze Test 3 7
Exidy Targ & Spectar Audio Amps 3 7
Bally Tech Quiz (Part 2) 3 7
Misc Mod: 1 coin-one play machine into 2 coin-1 Play Machine 3 7
Williams Defender notes 3 7
Midway Card Rack System Compatibility 3 7
Stern Berzerk Handle Assembly 3 7
Midway Omega Race Features 3 7
Wico Joystick Report 3 7
Exidy Venture Program Change 3 7
Gremlin Space Fury Cabinet Notes 3 7
Gottlieb System 80 Sound/Speech Board 3 7
Seeburg Price-Setting Instructions (Part 1) 3 7
Midway Omega Race T'shooting Guide 3 8
Centuri Phoenix Credit Mod 3 8
Stern Berzerk Alternate Joystick 3 8
Exidy Venture Audio Diagnostic test 3 8
Bally Tech Quiz (Part 3) 3 8
Coinco Door Notes 3 8
Misc 2nd Annual S*TJ Reader Survey 3 8
Bally Rectifier Board Fuse Change 3 8
Atari Centipede Potential Shock Hazard 3 8
Stern Super Cobra Power Supply Mod 3 8
Stern Super Cobra Logic System ID 3 8
Seeburg Price-Setting Instructions (Part 2) 3 8
Atari Centipede Track-Ball Mod 3 9
Bally Centaur Service Notes 3 9
Exidy Venture Joystick 3 9
Atari Tempest Service Documentation 3 9
Midway Pac-Man - Rally X & Galaxian Coin Door Mod 3 9
Stern Super Cobra Garbled Sound Mod 3 9

<http://www.startechjournal.com>

Seeburg Price-Setting Instructions (Part 3) 3 9
Midway Omega Race Dip Switch Setting 3 9
Midway Omega Race Wizard of Wor & Pac-Man Display Glass 3 9
Gremlin Sega Space Fury Color (G-80) X-Y System Redesign 3 9
Misc Interfacing Dynamic 4027 RAMS to the Z80 3 9
Taito Moon Shuttle Program Change 3 9
Bally Tech Quiz (Part 4) 3 9
Misc AMOA Expo '81 New Game Standouts 3 10
Sega Gremlin G-80 Power Supply 3 10
Bally Fuse Changes on New Rectifier PCB 3 10
Midway Pac-Man New Program Available 3 10
Midway Omega Race Encoder Substitutions 3 10
Atari Tempest New System Preview 3 10
Misc! Two Coin/One Play Circuit Redesign 3 10
Centuri Clay Champ Xenon Tube Notes 3 10
Taito Qix Service Notes 3 10
Midway Omega Race Rom/Ram Checklist 3 10
Rock-Ola Intermittent Problems and Solutions 3 10
Gottlieb System 80 Prom List 3 10
Bally Tech Quiz (Part 4) Answers 3 10
Williams Defender Ram Failure Due to Blown Fuse 3 10
Bally Burnt Connector Solution 3 10
Exidy Monitor Adjustment Procedure 3 10
Exidy Checking Voltages on Venture 3 10
Exidy Mousetrap Special Device Notes 3 10
Allied Leisure Clay Champ Xenon Tube Notes 3 10
Gremlin Sega Coin Switch Installation 3 11
Taito Crazy Climber Video Mod 3 11
Stern Super Cobra MPU Mod 3 11
Williams Make Trax Coin Meter Installation 3 11
Williams Defender CPU Schematic Errors 3 11
Midway Galaga IC Replacement 3 11
Gottlieb Volcano Coil Change 3 11
Gottlieb Black Hole Modifications 3 11
Williams Crowbar Protection for Defender RAMS 3 11
Exidy Targ Joystick Suggestion 3 11
Taito Qix New System Preview 3 11
Atari The Book Reviewed 3 11
Matsushita Adjusting the Monitor 3 11
Midway Omega Race Power Supply Information 3 11
Atari Earom Replacement Notes 3 11
Gremlin Sega Digital Tech Test (Part 1) 3 11
Rowe BC-25 Bill Changer Notes 3 11
Exidy Venture Audio Color Board Modifications 3 11
Misc Monitor Jiggle/Audio Interference 3 11
Wells Gardner Monitor Blooming Mod 3 11
Nintendo Donkey Kong Service Notes 3 12

Midway Galaga Z-80-A CPU 3 12
Atari Tempest Program Bug 3 12
Taito Qix Game Freeze-Up Modification 3 12
Atari Start Bezel Change 3 12
Gremlin Sega Frogger Audio Mod 3 12
Bally Eight Ball Deluxe Bridge Rectifiers 3 12
Gottlieb Pop Bumper Scoring Switch 3 12
Gremlin Sega Digital Tech Test (Part 2) 3 12
Exidy Mousetrap New System Preview 3 12
Cinematronics Symptoms and Solutions 3 12
Midway Kick Service Notes 3 12
Midway X-Y Monitor T'shooting Guide (Part 1) 3 12
Misc Service Notes:Bill Changers-Rejectors & Coin Doors 3 12
Misc Industry Technical Schools 3 12
Taito Qix New Rom Available 4 1
Nintendo Donkey Kong Cabinet Problems 4 1
Atari Centipede Service Notes 4 1
Gottlieb Black Hole Service Notes 4 1
Williams Make Trax Increase Appeal Using Options 4 1
Nintendo Donkey Kong PCB Interchangeability 4 1
Atari Asteroids Display Problem 4 1
Gottlieb Switch Arcing Modification 4 1
Williams Hyperball New System Preview 4 1
Stern Video Powr Supply Interchangeability 4 1
Rock-Ola 473 - 474 -468-1 Credit Mod 4 1
Gremlin Sega Digital Tech Test (Part 1) 4 1
Midway Kickman Service Notes 4 1
Gottlieb Haunted House Prom ID 4 1
Williams Overvoltage Protection for Defender 4 1
Atari Centipede Erasing High Scores 4 1
Misc T'shooting with the Logic Comparator 4 1
Midway CRT Substitutions 4 1
Midway Bosconian Service Video Tape 4 1
Rowe Bill Changers Service Tips 4 1
Williams Flippers Service Tips 4 1
Atari Coin Doors Service Tips 4 1
Midway X-Y Monitor T'shooting Guide (Part 2) 4 1
Gottlieb New System 80A 4 2
Nintendo Donkey Kong Pix Flip Mod 4 2
Taito Qix Static Mod 4 2
Midway Mini Pac-Man Static Solution 4 2
Nintendo Donkey Kong On the Service Trail 4 2
Rowe Bill Changers On the Service Trail 4 2
Tommy Gate Lift Gates On the Service Trail 4 2
Stern Pop Bumpers On the Service Trail 4 2
Midway Ms Pac-Man Notes 4 2
Taito Qix PCB Lock-up Mods 4 2

<http://www.startechjournal.com>

Midway Galaga - Kickman Lock-up Mods 4 2
Midway Kick/Kickman Notes & Modifications 4 2
Exidy Mouse Trap Audio Board Modification 4 2
Bally Flash Gordon Strobe Unit Service Tip 4 2
Gottlieb Haunted House New System Preview 4 2
Misc Nickel/Dime Adjustments for Jukebox Coin Mechs 4 2
Rowe Responds to Erickson 4 2
Atari Monitor Tech Tips 4 2
Midway X-Y Monitor T'shooting Guide (Part 3) 4 2
Midway Ms Pac-Man PCB Layout - Difficulty Mod 4 2
Fluke New Tester for T'shooting Microprocessor Based Games 4 2
Misc Doing Away with That Tired Feeling 4 2
Gremlin Sega Digital Tech Test (Pat 4) 4 2
Williams Hyperball Notes 4 3
Williams PCB Interchangeability 4 3
Atari Centipede Board Revisions 4 3
Wells Gardner New Input Protection Circuit for Color X-Y Display 4 3
Stern Turtles Update Kit 4 3
Newport Joystick Replacement Solution 4 3
Misc AOE '82 Show Report 4 3
Williams Hyperball Location Notes 4 3
Williams Hyperball Handles 4 3
Rowe Response to Rowe Letter 4 3
Williams Hyperball Ball Lift Motor Kit & General panel Alignment 4 3
Misc Annual Technicians Convention 4 3
Gottlieb Transistor & Diode Substitution Guide 4 3
Midway X-Y Monitor T'shooting Tips (Continued) 4 3
Exidy Mouse trap Joystick Modification 4 3
Misc Additional Mfg Customer Service Numbers 4 3
Stern Frenzy New System Preview 4 3
Atari Centipede & Asteroids Tech Tips 4 3
Misc Interchangeability of Phono Volume Controls 4 3
Gottlieb System 80 Prom List 4 3
Taito Alpine Ski Joystick Modification 4 3
Misc Metal/Plastic Coin Acceptors Coin Door Maintenance 4 3
Misc INQuizITIVE 4 3
Gottlieb Haunted House Up Kicker Burnout Solution 4 4
Bally Rapid Fire Computer Volume Control 4 4
Exidy Mouse trap Enhancement Kit 4 4
Midway Ms Pac-Man & Galaga Wavy Video Mod 4 4
Nintendo Donkey Kong Static Problems 4 4
Gremlin Sega Zaxxon Joystick handle Precaution 4 4
Gremlin Sega Eliminator Fuse Change - X-Y Timing PCB Mod -Freeze-up Mod 4 4
Midway Color TV Monitor repair (Part 1) 4 4
Atari Dig Dug New System Preview 4 4
Atari Pat 9000 Test Station Introduction 4 4
Pace Micro Portable Soldering & Desoldering System 4 4

Taito Grand Champion Coin & Reset Mod 4 4
Midway Galaga Lock-Up Mod 4 4
Venture Line Looping Loss of Audio Solutions: Eprom Exchange 4 4
Venture Line Looping Loss of Audio Solutions: Power Supply Mod 4 4
Bright Star New Product Line 4 4
Data East Lock 'N' Chase Cassette System Notes 4 4
Misc Pinball Suggestion - Lock Gripe - Gremlin Report 4 4
Misc InQuizItive 4 4
Gottlieb Coil Chart 4 4
Gremlin Pinball Suggestion - Lock Gripe - Gremlin Report 4 4
Atari Centipede Service Tips 4 5
Gottlieb Haunted House Service Tips 4 5
Midway Pac-Man & Galaga Service Bulletins 4 5
Midway Kick-Man & Bosconian Service Bulletins 4 5
Midway Rally-X & Ms Pac-Man Service Bulletins 4 5
Midway Robby Roto & Tron Service Bulletins 4 5
Misc Service Control Panels & Video Game Adjustments 4 5
Stern Flipper Assy's Service Tips 4 5
Williams PS Connector Service Tips 4 5
Misc Stereo vs. Mono 4 5
Pace Fused Eyeletting System 4 5
Exidy Mousetrap Stand-Off Modification 4 5
Gremlin Sega Turbo Modifications 4 5
Midway Pac-Man T'shooting Steps 4 5
Gottlieb Caveman New System Preview 4 5
Williams Robotron 2084 Game Adjustments 4 5
Wells Gardner Color X-Y Display Tech Tip 4 5
Midway Color TV Monitor Repair (Part 2) 4 5
Atari Dig-Dug Static Mod 4 5
Williams Hyperball Rev 4 Program/Function Settings 4 5
Atari Dig-Dug Custom Chips 4 5
Gottlieb System 80 Solenoids 4 5
Misc InQuizitive 4 5
Rock-Ola Service Outlets for Jukeboxes 4 5
Sega optic 4 6
Midway Galaga Free Play Solution 4 6
Exidy Venture to Pepper II Conversion 4 6
Wells Gardner Color X-Y Display 4 6
Misc The Goose That Laid The Golden Egg 4 6
Midway Galaga - Tron & Lazarian Service Bulletins 4 6
Wells Gardner Vertical Deflection Circuit Revision 4 6
Platt New Product Line 4 6
Misc Electrical Effects on the Body 4 6
Bally New System Preview 4 6
Midway Tron Tilt New System Preview 4 6
Atari Dig-Dug Credit Accumulation/Temporary Fix 4 6
Pace New Catalog of Equipment 4 6

<http://www.startechjournal.com>

Midway Color TV Monitor Repair (Part 3) 4 6
Gottlieb System 80 Controlled Lamp CKT T/shooting 4 6
Misc InQuizItive 4 6
Seeburg Phonos Service Tips 4 7
Atari Tempest Service Tips 4 7
Nintendo Donkey Kong Service Tips 4 7
Exidy Victory to Victor Banana Modification Kit 4 7
Atari Dig-Dug Credit Mod 4 7
Data East Monitor Spark Gap Cleaning & Grounding Kits 4 7
Gremlin Sega G08003 Color X-Y Monitor/Voltage Analysis 4 7
Gottlieb System 80 T/shooting Game Operation & Switch Matrix 4 7
Rock-Ola Pricing Conversion 4 7
Atari Kangaroo New System Preview 4 7
Nintendo Donkey Kong/Adding a Slam Switch 4 7
Gremlin Sega Zaxxon Joystick 4 7
Wico Contact Sets 4 7
Atari Mailing List 4 7
Nintendo Donkey Kong Anti-Straw Mod - Free Games? 4 7
Taito Grand Champion Lock-Up 4 7
Taito Kram High Score ROM Revision 4 7
Taito Electric Yo Yo ROM Revision 4 7
Taito Qix & Alpine Ski Service Tips 4 7
Taito Wild Western & Kram Service Tips 4 7
Taito Electric Yo Yo Powr Supply Mod 4 7
Sega New Customer Service Numbers 4 7
Atari Color Rasterscan Monitors T'shooting Guide 4 7
Bally Midway External Video Game Monitor 4 7
Gremlin Sega Turbo Notes 4 7
A.P.E. Line of Desoldering Systems & Circuit Track Repair Kits 4 7
Misc InQuizItive 4 7
Misc Electronic Technicians Association Elects Officers 4 7
Midway Tron Notes:Upright/Cocktail PCBsk & Video Cable 4 8
Atari Dig-Dug Freeze Game Action 4 8
Midway Tron Rac Advance 4 8
Atari Power Supply Suggestion 4 8
Sega Gremlin Frogger Audio Volume Mod 4 8
Pace CIR-KIT for Repair of Tracks on PCBs 4 8
Williams Stargate & Robotron PCB Compatibility 4 8
Nintendo Flange Mount/Credit Solution 4 8
Taito T/shooting PCBs 4 8
Gottlieb System 80 General T/shooting Guide 4 8
Wells Gardner CRT Replacements 4 8
Taito Coin Door Cable Precaution /Kram Yo Yo & Space Dungeon 4 8
Misc Games in '83 4 8
Misc Jukebox Publications Reviewed 4 8
Gottlieb Caveman/Maintenance & Servicing Access to Monitor 4 8
Misc Star*Tech Journal 3rd Annual Reader Survey Result 4 8

Taito Jungle King New System Preview 4 8
Sega Gremlin ROM Line (Part 1) 4 8
Atari Dig-Dug Credit Mod/New Rev PCBs 4 8
Gottlieb Reactor: A Technical Outline 4 8
Chicago Switch New Spill resistant Switch for Games 4 8
Atari Tempest Video Art 4 8
Nintendo Donkey Kong Jr/Adding a Slam Switch 4 8
Stern Reset Modification for Super Cobra Type Logic Boards 4 8
Gottlieb Haunted House Lower Level Up-Kicker Final Solution 4 8
Misc InQuizItive 4 8
Misc AMOA 1982 Exposition 4 8
K-Tron Coin Currency Counter and Weighing Scale 4 8
Bally Midway Tron Service Bulletin 4 9
Bally Midway Solar Fox Service Bulletin 4 9
Bally Midway Blue Print 4 9
Pace Power Desoldering System 4 9
Atari Tempest Monitor Jitters 4 9
Misc Game Security 4 9
K-Tron Scale & Tron Handles 4 9
Midway Zaxxon Joystick Hum Bar & Ms Pac-Man 4 9
Midway Satans Hollow Power Supply Jumper 4 9
Bally Midway Toll Free Service Numbers 4 9
Atari Technical Tips for Dig-Dug & Centipede 4 9
Misc ROM/PROM Test Rig for Signature Analysis 4 9
Misc In Other Words 4 9
Bally Midway Video T'shooting Guide 4 9
Randustrial Overnight Floor Resurfacer 4 9
Jensen Tool Catalog 4 9
Misc ETA Wage Survey 4 9
Misc Choosing Location Speaker Systems 4 9
Nintendo Donkey Kong Junior New System Preview 4 9
Misc InQuizItive 4 9
Misc Pacific Amusement Operators Show 4 9
Sega Gremlin ROM Line (Part 2) 4 9
Wells Gardner T'shooting Color X-Y Monitor Power Supply 4 9
Taito Memory Failure T'shooting Procedure 4 9
Gottlieb T'shooting Displays 4 9
Misc AMOA Expo 4 10
Misc Identifying IC Socket Problems 4 10
Electrohome T'shooting The GO7 HVL Circuit 4 10
Sega Gremlin ROM Line (Part 3) 4 10
Misc Whac-A-Mole Ticket Motor Drive 4 10
Rowe BC-35 Bill Changer On the Service Trail 4 10
Williams Games on the Service Trail 4 10
Midway Tron Limited Buy-In Feature 4 10
Atari Power-On Reset & Watchdog Circuits 4 10
Gottlieb Q*Bert New System Preview 4 10

Taito Grand Champion Steering Wheel Mod 4 10
Misc In Other Words Electronic Components 4 10
Misc Tax Tips for Coin-Op Operators - Depreciating Equip 4 10
Misc InQuizItive 4 10
Misc Murphy's Law #410 4 10
Taito Jungle King to Jungle Hunt Conversion Kit 4 10
Misc More AMOA '82 Show Reviews 4 11
Williams Electronics Pinball Maintenance 4 11
Misc Pacific Amusement Operators Show Filming 4 11
Pace Portable Gold Plating system for PCB Repair 4 11
Sega Electronic ROM Line (Part 4) 4 11
Misc AMOA'82 Operator's Viewpoint 4 11
Misc Eeproms 4 11
Nintendo Donkey Kong Button Quick Fix 4 11
Misc Murphy's Law #411 4 11
Misc CMOS Construction & Handling 4 11
Namco Shoot Away Maintenance 4 11
Misc Fanky Malloon Balloon Machine operation 4 11
Atari Dig-Dug ROM Update - Joystick Mod - Reset Mod 4 11
Atari Centipede Trackball Mods - Battlezone Handles 4 11
Williams Joust New System Preview 4 11
Sega Electronics Systems and Solutions: Turbo Video Display 4 11
Sega Electronics Systems and Solutions: Monaco GP 1 Coin/1 Play Mod 4 11
Sega Electronics Systems and Solutions: Space Fury Moving Lines 4 11
Misc Summary of Major Op-Amp Circuits (Part 1) 4 11
Bally Midway Service Bulletin: Super Pac-Man & Anti Stringing Circuit 4 11
Bally Midway Service Bulletin: Super Pac-Man Rack Advance Test 4 11
Bally Midway Service Bulletin: Burger Time Lock-Up Mod 4 11
Bally Midway Additional Static Protection Kit 4 11
Misc AMOA Expo '82 Revisited 4 11
Misc Video Game Controls 4 11
Centuri Swimmer Switch Settings 4 11
Misc S.O.S. Micro's Spirit of 76 4 11
Misc InQuizItive 4 11
Atari Tempest Display Problems/Solutions & Monitor Adjustments 4 12
Bally Midway Super Pac-Man Difficulty Settings 4 12
Bally Midway Super Pac-Man Service Bulletin 4 12
Bally Midway Coin Option Switch Settings 4 12
Bally Midway Burger Time Service Bulletin 4 12
Bally Midway Super Pac-Man Fuse Change & Power Supply Assignment 4 12
Bally Midway Super Pac-Man Volume Control Location 4 12
Randustrial Maintenance Catalog Brief 4 12
Misc Summary of Major Op-Amp Circuits (Part 2) 4 12
Berg-Torseth Membrane Keyboard Panel 4 12
Sega ROM Line (Part 5) 4 12
Rock-Ola Dim Fluorescent Displays 476 to 484 4 12
Sega Turbo Interface PCB/Display Solutions 4 12

National Lock National Lock-Out! K-Tron Scale Saves Time 4 12
Williams Joust ROM Revision 4 12
Atari Complies to FCC Regulations 4 12
Sega Super Zaxxon Kit 4 12
Stern Lost Tomb Kit 4 12
Atari Pole Position New System Preview 4 12
Misc CMOS Operating Requirements 4 12
Namco Sweet-Licks Mallets 4 12
Vending Int'l Cotton Candy Machine 4 12
Misc Superball Modification 4 12
Taito Jungle Hunt T'shooting Chart for Sounds 4 12
Misc AMOA '82 Sets Record Attendance 4 12
Atari Pole Position Modifications & Manual Changes 4 12
Misc Pacific Amusement Operators Show: New Date/New Location 4 12
Taito Wild Western ROM Revision 4 12
Nintendo Model #730 Coin Selector Modification 4 12
Misc Pinball Playfield Parts 4 12
Sega Laser Disc Video Game Concept 4 12
Misc Murphy's Law #412 4 12
Misc InQuizItive 4 12
K-Tron National Lock-Out! K-Tron Scale Saves Time 4 12
Atari Pole Position Notes 5 1
Atari Dig-Dug Difficulty Adjustment 5 1
Atari Black Widow/Gravitar Update 5 1
Atari Centipede Intermittent Trackball Solution Revised 5 1
Atari Fire Button and Coin Switch Mod 5 1
Atari Picture Flip Mod 5 1
Atari Pole Position High Score Retention Mod 5 1
Atari Gas Pedal Maintenance 5 1
Atari Steering Wheel Lock-up 5 1
Atari Intermittent Gear Shift 5 1
Atari Double Vision 5 1
Atari Coin Door Part Numbers 5 1
Bally Midway Pac-Man Plus Precaution 5 1
Bally Midway Picture Tube Interchangeability 5 1
Bally Feature Lamp Power Supply Mod 5 1
Data East Cassette System Power Supply Mod 5 1
Gottlieb Q*Bert Technical Notes 5 1
Gottlieb MA4000 Filter Board 5 1
Gottlieb Q*Bert GG-III System 5 1
Rowe Service Tips 5 1
Seeburg Service Tips 5 1
Sega Tac-Scan conversion Kit 5 1
Sega Frogger Intermittent Sound 5 1
Sega Electronics' ROM Line (Part 6) 5 1
Taito Front-Line Ribbon Cables 5 1
Taito Wild Western Option Switch Settings 5 1

<http://www.startechjournal.com>

Wells Gardner Adjustments for Color X-Y Monitor 5 1
Misc The Operator's Business Status 5 1
Bugtrap Signature Analyzer 5 1
Misc ROM/PROM Test Cable Assy 5 1
Misc Summary of Major OP-Amp Circuits (Part 3) 5 1
Coinco Coin Return Level Mod 5 1
Misc Digital Logic Intro 5 1
Misc 555 Timer Circuits 5 1
Kasco Driver II 5 1
Misc Ticket Dispenser Feedback 5 1
Misc An R&D Tax Credit For Your Electronic Coin-Op Business 5 1
Atari New System Preview Xevious 5 1
Atari New System Preview Xevious 5 1
Atari Pole Position Gas Pedal Modification 5 2
Atari Customer/Field Service 5 2
Atari Millipede and Tempest Option Setting Recommendation 5 2
Atari Pole Position Pulley Cable 5 2
Bally Midway Baby Pac-Man Vidiot PCB Adjustments 5 2
Bally Midway Baby Pac-Man Schematic Type 5 2
Bally Midway Baby Pac-Man Flipper E.O.S. Wiring 5 2
Bally Midway Centaur & Speak Easy Solenoid Expander PCBs 5 2
Data East Bump N Jump Option Switch Settings 5 2
Gottlieb Q*Bert Symptoms/Possible Causes 5 2
Gottlieb 8088 Microprocessor Notes 5 2
Nintendo Donkey Kong Jr. Speed Up/Down Kits 5 2
Sega Electronics' ROM Line (Part 7) 5 2
Stern Lost Tomb Service Notes 5 2
Taito FMPOO1 Switching Regulator 5 2
Wico New Contact Points 5 2
Misc Mfgs Phone Numbers for Canada and Other Countries 5 2
Misc Logic Board Lock-Ups 5 2
Misc Logic Truth Tables 5 2
Misc Scoutball Troubleshooting Tips 5 2
Nintendo New System Preview Popeye 5 2
Atari Pole Position Gas Pedal Modification 5 2
Bally Midway Thumper Bumper Locking Ring 5 3
Bally Midway Wire Cheating Kits 5 3
Bally Feature Lamp Burnout Cure 5 3
Namco Hotball Hockey 5 3
Sega Turbo PROM Identification Chart 5 3
Sega Electronics' ROM Line (Part 8) 5 3
Misc AOE '83 Highlights 5 3
Misc AOE '83 in Review 5 3
Misc AOE Expo '83/Non-Videos 5 3
Misc AOE Asides 5 3
National Lock Reports on Lockout Problem 5 3
Misc Logic Gates 5 3

Misc Logic Math 5 3
Misc Divide-by-N Counters 5 3
Misc Pulse Generator 5 3
Namco Hotball Hockey 5 3
Destron Bio-Rhythm and Astrograph Modifications 5 3
Misc Tech Shop Profile Eastern Distributing Co 5 3
Sega New System Preview Star Trek 5 3
Atari Tempest Color X-Y Monitor 5 4
Atari Dig-Dug Display Distortion 5 4
Bally Midway Super Pac-Man Drop Off 5 4
Bally Midway Pac-Man Plus 5 4
Bally Midway Super Pac-Man Enhancement Chip 5 4
Bally Midway Monitor Connector Precaution 5 4
Bally Midway Grand Slam Fly-Away Target Adjustment 5 4
Bally Midway Journey Cassette Notes 5 4
Bally Midway Journey Intermittent Shut-Off of Tape Cassette 5 4
Data East Analyzing Cassette System 5 4
Gino Rondina Scoutball Tips for Light or Sound Failure 5 4
Sega Electronics' ROM Line (Part 9) 5 4
Sega G-80 Power Supply Ground Mod 5 4
Sega Zaxxon Upright/Table Joystick Mod 5 4
Sega Color X-Y Monitor Zener Replacement 5 4
Williams Drop Target Jumper Wire Fix 5 4
Williams Black Knight Flipper Coil Replacement 5 4
Misc AOE '83: Largest Yet 5 4
Misc Introduction to the 68000 5 4
Misc PAO Show 5 4
Misc R-S Latch Operation 5 4
Misc Keyboard Programmable Divide-by-N Counter 5 4
Misc Scoutball Tips for Light or Sound Failure 5 4
Misc Sole Proprietorship Life Insurance 5 4
Misc Tech Shop Profile United Distributing Inc 5 4
Cinematronics New System Preview Cosmic Chasm 5 4
Atari Pole Position Front Glass Panel 5 5
Atari Dig-Dug and Xevious Contact Points 5 5
Atari Quantum Monitor Mod 5 5
Bally Midway Mappy Difficulty Level Setting 5 5
Bally Midway Wacko 5 5
Bally Midway Kozmik Kroozs Journey etc 5 5
Bally Midway Power Schematic Manual Errors 5 5
Bally Midway Super Pac-Man/Mappy Similar Electronics Circuits 5 5
Bally Midway Baby Pac-Man Switched Illumination Mod 5 5
Cinematronics Cosmic Chasm Changes: Monitor: Jitter 5 5
Cinematronics Cosmic Chasm Changes: Monitor: Stray Lines 5 5
Cinematronics Cosmic Chasm Changes: Monitor: Power Problem 5 5
Cinematronics Cosmic Chasm Changes: Monitor: Cooling 5 5
Cinematronics Cosmic Chasm Changes: Monitor: Erratic Trackball 5 5

Cinematronics Cosmic Chasm Changes: Monitor: Game Lock-Up 5 5
Cinematronics Cosmic Chasm Changes: Monitor: Power-Up Credits 5 5
Cinematronics Cosmic Chasm Changes: Monitor: Muffled Audio 5 5
Data East Analyzing Cassette System (Part 2) 5 5
Meltec Meltec Boom Balls Trouble Areas 5 5
Sega Sit Down Star Trek Start Button 5 5
Sega Electronics' Turbo Troubleshooting (Part 1) 5 5
Sega Electronics' ROM Line (Part 10) 5 5
Wells Gardner Color X-Y High Voltage Supply 5 5
Williams Gorgar Solenoid Problem 5 5
Misc Build Your Own Logic Probe 5 5
Misc The Importance of Good Cash Management 5 5
Misc Power Supply Primer 5 5
Misc JK Divide-By-Counters 5 5
Skeeball Audio Tickets 5 5
Misc Cotton Candy Vendor Retrofit Kit/New EPROM 5 5
Misc CDC Micron Timer 5 5
Misc Industry Technical Schools 5 5
Misc Tech Shop Profile Pioneer Sales & Service 5 5
Universal New System Preview Mr. Do! 5 5
Atari Dangerous Display Harness 5 6
Atari Using the Z80 Interface 5 6
Atari Food Fight Joystick Calibration/Selecting Options 5 6
Atari Star Wars Hardware 5 6
Atari Pole Position Heat Cure 5 6
Bally Midway 125VA Power Supply Blow Fuses Cure 5 6
Bally Midway Baby Pac-Man Memory Combinations 5 6
Bally Midway Ms Pac-Man RFI Modification 5 6
Gino Rondina Hydraulic Toys 5 6
Gottlieb Power Distribution for the GG-III Video System 5 6
Sega Star Trek Kit 5 6
Sega Star Trek/The Kit 5 6
Sega Sega Electronics' Turbo Troubleshooting (Part 2) 5 6
Taito Rectifier Heat Sinks 5 6
Williams New Plastic Cabinets 5 6
Misc Varistor Protection 5 6
Misc Using Ohm's Law 5 6
Misc How to Troubleshoot DC Power Supplies 5 6
Misc Superball Ticket Motor Drive Mod 5 6
Misc Ball Release Kit 5 6
Misc Ball Stop Guard 5 6
Ikemoto Frog Hunter Ticket Dispenser Kit 5 6
Kurz-Kasch Protection Mod for TF650 5 6
Misc How to Use Low-Cost Photo Equipment to Fight Crime 5 6
Misc Tech Shop Profile Sandler Vending Co 5 6
Atari New System Preview Star Wars 5 6
Atari New System Preview Star Wars 5 6

Atari Food Fight Location Adjustments 5 7
Atari Star Wars Controls 5 7
Atari Monitor Hi-Voltage Board 5 7
Atari Troubleshooting the Amplifone Color X-Y Display 5 7
Atari Crystal Castles Checksums 5 7
Atari Star Wars Color X-Y Monitor Modifications 5 7
Atari Amplifone Color X-Y Monitor Voltage Regulator Circuit 5 7
Atari Tempest Wells Gardner X-Y Monitor IPC Board Mod 5 7
Bally Midway Baby Pac-Man Power-Up Problem 5 7
Bally Midway Mr & Mrs Pac-Man Top Saucer Problem 5 7
Bally Midway Pins 555 Lamp Burnout 5 7
Bally Midway Baby Pac-Man Feature Lamp Burnout 5 7
Gottlieb Q*Bert/Foreground 5 7
Gottlieb Q*Bert/Background 5 7
Nintendo Monitor Vertical Rollover 5 7
Sega Star Trek Kit Installation 5 7
Sega Universal Sound Board 5 7
Williams New Flipper Assembly 5 7
Misc AMOA Exposition 1983 5 7
Misc Series and Parallel Resistance/Capacitance Circuits 5 7
Misc Non-Video Game Troubleshooting (Part 2) 5 7
Misc Solid State Sound Replaces Tape Players in Kiddie Rides 5 7
Misc 10 Ways to Ruin Your Business 5 7
Misc Arcade Debit System 5 7
Misc Tech Shop Profile Bally Southwest 5 7
Cinematronics New System Preview Dragon's Lair 5 7
Atari Star Wars Unreliable Power-Up 5 8
Bally Midway Discs of Tron 125VA Power Chassis Mod 5 8
Bally Midway Professor Pac-Man Video Distortion 5 8
Cinematronics Dragon's Lair Intermittent Vertical Roll 5 8
Gino Rondina Rally Video Car Review 5 8
Gottlieb Mylstar Sound/Speech Piggyback Board Replacement 5 8
Nintendo Control Panels 5 8
Sega Star Trek G-80 Power Pins 5 8
Sega Burnt Power Supply Connector Mod 5 8
Sega Frogger 5 8
Sega Electrohome Color X-Y Monitor Deflection Amp Mod 5 8
Sega G-80 Power Supply Connector Mod 5 8
Sega Pengo EPROM Lock-Up 5 8
Stern Frenzy Power-Up Credits 5 8
Misc Mfgs Need Help 5 8
Misc Pre-AMOA Industry Outlook 5 8
Misc Managerial Strategies 5 8
Misc Base-Car Communications 5 8
New-Tone Quartz Crystal Application Guide 5 8
Misc Laserdisc Technology Brief 5 8
Misc 555 Timer Update 5 8

Misc Motors Clutches & Brakes for Kiddie Rides & Arcade Pieces 5 8
Misc Manufacts: Understanding Speech Synthesizers 5 8
Misc S*TJ 4th Annual Reader Survey Results 1983 5 8
Misc Tech Shop Profile World-Wide Distributing 5 8
Cinematronics New System Preview Dragon's Lair (Cont.) 5 8
Atari New System Preview Crystal Castles 5 8
Atari New System Preview Crystal Castles 5 8
Atari Pole Position II 5 9
Atari Star Wars Control Calibration 5 9
Atari Star Wars Freeze Mode Warning 5 9
Atari Star Wars PCB Component Changes 5 9
Atari Star Wars AMD RAMS 5 9
Atari Star Wars Game Options 5 9
Bally Midway Discs of Tron Wiring Error 5 9
Gino Rondina Rally Video Car Circuit Operation (Part 1) 5 9
Rowe OBA 1/5 Bill Acceptor 5 9
Sega Champion Baseball Theory of Operation 5 9
Williams Joust Pinball Problems and Percentaging 5 9
Misc 7-Segment Displays 5 9
Misc VideoDisc Maintenance 5 9
Misc A Glossary of Microprocessor Terms 5 9
Misc Reading Effectively 5 9
Pioneer PR-7820 Notes:Dragon's Lair Options/Modes 5 9
Pioneer PR-7820 Warranty Procedure 5 9
Misc Disc Mounting 5 9
Misc Disc Cleaning 5 9
Misc Tech Shop Profile Brady Distributing Co 5 9
Centuri New System Preview GyruSS 5 9
Centuri New System Preview GyruSS 5 9
Atari Star Wars Notes 5 10
Atari Star Wars Amplifone X-Y Monitor 5 10
Bally Midway Discs of Tron Upright/Environmental Differences 5 10
Bally Midway Discs of Tron/Granny and the Gators 5 10
Bally Midway Diode Change 5 10
Bally Midway Pinball Test Fixture Updates 5 10
Bally Midway Astron Belt Self Test 5 10
Bally Midway Astron Belt Back Door Key 5 10
Bally Midway Astron Belt Demodulator Board- Dip Stick Switch 1 5 10
Bally Midway Astron Belt Demodulator Board (Connectors & Adjustments) 5 10
Bally Midway Astron Belt Basic Game Troubleshooting 5 10
Bally Midway Astron Belt Laserdisc Player 5 10
Bally Midway Astron Belt VideoDisc Precautions 5 10
Bally Midway Astron Belt Laserdisc Storage 5 10
Bally Midway Astron Belt False Error Message 5 10
Bally Midway Cheap-Squeak Sound Module Self Test/Theory of Operation 5 10
Bally Midway Electrohome & Wells Gardner Monitors (Part 1) 5 10
Bally Midway Ms Pac-Man Speed-Up Mod 5 10

Centuri Gyruus Shorted Power Supply Problem 5 10
Cinematronics Dragon's Lair Intermittent Joystick 5 10
Cinematronics Dragon's Lair to TV Hook-Up 5 10
Gino Rondina Rally Video Car Circuit Operation (Part 2) 5 10
Wells Gardner X-Y Monitor/Final Solution 5 10
Misc AMOA '83 Highlights 5 10
Misc Videodisc: Description/Format 5 10
Misc Tech Shop Profile Royal Distributing Corp 5 10
Bally Midway New System Preview Discs of Tron 5 10
Bally Midway New System Preview Discs of Tron 5 10
Atari Food Fight Joystick Update 5 11
Bally Midway Astron Belt Laserdisc Players 5 11
Bally Midway Astron Belt Part Numbers 5 11
Bally Midway Electrohome & Wells Gardner Monitors(Part 2) 5 11
Centuri Track & Field Switch Mod 5 11
Cinematronics Dragon's Lair Control Panel Ground Loop 5 11
Cinematronics Dragon's Lair Audio Hum 5 11
Gino Rondina Rally Video Car Circuit Operation (Part 3) 5 11
Gottlieb Mylstar M.A.C.H. 3 Game Adjustments/Options 5 11
Sega Star Trek Cockpit Control Panel Assembly 5 11
Williams Sinistar Bug 5 11
Misc AMOA '83 Review 5 11
Misc AMOA Expo '83 Non-Videos in Review 5 11
Misc CMOS Info 5 11
Misc Troubleshooting Non-Videos (Part 4) 5 11
Misc Watch Out for the Co-Insurance Clause! 5 11
Misc Cash or Accrual Basis Accounting 5 11
Pioneer Latest VideoDisc Player/LDV1000 5 11
Ardac Note Acceptors: Resistor Change 5 11
Ardac Note Acceptors: New Alignment Card 5 11
Misc Hoppers: Crimping Problem 5 11
Misc Hoppers: Coin Jam Improvement 5 11
Misc Troubleshooting Tip: Intermittent Vends 5 11
Misc Tech Shop Profile World Wide Distributors 5 11
Mylstar New System Preview M.A.C.H. 3 5 11
Atari Pole Position Harness Breakage 5 12
Atari Fuse Holder Burnout 5 12
Atari Star Wars Main PCB 5 12
Atari Vector-Generator PCB 5 12
Atari Color X-Y Monitor 5 12
Atari Pole Position II Enhancement Kit 5 12
Atari Star Wars Handle Assembly Working Loose 5 12
Atari Star Wars Coin Door-Free Credits 5 12
Atari Star Wars Adding a Monitor Fan 5 12
Bally Midway Galaga Program Problem 5 12
Bally Midway NFL Football Credit and Self Test Switch 5 12
Bally Midway Break-in Period and Disc Cleaning 5 12

Bally Midway RCA VideoDisc Player Shut Down Procedure 5 12
Bally Midway Dip Switches 5 12
Bally Midway RCA Disc Player Operation 5 12
Bally Midway RCA Disc Player-Shipping Tabs 5 12
Bally Midway RCA VideoDisc Skipping 5 12
Bally Midway Electrohome & Wells Gardner Monitors 5 12
Bally Midway Spy Hunter Power Chassis Modification 5 12
Bally Midway Upright and Sit Down Logic Board Interchangeability 5 12
Bally Midway Upright and Sit Down in Attract Mode Option 5 12
Bally Midway Astron Belt VideoDisc Player Cover 5 12
Cinematronics Dragon's Lair Disc Player Compatibility 5 12
Gino Rondina Rally Video Car Circuit Operation (Part 4) 5 12
Gottlieb Mylstar M.A.C.H. 3 Troubleshooting 5 12
Gottlieb Mylstar M.A.C.H. 3 Interpreting Location Figures 5 12
Gottlieb Mylstar M.A.C.H. 3 Easy-Play Program Change 5 12
Williams Intermittent Reset 5 12
Williams Servicing Flipper Mechanisms 5 12
Williams New Flipper Assembly Introduced 5 12
Williams Firepower and Big Strike General Illumination Circuit 5 12
Pioneer LD-V1000 Specs 5 12
Misc IAAPA Convention Review 5 12
Misc Electronic Test Procedures/Diodes 5 12
Misc Tech Shop Profile Bally Midwest 5 12
Universal New System Preview Universal's Mr. Do!'s Castle 5 12
Atari RED BARON 6 1
Atari POLE POSITION 11 6 1
Bally Midway Electrohome & Wells Gardner Monitors (Part 4) 6 1
Bally Midway NFL FOOTBALL Program Update Kit 6 1
Bally Midway SPY HUNTER Potentiometer Calibration 6 1
Bally Midway NFL FOOTBALL Vertical Roll with Slave Monitor 6 1
Bally Midway JR. PAC-MAN Mod for Universal Tester 6 1
Bally Midway JR. PAC-MAN Logic Boards Not Interchangeable 6 1
Bally Midway JR. PAC-MAN Field Kit: Coin Counter 6 1
Bally Midway SPY HUNTER (S/D and U/P) Accelerator/Steering Pots 6 1
Bally Midway NFL FOOTBALL And TAPPER Possible PWR Short 6 1
Bally Midway MS. PAC-MAN: Filter PCB Caution 6 1
Bally Midway MS. PAC-MAN: Power Supply Burnt Pins Mod 6 1
Centuri/Konami TRACK & FIELD 6 1
Cinematronics PR7820 Exchange Program 6 1
Electrohome and Wico Form Marketing/Distribution Partnership 6 1
Mylstar/Gottlieb Pop Bumper Burn-Out Cure 6 1
Sega G-80 Card Cage System Games Custom Chips and Program Series 6 1
News Bits First Digital TV Sets Shown In Europe 6 1
News Bits Hook a Videodisc to Your Apple 6 1
News Bits Sharpest Tube in Town 6 1
News Bits Flicker-Free 3-D Movies with New Stereo System 6 1
News Bits Color Oscilloscope uses Liquid-Crystal Shutter 6 1

Miscellaneous Z-80 Micro Outline 6 1
Miscellaneous RCA SJT400 Random Access Videodisc Player 6 1
Miscellaneous Control Panels 6 1
Miscellaneous Testing Semiconductors 6 1
Atari QUANTUM Schematic Corrections 6 2
Atari STAR WARS Notes 6 2
Atari STAR WARS Display Problems 6 2
Atari CLOAK AND DAGGER Troubleshooting Procedure 6 2
Atari CRYSTAL CASTLES ROM Update 6 2
Atari Cat Box Checksums 6 2
Bally Midway BURGER TIME Credit Mod 6 2
Bally Midway JR. PAC-MAN (Field Kit) 6 2
Bally Midway SPY HUNTER (S/D and U/R) Calibration Mod 6 2
Bally Midway JR. PAC-MAN (Games & Kits) +5vdc Reg. Schematic Error 6 2
Cinematronics DRAGON'S LAIR Laserdisc Repair Problems 6 2
Electrohome GO7-CBO DC Voltage Measurements 6 2
Mylstar/Gottlieb M.A.C.H. 111 Troubleshooting (cont) 6 2
Mylstar/Gottlieb Pop Bumper Board Symptom/Solution 6 2
Stern Intermittent Operation 6 2
Williams GORGAR Solenoid Problem 6 2
News Bits Arcade-Style Games Board 6 2
News Bits Laservision Goes Solid State 6 2
Miscellaneous Atari Remembers Its Own 6 2
Miscellaneous Cutting Excess Overhead Costs 6 2
Miscellaneous Laserdisc Repair Part 1 Short of Actual Repair 6 2
Miscellaneous ASI '84 6 2
Miscellaneous Kits-Make Your Game Look New 6 2
Atari FOOD FIGHT Joystick Calibration 6 3
Atari STAR WARS Troubleshooting Guide Notes 6 3
Atari FIREFOX Amplifone Raster Modification 6 3
Atari TEMPEST Display 6 3
Bally Midway Flipper Assembly Revisions 6 3
Bally Midway 555 Lamp Burnout Circuit Mod 6 3
Bally Midway SPY HUNTER Cheap Squeak Deluxe Module PAL Substitution 6 3
Bally Midway SPY HUNTER TAPPER AND ROOT BEER Fuse Change 6 3
Bally Midway ASTRON BELT to GALAXY RANGER Conversion Kit 6 3
Cinematronics Laserdisc Repair Part 2 Theory and Safety 6 3
Cinematronics SPACE AGE 6 3
Mylstar/Gottlieb T'Shooting Tips for M.A.C.H. 111 6 3
Nintendo DONKEY KONG Radar Scope Scrambled Screen 6 3
Nintendo MARIO BROS. COIN/CREDIT PROBLEMS 6 3
Nintendo RADAR SCOPE Frozen Picture 6 3
Nintendo RADAR SCOPE Speed-Up Kit 6 3
News Bits High-Power Switch 6 3
News Bits New Look for TV 6 3
News Bits Semiconductor and Gas Lasers 6 3
News Bits RCA Corp Phases Out Videodisc Player 6 3

<http://www.startechjournal.com>

Miscellaneous Pioneer's LD-V4000 Industrial Laserdisc Player 6 3
Miscellaneous The Game That Has Never Worked Properly 6 3
Miscellaneous AOE Review 6 3
Miscellaneous Conversion Kits 6 3
Miscellaneous RF Modulator Circuit for use with Radio Shack UM1285-8 6 3
Miscellaneous Atari & Activision to Broadcast Software 6 3
Miscellaneous Mylstar Announces Three Day Seminar 6 3
Miscellaneous Nintendo Introduces Their Service Package 6 3
Atari FIREFOX Main & Graphic PCB Signals 6 4
Atari Narrowing Down Game Problems 6 4
Atari STAR WARS X-Y Display Modification 6 4
Bally Midway TEN PIN DELUXE Shuffle Alley Playfield Cleaner 6 4
Bally Midway TEN PIN DELUXE Shuffle Alley ROM Self Test 6 4
Bally Midway SPY HUNTER Power-Up Failure 6 4
Bally Midway Pinball Flipper Assembly 6 4
Bally Midway TEN PIN DELUXE Shuffle Alley Safety Switch 6 4
Bally Midway TEN PIN DELUXE Shuffle Alley Options 6 4
Bally Midway TEN PIN DELUXE Shuffle Alley Hi-Voltage 6 4
Bally Midway TEN PIN DELUXE Shuffle Alley RAM Location 6 4
Centuri/Konami TRACK & FIELD Missing Video Cure 6 4
Nintendo New System Preview: Nintendo VS. TENNIS 6 4
Nintendo DONKEY KONG DONKEY KONG JR Slam Switch 6 4
Nintendo POPEYE MARIO BROS. Slam Switch 6 4
Nintendo RADAR SCOPE Interchange of Hybrid ICs in Pwr Sup PP7A 6 4
Nintendo DONKEY KONG Interchange of Hybrid ICs in Pwr Sup PP7A 6 4
Nintendo DONKEY KONG JR Intrchnge of Hybrid ICs in Pwr Sup PP7A 6 4
Rowe BC-35 Changer Notes 6 4
Taito FRONT LINE 6 4
Williams GORGAR Solenoid Problem Response 6 4
News Bits High Resolution Touch Screen 6 4
News Bits New Flat-Panel Display Technology Yields Color & 3-D 6 4
Miscellaneous Timing-A Must for Advertising Success 6 4
Miscellaneous Ticket Dispensers 6 4
Miscellaneous Pioneer LD-V1000 Remote 6 4
Miscellaneous Pinball Warehouse's Tech Shop 6 4
Miscellaneous Laserdisc Repair Part 3 Voiding Your Warranty 6 4
Miscellaneous Atari Lucasfilm 6 4
Atari FIREFOX Program Update 6 5
Bally Midway Monitors:Differences Parts and Picture Tube Interchange 6 5
Bally Midway SPY HUNTER TAPPER & ROOT BEER Fuse Change 6 5
Bally Midway SPY HUNTER(Upright S/N 101-635)Loss of Battery Memory 6 5
Bally Midway New System Preview SPY HUNTER 6 5
Bally Midway SPY HUNTER Steering & Gas Pedal Calibration 6 5
Bally Midway UP N DOWN Option Switch Setting Error 6 5
Bally Midway FOOTBALL RCA Videodisc Player SJT-400 Turntable Removal 6 5
Cinematronics DRAGON'S LAIR/SPACE AGE Modifying for 1 Coin/1 Credit 6 5
Data East COBRA COMMAND Conversion Kit for BEGA'S BAYTTLE Laserdisc Games 6 5

Data East BOOMER RANG'R conversion Kit Manual Correction 6 5
Mylstar/Gottlieb Coil Chart 6 5
Stern BAGMAN to SUPER BAGMAN Reset Mod 6 5
News Bits Rechargeable Button 6 5
News Bits Money Weigher 6 5
News Bits IBM Makes a Big Chip 6 5
Miscellaneous Atari Intros Advanced Game for Home Market 6 5
Miscellaneous Making Pinball Last 6 5
Miscellaneous Understanding CMOS IC Technology 6 5
Miscellaneous Laserdisc Repair Part 4 PR8210 Type Disc Players 6 5
Miscellaneous Atari's New Game Machine 6 5
Atari Switching Power Supply Precautions 6 6
Bally Midway SPY HUNTER (U/R and S/D) Schematic Error 6 6
Bally Midway BIG BAT PC Board Interchangeability 6 6
Bally Midway MR.VIKING Button Reversal 6 6
Bally Midway MR.VIKING Option Card Info 6 6
Nintendo PUNCH-OUT 11 6 6
Stern BAGMAN to SUPER BAGMAN Wavy Video Mod 6 6
News Bits EIA Sets New Standards for Silicon Digital ICs 6 6
Miscellaneous Tooting Your Own Horn 6 6
Miscellaneous Telephone Modem Attachment 6 6
Miscellaneous S*TJ 5th Annual Reader Survey 6 6
Miscellaneous Star*Bay's 10 Hottest/Blue Book Listings 6 6
Miscellaneous Putting a Value on Your Coin-Operated Games Business 6 6
Miscellaneous Video Games Can Cause Interference to Radio Com. 6 6
Atari Convertible Games 6 7
Atari STAR WARS Amplifone Monitor Flyback Test 6 7
Atari STAR WARS Shorted Output Transistors 6 7
Bally Midway WIZARD OF WOR 1 Coin/2 Plays Mod 6 7
Bally Midway TWO TIGERS Tape Player I/O Mod 6 7
Bally Midway BLACK PYRAMID Attract Mode Sound Shut-Off 6 7
Bally Midway BLACK PYRAMID Game Manual Correction 6 7
Cinematronics DRAGON'S LAIR/SPACE AGE 1 Coin/1 Play Modification Addendum 6 7
Electrohome Monitor Modification:Horizontal Sync Adj 6 7
Monroe BIRDIE KING 2 6 7
Monroe BIRDIE KING 2 Video Display Tearing 6 7
Monroe BIRDIE KING 2 Object Detection Board 6 7
Nintendo VS System Upright Monitor Interchange 6 7
Nintendo PUNCH-OUT 11 Power Supply Anti-Oscillation Mod 6 7
Rowe R-85 Jukebox Danger 6 7
Stern Cliff Hanger Power Up Problems 6 7
Stern FREE FALL Pinball Adds Players 6 7
Stern FREE FALL Pinball Goes Into Game Over Problems 6 7
Williams PENNANT FEVER CPU-Board Field Mod 6 7
Williams New Flipper Assemblies 6 7
Williams PENNANT FEVER Magnet Coil Burnout Cure 6 7
Williams PENNANT FEVER Setting the Game for Award Innings instead of Credit 6 7

Williams PENNANT FEVER Random Fitch on Two-Player Games 6 7
News Bits The Gigabit RAM 6 7
News Bits Powerful Video-Processor ICs Start to Appear 6 7
News Bits 1000 Charge Cycles in Carson-Litium Cell 6 7
Miscellaneous Get The Most Out of a Convention or Trade Show 6 7
Miscellaneous Tax Reform Act of 1984 and Depreciation 6 7
Miscellaneous Star*Bay's 10 Hottest/Blue Book Listings 6 7
Miscellaneous Tips from Pro-Circuitry 6 7
Miscellaneous Discussing Video Game Options 6 7
Miscellaneous Music Vend Distributing 6 7
Miscellaneous Locks...Beware! 6 7
Miscellaneous Electrostatic Facts & Figures 6 7
Miscellaneous Star*Tech Journal 5th Annual Reader Survey Results '84 6 7
Miscellaneous Laserdisc Repairs Part 5 Solid State Players 6 7
Miscellaneous Survival in '85 6 7
Bally Midway NFL FOOTBALL RCA Player Update Kit No. 2 6 8
Bally Midway NFL FOOTBALL DALLAS COWBOYS New Disc Kit No.3 6 8
Bally Midway NFL FOOTBALL WASHINGTON REDSKINS New Disc Kit No.3 6 8
Bally Midway SPY HUNTER Cheap Squeak Deluxe LED Test Sequence 6 8
Bally Midway 10 PIN DELUXE Shuffle Powder Wax(Shuffle Alley Way) 6 8
Bally Midway FLASH GORDON MPU Jumper Requirements 6 8
Bally Midway EIGHT BALL DELUXE MPU Jumper Requirements 6 8
Bally Midway FIREBALL 11 MPU Jumper Requirements 6 8
Bally Midway EMBRYON MPU Jumper Requirements 6 8
Bally Midway SPY HUNTER Pinball Replay Adjustment 6 8
Data East KARATE CHAMP Video Freeze-Up 6 8
Konami TIME PILOT '84 6 8
Taito Selects Wico for Nat'l Parts Distribution/Board Serv 6 8
Taito Konami Difficulty Settings 6 8
Williams A Word about Troubleshooting 6 8
Williams BLACK KNIGHT Plastic Reinforcement Plates 6 8
Williams D8363 7-Digit Master Display Board - ALIEN POKER 6 8
Williams D8363 7-Digit Master Display Board - ALGAR 6 8
Williams D8363 7-Digit Master Display Board - BLACK KNIGHT 6 8
Williams Comma Circuit Mod 6 8
Williams Flipper Game Driver Boards 6 8
Williams TRIPLE STRIKE Manual Amendment 6 8
Williams BLACK KNIGHT Playfield Mylar Protectors 6 8
Williams General Illumination Mods 6 8
Williams FIREPOWER 11 50v Flippers 6 8
Williams Driver Board Early BLACK KNIGHT & ALGAR Games 6 8
Williams Switch Matrix Circuit Modifications 6 8
Williams HYPERBALL Backbox Ground for Lamp 6 8
Zaccaria DEVIL RIDERS Options 6 8
News Bits Deep-UV Laser Writes Narrow Lines in Silicon 6 8
News Bits Color LCD Technology Advances 6 8
News Bits Large-Screen TV Has High Definition 6 8

News Bits Polymer Conductivity Boosted a Hundredfold 6 8
Miscellaneous Financial Planning 6 8
Miscellaneous Dealing with Stress and Energy Levels 6 8
Miscellaneous Videodisc Player Roundup 6 8
Miscellaneous Service and the Univid 1000 Video Game Test System 6 8
Miscellaneous Installing Your New Game Package 6 8
Miscellaneous Star*Bay's 10 Hottest/Blue Book Listings 6 8
Miscellaneous Pick Hits of the AMOA Show 6 8
Miscellaneous AMOA Expo Attractions '84 6 8
Miscellaneous Circuit for Measuring Timing Relationships Tip 6 8
Arachnid English Mark Darts Micro Chip problems 7 1
Atari Marble Madness Game Resets at Low Line Voltage 7 1
Atari Marble Madness Game Displays Software Exception 7 1
Atari Marble Madness Humming Noise from Speakers 7 1
Atari System Notes 7 1
Bally Midway Fireball Classic Continuous Extra Ball condition 7 1
Bally Midway Spy Hunter Tapper Game locked up 7 1
Bally Midway Spy Hunter Tapper Game White Screen with Random Graphics 7 1
Bally Midway Spy Hunter Tapper Game Will not Coin or Start 7 1
Bally Midway Displays 7 1
Bally Midway Spy Hunter Slight Hum Bar in Video and Distorted Audio 7 1
Bally Midway Two Tigers Slight Hum Bar in Video and Distorted Audio 7 1
Bally Midway Fireball Classic Game-Over and High-Score Feature Lights 7 1
Bally Midway Demolition Derby ROM Change 7 1
Game Plan Atilla The Hun/Agents 777 Ball Shocker Lane 7 1
Game Plan Atilla The Hun/Agents 777 Oscillator I.C. on the MPU Board 7 1
Gottlieb Mylstar All System 80 and 80A Games Bookeeping Failures 7 1
Rowe R88 & R89 Phono Throwing Records and Putting in Wrong Slot 7 1
Stern Split Second 7 1
Stern Bally Stern Displays 7 1
Williams Williams Drop Targets 7 1
Misc National Locks 7 1
Misc Board Repair: Like It or Not 7 1
Misc ASI/AOE '85 7 1
Atari Paper Boy Game Dead - Garbage on screen 7 2
Bally Midway Trivial Pursuit Program Cartridge Interchangeability 7 2
Bally Midway Galaga Logic Board Dip Switches 7 2
Bally Midway Tron Logic Lock-Up 7 2
Gottlieb Premier Eldorado Ice Fever Display Blank Out 7 2
Merit Trivia Whiz Troubleshooting Tips 7 2
Merit Installing Mini Kit in Your Pit Boss 7 2
Romstar Kickstart Game Will Not Credit 7 2
Romstar Hal-21 Additional Information: Continue-Play 7 2
Romstar L942 Additional Information 7 2
Wico Aftor Pinball Ball Bouncing Lower Bumpers 7 2
Wico Aftor Pinball Game Goes Into Self-Test by Itself 7 2
Williams Diagnostics 7 2

<http://www.startechjournal.com>

Misc Diagnosis: The First Step 7 2
Misc Conversion Tips Start-Up Power Supplies Monitor 7 2
Arachnid Dart games 7 3
Atari Paper Boy Very High Scores 7 3
Atari Paper Boy Extreme Playing Times 7 3
Atari Paper Boy Auxiliary Power Supply Schematic 7 3
Atari Missile Command Conversion 7 3
Atari Robot Wrong ROM Read-Out 7 3
Bally Midway Trivial Pursuit-How to Reset High Score (Upright & Cocktail) 7 3
Magic Samurai Game Difficulty Setting 7 3
Nintendo System Comments 7 3
Nintendo VS System Machine is Dead 7 3
Williams Pinball Problem & Tips 7 3
Misc Input Problems 7 3
Misc Power Supplies: Check for Ripple 7 3
Misc Conversion Tip: Control Panels 7 3
Arachnid English Mark Darts New Player Change Button 7 4
Data East Command Collections Down and Very Long Playing Times 7 4
Innovative Concepts KIXX Soccer Light Bulb Replacement 7 4
Nintendo VS Dualsystem VS Unisystem Gun Games 7 4
Williams Shuffle Alley Problems and Tips 7 4
Williams Space Shuttle 7 4
Misc Rastar Scan Monitor Tips 7 4
Misc Conversion Tips: Coin Doors 7 4
Misc Tools of the Trade 7 4
Bally Midway 8-Ball Champ Pinball 6803 Control Board Power-Up Test Sequence 7 5
Bally Midway The Player: Eight Ball Deluxe 7 5
Data East Commando Misses Coin Drops 7 5
Data East Cassette System: Operation and Maintenance 7 5
Magic Special Forces Conversion Kit 7 5
Namco Shoot Away Shot Sound But No Gun Flash 7 5
Nichibutsu Magmax Game Goes Into Self-Test by Itself occasionally 7 5
Nichibutsu Magmax: Free Credits When Coins are Inserted 7 5
Nintendo VS Dualsystem VS Unisystem Gun Games 7 5
Seeburg Models LS3 thru STD4 Plays Same Record Again and Again 7 5
Seeburg Models SPS 160 thru SMC2 Muffled Sound and Volume Changes 7 5
Misc Changing Components 7 5
Misc Conversion Tip: Cosmetics 7 5
Bally Midway Demolition Derby (2 & 4 Player) Optical Encoder Deluxe 7 6
Bally Midway 8 Ball Champ Game Percentage too High 7 6
Gottlieb Mars (God of War) 7 6
TNK Conversion Tips:TNK 111 & Rush n Attack Kits 7 6
Nintendo VS Dualsystem VS Unisystem Gun Games Attract Mode 7 6
Nintendo VS Dualsystem VS Unisystem Gun Games Repair/Replace 7 6
Nintendo VS Dualsystem VS Unisystem Gun Games Repair/Exchange 7 6
Nintendo Guns 7 6
Williams Comet Field Service Mods 7 6

Misc Plex Scratches 7 6
Misc Pinball Shooter Tips 7 6
Misc Microprocessors 7 6
Misc Pinball Legs 7 6
Misc Pinball Playfield 7 6
Misc Pinball Service Keys 7 6
Arachnid English Mark Darts Electrical Noise Problem 7 7
Atari Troubleshooting Pole Position PCBs 7 7
Atari Gauntlet Technical Updates 7 7
Merit Trivia Whiz Recycle of Starting Points when power Off and On 7 7
Nintendo Gun Update 7 7
Rowe Rowe BC-35 7 7
Williams Game Documentation 7 7
Williams Comet 7 7
Misc AMOA '85 7 7
Misc Conversion Tips 7 7
Misc Thermal Problems 7 7
Atari Indiana Jones Self Test 7 8
Atari Gauntlet Software Update 7 8
Memetron Mat Mania Wire Table 7 8
Williams Firepower 7 8
Williams Comet Game Adjustments 7 8
Misc Optocoupler Tester 7 8
Bally Midway Beat The Clock PCB Mod 7 9
Bally Midway The Player: Bally Midway Eight Ball Champ 7 9
Bally Midway Jumpshot Option Switches 7 9
Gottlieb Sound-Speech Board Audio Amps 7 9
Memetron Mat Mania Video Mod 7 9
Romstar L942 No Sound Check 7 9
Romstar Gunsmoke Changes/Hi Score Mod 7 9
Sega Choplifter Kit 7 9
Misc Standardization (AMOA '85 Seminar) 7 9
Misc What Is A Bus 7 9
Rowe/Ami Amplifiers Intermittant Audio 8 .3
Atari Gauntlet Program Change/IC Fix 8 1
Atari Shows Home Videos at CES 8 1
Atari Gauntlet Acrylic Shield Kit 8 1
Bally Midway Beat the Clock 8 1
Bally Midway Jump Shot Game Reset Note 8 1
Data East Ring King Operator Options 8 1
Nichibutsu Terra Cresta Dip Sw/Joystick 8 1
Nintendo Dual/Uni-System Gun Games 8 1
Misc Getting In Tune 8 1
Cinematronics World Series Joysticks 8 2
Data East Ring King 11 Distorted Audio 8 2
Menetron Mat Mania Washed-Out Video 8 2
Nichibutsu Tube Panic Joystick Mod 8 2

<http://www.startechjournal.com>

Premier/Gottlieb Bounty Hunter 8 2
Rock-Ola 490-2 Magazine/Turntable Mod 8 2
Sega Choplifter Unstable Video 8 2
Williams System 11 Features 8 2
Misc ACME '86 8 2
Misc A look at the First ACME Show 8 2
Atari Gauntlet Service Tips 8 3
Bally Sente SAC Kits 8 3
Data East Express Raider Program Update 8 3
Nintendo VS System Duel Cabinet 8 3
Romstar Gunsmoke Joystick Mod 8 3
Romstar Battle Lane Video Mod 8 3
Williams Seminars Take Ohio by Storm 8 3
Williams High Speed 8 3
Williams Shuffle Alleys & Pins 8 3
Misc About Pinball Boards 8 3
Misc Power Supply Conversions 8 3
Atari Star Wars Monitor Problems 8 4
Data East Ring King and Speed Buggy Mods 8 4
Merit Phraze Craze Program Update 8 4
Romstar Plug-In Kits 8 4
Sega Space Warriar Video Lock-Up Mod 8 4
Cranes/Merchandisers Cranes and Rotary Merchandisers 8 4
Misc Negative Voltages from Positive Supplies 8 4
Atari Pole Position Gauntlet & Super Sprint Mods 8 5
Bally Sente Main Frame Cable Mod 8 5
Bally Sente Name That Tune Test 8 5
Merit Phraze Craze Sex Program 8 5
Monitor Horizontal Tear 8 5
Premier/Gottlieb Raven 8 5
Sega Space Warriar Motor Burn-Out 8 5
Tradewest Ikari Warriors Video 8 5
Williams Game Recommendations 8 5
Cranes/Merchandisers Skil-O-Bingo 8 5
Cranes/Merchandisers Adjust Your Crane 8 5
Misc Need for a Professional Presentation 8 5
Misc Dull Bit Problem 8 5
Misc Something Different 8 5
Bally Midway Motordome Lamp Assy 8 6
Monitor Wells Gardner 19K4901 Flyback xformer 8 6
Monitor Horizontal Tearing Mod 11 8 6
Nintendo Guns Revisited 8 6
Premier/Gottlieb Hollywood Heat 8 6
Romstar Trojan New Eprom 8 6
Romstar Tokio Coin Switch Jumper 8 6
Cranes/Merchandisers Showcase Inc Response 8 6
Cranes/Merchandisers Replacement Motors 8 6

Vending DBAs 8 6
Misc Getting Negative Voltages from Switching Regs 8 6
Atari Roadrunner Color Ram Failure 8 7
Atari Paper Boy Display Failures 8 7
Atari Pole Position Resistor Burn 8 7
Data East Speed Buggy Steering Control 8 7
Merit Trivia/Phrase Eprom Labels 8 7
Monitor Wells Gardner Sync Board Modification 8 7
Monitor Older Monitor Alert 8 7
Premier/Gottlieb Rock 8 7
Cranes/Merchandisers Showcase Has No Case 8 7
Vending Multiple Bill Acceptors 8 7
Misc Beefing-Up Older Power Supplies 8 7
Bally Midway Motordome Cheap Squeak 8 8
Bally Midway Black Pyramid 8 8
Bally Midway Black Belt Manual Error 8 8
Merit Bull Buster Panel Overlay 8 8
Merit Bull Buster Test Precaution 8 8
Merit-Nomac Pub Time Darts 8 8
Nintendo Power Supply Alert 8 8
Nintendo Capacitor Replacement 8 8
Sega Enduro Racer Handle Assy 8 8
Sega Shooting Master Credit Mod 8 8
Tehkan Pinball Action Intermittent Sound 8 8
Tradewest Ikari Warriors Edge Connectors 8 8
Cranes/Merchandisers Crompton's Silver Ski Hopper Mod 8 8
Vending Automatic Products 4000 Series Snackshops 8 8
Atari Championship Sprint Scrambled Video 8 9
Atari Cat Box: New Interface Available 8 9
Bally Midway Galaga GG-4 Prom 8 9
Memetron Mania Challenge Coin Input Circuit 8 9
Merit-Nomac Pub Time Darts Warranty 8 9
Nintendo Playchoice-10 Program Revision 8 9
Nintendo VS System RP2AO4 Chip 8 9
Williams EOS Switch & Flasher Circuits 8 9
Williams CPU Reset & Pin Relays 8 9
Cranes/Merchandisers Another Response from Showcase Inc 8 9
Cranes/Merchandisers Silver Ski Hopper Mod 8 9
Vending Automatic Products RMI & Dixie-Narco 8 9
Misc Video Probe 8 9
Misc Conversion Hints 8 9
Misc Pin Skills 8 9
Misc ESD Pool Table Coin Slides 8 9
Atari Super Sprint Free Play Problem 8 10
Data East Breakthru Con Problem 8 10
Nintendo VS Super Mario Bros Bug 8 10
Cranes/Merchandiser Big Choice California Version Mod 8 10

<http://www.startechjournal.com>

Misc 1986 AMOA Expo 8 10
Misc AMOA '86 Comments and Opinions 8 10
Misc Various Problems Concerning Electronics 8 10
Misc Power Supplies Theory of Operations 8 10
Atari 720: Squares in Video Symptom 8 11
Atari Championship Sprint Bad Video 8 11
Data East Last Mission No Vertical Deflection 8 11
Monitor Electrohome Horizontal Wave 8 11
Nintendo Playchoice 10 Front Screen 8 11
Sega Enduro Racer Steering Modification 8 11
Cranes/Merchandiser Maintaining and Fine-Tuning Your Cranes 8 11
Misc Power Supplies Theory of Operation Part 11 8 11
Misc Various Problems concerning Electronics Part 2 8 11
Arachnid English Mark Darts Credit Mod 8 12
Arachnid English Mark Darts Service Tip 8 12
Atari 720 Handgrip Package 8 12
Atari Road Runner Ticket Dispenser Installation 8 12
Atari Gauntlet Color Ram Troubleshooting Tip 8 12
Atari Super Sprint Steering Shafts 8 12
Bally Midway Switching Power Supply Mod 8 12
Bally Midway Rampage Power Supplies 8 12
Memetron Mania Challenge Credit Mod 8 12
Merit Sex Match'em Up/Quik Kit 8 12
Premier/Gottlieb Gold Wings Fire Precaution 8 12
Skee Ball Potential Lethal Hazard 8 12
Williams Grand Lizard 8 12
Williams Flipper Discharge 8 12
Williams Ball Eject Plunger 8 12
Cranes/Merchandiser More on Fine-Tuning 8 12
Vending 1986 NAMA Convention 8 12
Misc Various Problems concerning Electronics Part 3 8 12
Atari Gauntlet 11 Reset Game Options 9 1
Bally Midway Spy Hunter Steering Roll Pins 9 1
Merit Bull Buster Catch Ring Kit Installation Tips 9 1
Premier Gottlieb Gold Wings Ball RElease Problems 9 1
Premier Gottlieb Gold Wings Genesis Conductive Solder 9 1
Romstar Tournament Arkanoid Retro-Kit 9 1
Skee Ball Potential Shock Retroo-Kit 9 1
Williams Pin Bot Fixes 9 1
Cranes/Merchandising Rotary Merchandiser Make Money 9 1
Cranes/Merchandising Big Choice Problems & Solutions 9 1
Monitors Electrohome Monitor Keystone Image Fix 9 1
Vending Food Merchandiser 2400 Drum Cover Mod 9 1
Miscellaneous Pinball Boards: Battery Corrosion Danger 9 1
Miscellaneous Tips for Operators & Technicians Part 1 9 1
Miscellaneous Inside Switching Power Supplies Part 1 9 1
Atari 5v Switching Supply Low Voltage 9 2

Bally Midway Special Force 9 2
Bally Midway Cabinet Preservation 9 2
Tradewest Ikari Warriors Joystick Replacement 9 2
Williams Millionaire Lock Ball Adjustment 9 2
Williams Pinball Switch Adjustments 9 2
Williams New Generation Flippers 9 2
Cranes/Merchandising Hot Picks/Big Choice Light Bulb Mod 9 2
Miscellaneous Control Marketing Inc Intros New Pushbutton 9 2
Miscellaneous Acme '87 Seminar Programs 9 2
Miscellaneous Tips for Operators & Technicians Part 2 9 2
Miscellaneous Inside Switching Regulators Part 2 9 2
Miscellaneous PCB Edge Connector Repair 9 2
Miscellaneous AMOA Expo '87 in Chicago November 5-7 9 2
Atari Pole Position Accelerator 9 3
Atari Joystick Report 9 3
Atari Gauntlet No Picture 9 3
Seeburg Help!Seeburg Component List Needed 9 3
Tradewest Ikari Warriors Tips & Tricks 9 3
Williams Millionaire Kick-Back Switch Replacement 9 3
Williams New Flipper Assy Update 9 3
Williams Pin Bot Resistor Damage 9 3
Williams F-14 Tomcat Shorting Condition 9 3
Williams Pin Bot Visor Operation 9 3
Cranes/Merchandising Big Choice Chaser Light Bulb Mod 9 3
Vending Automatic Products Snack Machines Lost Memory 9 3
Vending RMI 8050-G Coffee Machine Pawl Replacement 9 3
Miscellaneous Determining Sync Polarity With a Voltmeter 9 3
Miscellaneous Inside Switching Regulators Part 3 9 3
Miscellaneous The Player/Root's Machine 9 3
Ardac MBA Bill Acceptor Harness Strain Relief Caution 9 4
Bally Midway Hardbody Ball Escape 9 4
Exidy Top Secret Power Mod 9 4
Exidy Most Common Problems: Power Supplies 9 4
Merit Countertop Games + 12vdc Supply 9 4
Williams Pins Power Supply Low +5vdc 9 4
Cranes/Merchandising Big Choice Attraction Lights Mod 9 4
Monitors Electrohome Horizontal Tear 9 4
Miscellaneous Hot Summer Tip/Cover Pins 9 4
Miscellaneous Amusement Emporium Power Supply Failure 9 4
Miscellaneous A Word About Parts & Shipping 9 4
Miscellaneous The Octopus Analyzer Part 1 9 4
Atari Dunk Shot New Rom Updates 9 5
Atari Roadblaster Sitdown Speaker Hum 9 5
Bally Midway Strange Science Ball Trough Kit 9 5
Capcom Bionic Commando Credit Mod 9 5
Exidy Most Common Problems:Optic Electronics 9 5
Premier Gottlieb Spring Break Game Prom Change 9 5

Premier Gottlieb Spring Break Plastic Ramp Breakage 9 5
Valley Valley Pool Table Auto Locks 9 5
Williams Pins 50 Volt Flipper PM 9 5
Cranes/Merchandising Summer Updates 9 5
Miscellaneous Inside Switching Regulators Part 4 9 5
Miscellaneous The Octopus Analyzer Part 2 9 5
Atari System 1 TTL Rev A to Rev C Mod 9 6
Atari Roadblaster Kits/Intermittent Reset 9 6
Digital Controls Little Casino Power Mod 9 6
Premier Gottlieb Spring Break Multi Ball Mod 9 6
Rowe Black Modules R83 Rowe/AMI Jukes 9 6
Taito Double Dragon Disposable Cabinet 9 6
Williams F-14 Tomcat Improvements 9 6
Cranes/Merchandising Shoot to Win & Comer Notes 9 6
Monitors Electrohome GO-7 Chassis Capacitors 9 6
Miscellaneous Operators! We Need Your Feedback 9 6
Atari Gauntlet Audio Amp Sub Mod 9 7
Bally Midway Anti-Cheat Devices 9 7
Nintendo Playchoice 10 Top Monitor 9 7
Premier Gottlieb Late Model Pins Display Blanking 9 7
Rowe Hopper Payout Machine Motors 9 7
Sega Turbo-Mini Power Supply 9 7
Williams High Speed Flipper Update 9 7
Cranes/Merchandising Fantasy Island Revenues/Silver Ski Mod 9 7
Cranes/Merchandising Wedges/Ledges Claws Plush 9 7
Monitors Electrohome GO-7 Monitor Picture Locke 9 7
Vending Automatic Products Dual Volume Mod 9 7
Miscellaneous Inside Switching Regulators Part 5 9 7
Atari Star Wars Sound Board 9 8
Bally Midway Eight Ball Deluxe Sound Board 9 8
Centuri Toei Monitor Vertical Crunch 9 8
Nintendo Sanyo Monitor Distortion 9 8
Rowe Medeco T-Handle 9 8
Rowe Multi Products Motors 9 8
Sega Monitor Nano MC-2000-S Vertical Collapse 9 8
Tehkan Megaforce Abnormal Game Condition 9 8
Cranes/Merchandising Spin Out 1/Emporer/Hollywood 9 8
Cranes/Merchandising Light Burnout Fix 9 8
Vending Wittenborg Coffee Machines Lime Scaling 9 8
Miscellaneous How to Save Fuses While Troubleshooting 9 8
Atari Roadblaster Rolling RoadwayFix 9 9
Bally Midway Xenophobe Intermittent Reset 9 9
Capcom 1943 Resets During Game Play 9 9
Capcom Street Fighter Deluxe Air Cylinder Problems 9 9
Data East Kid Niki Video Glitch 9 9
Data East Karnov Program Change 9 9
Data East Kid Niki Screen Size Tip 9 9

Merit Nomac Pub Time Darts Coin Meter Installation 9 9
Premier Gottlieb Field Conversion for EOS Assy 9 9
Romstar Time Soldiers Joystick Hint 9 9
Romstar Coin Meter Hookup 9 9
Sega After Burner Loose Handlegrip Assy 9 9
Taito Double Dragon Intermittent Joystick 9 9
Cranes/Merchandising Top Crane Items/AMOA Show Picks 9 9
Monitors Wells Gardner High Voltage Shutdown 9 9
Miscellaneous Custom ICs: Pros Cons and Troubleshooting 9 9
Miscellaneous Flipper Orientation 9 9
Data East Ghostbusters New Program 9 10
Data East Pin Support 9 10
Data East Ghostbusters Easy Setting 9 10
Premier Gottlieb Power Supply Regulators 9 10
Premier Gottlieb Prom Update for Arema Samples 9 10
Romstar Time Soldiers Reset Problem 9 10
Williams Fire! Checks & Remedies 9 10
Williams 50v Flipper Coil Problems II 9 10
Cranes/Merchandising AMOA Chicago Show 9 10
Cranes/Merchandising Fantasy Island Problems & Solutions 9 10
Monitors Electrohome GO-7 5 year Capacitor Clean-Up 9 10
Miscellaneous Inside Look at Switch Matrixes 9 10
Miscellaneous AMOA Game Awards 9 10
Miscellaneous Fuse Substitution Box 9 10
Miscellaneous AMOA Expo '87 9 10
Atari APB Ram Error Codes 9 11
Atari APB Rom Update 9 11
Atari Matsushita Monitor Shutdown 9 11
Atari Roadblaster Option Setting Reset 9 11
Cinematronics Parts: A Source For Disc Games 9 11
Data East TKO Boxing Game Start Procedure 9 11
Merit Free Kick Conversion Kit Tips 9 11
Premier Gottlieb System 80 Chronology 9 11
Premier Gottlieb Pinball Driver Board Modification 9 11
Wico Review Positive Detent Joystick 9 11
Williams F-14 Tomcat High Speed Flipper Assembly 9 11
Monitors Electrohome GO-7 Flyback Failure 9 11
Monitors Wells Gardner 19K4615 Sync Problems 9 11
Monitors Wells Gardner 19K4675 Warped Picture 9 11
Miscellaneous 1987 Status of the Industry Survey:Salaries 9 11
Miscellaneous Safety Precautions: Danger Electrical Shock 9 11
Leland Care and Feeding of Quarterback 9 12
Leland Quarterback Program Revisions 9 12
Merit Model 5000 Crick Kits New Program 9 12
Nintendo R-Type Difficulty Setting 9 12
Nintendo VS System and Playchoice 10 System Guns 9 12
Taito Double Dragon Button Cure 9 12

Cranes/Merchandising Lotto-Fun Lottery Game 9 12
Monitors Wells Gardner 4600 Series Capacitor Change 9 12
Miscellaneous Cleaning Up After Leaky Batteries 9 12
Miscellaneous Parts That Fail Often: Z80's By SGS/Xtal Osc Pkg 9 12
Miscellaneous Look Out Operators - The Elephants Are Stampeding 9 12
Miscellaneous Changes - Changes - Changes 9 12
Miscellaneous Suggestions for the Aspiring Technician 9 12
Atari 720* Joystick Control Update 10 1
Atari Responds to Operator Letter 10 1
Atari Blasteroids Images & Sound 10 1
Atari 720 & Road Blaster Power-Up 10 1
Bally/Midway Heavy Metal Pwr Shot 10 1
Data East Laser War Problem/Solution 10 1
Data East Laser War Modifications 10 1
Gottlieb Diamond Lady Playfield 10 1
Merit Bull Buster Darts Cab Brackets 10 1
Nintendo Sanyo Monitor Cap Failure 10 1
Seeburg SCD-1 Mic Problems 10 1
Suzo Inductive Joystick Review 10 1
Taito Double Dragon Blown Traces 10 1
Tecmo Rygar Eprom Replacement 10 1
Wells Gardner 4600 Black Level 10 1
Williams Matrix Xsistor Replacement 10 1
Miscellaneous Flippers: Improve Action/Reliability 10 1
Miscellaneous It Has Arrived! S*TJ BBS 10 1
Bally/Midway Rabbit Punch Wiring 10 2
Data East Vigilante Pwr Supply Short 10 2
Data East Vigilante Credit Pricing 10 2
Data East Ghostbusters ROM 10 2
Gottlieb System 80/80A Trans/Coils 10 2
Intermark Basketball Display 10 2
Kiddieride Hydraulic Leaks 10 2
Sega Shinobi Kit Switches 10 2
Sega Color Codes 10 2
Suzo Joystick Technical Review 10 2
Taito Operation Wolf Gun Problems 10 2
Wells Gardner 194901 Brightness 10 2
Miscellaneous ACME '88: The Show in Review 10 2
Miscellaneous Coil Coil Who's Got the Coil? 10 2
Miscellaneous ACME Seminar: Basic Technical 10 2
Condor Power Supply Low +5v 10 3
Data East Heavy Barrel Score Entry 10 3
Exidy Rapid Fire For Gun Games 10 3
Gottlieb Solenoid Voltage Short 10 3
IGT Electroport Poker Memory Fix 10 3
Konami A Jax Error Codes 10 3
Merit Pit Boss II CRT-250 PCB 10 3

Premier Flipper Display Failure 10 3
Rockola Video Capacitor Failure 10 3
Smart Shoot To Win II Basketball 10 3
Suzo & Wico Joystick Updates 10 3
Taito Operation Wolf Gun Problems Part 2 10 3
Taito Renegade Sound Board Mod 10 3
Wico & Suzo Joystick Updates 10 3
Williams New Opto Targets 10 3
Miscellaneous Street Talk For The Operator 10 3
Miscellaneous Industry Survey: Joysticks 10 3
Miscellaneous Joystick Mounting Template 10 3
Miscellaneous Online: Game Security 10 3
Miscellaneous Socket Those New Chips 10 3
Atari System One Burnt Fuse Holder 10 4
Atari Handle Switch Failure 10 4
Atari Blasteroids Audio Eproms 10 4
Atari System One: Road Blaster 10 4
Bally/Midway 7533 DAC Failures 10 4
Data East Secret Service Ball Trap 10 4
Data East Secret Service Audio Mod 10 4
Hantarex PCB Screening Error 10 4
Leland Super Dodge Ball Lock-Up 10 4
Merit Pub Darts Static Problem 10 4
Nanao Monitor Deflection Problem 10 4
Rowe Changers:Transport/Hopper 10 4
Sega Outrun Lube Requirements 10 4
Sente Mini-Golf Trak-Ball Problems 10 4
Williams Reply: Customer Service Challenge 10 4
Monitors Reduce Screen Dust 10 4
Miscellaneous Industry Survey Switch Power Supply 10 4
Miscellaneous Commentary: Game Difficulty 10 4
Miscellaneous Standardization: Jamma Connect 10 4
Data East Bad dudes Lock-Up/dips 10 5
Konami Blades of Steel Audio Prob 10 5
Leland Viper Vertical/Horizontal Align 10 5
Leland Viper Rom Update 10 5
Merit Pit Boss II Eprom Update 10 5
Nintendo Monitor Video Inversion Mod 10 5
Rowe Bill Changer Cap Failure 10 5
Sega Thunder Blade Shaft Pin 10 5
Smart Shoot To Win II Rom Update 10 5
Wico Rotary Joystick Modification 10 5
Williams Pinball Fire Hazard 10 5
Miscellaneous AMOA Educational Seminars 10 5
Miscellaneous Industry Survey: Computers In Work 10 5
Miscellaneous Conversion Cabinet Preferences 10 5
Miscellaneous New Cherry Switch Buttons 10 5

Miscellaneous Coin-Ops Discuss Home Games 10 5
Atari Road Blasters Contest Option 10 6
Bally/Midway Party Animal Pinball Coil 10 6
Capcom Bowling Credit Rom Update 10 6
Capcom Marquees/Sega\$/Capcom Bowling 10 6
Data East Heavy Barrel Video Wave 10 6
Data East Secret Service Update 10 6
Drew's Card Games Pwr Supply Adj 10 6
Drew's Tiger Paw Light Mod 10 6
Konami Blades of Steel Update 10 6
Kramer High Speed Bonus Diode Mod 10 6
Romstar Gold Medalist Start Mod 10 6
SNK Fighting Golf Program Update 10 6
SNK Rotary Joystick Fix 10 6
Sega Marquees/Capcom/Sega \$ Bowling 10 6
Williams Buys Out Bally Coin-Op 10 6
Miscellaneous The Ideal Cabinet Design 10 6
Miscellaneous The Parallel PCB Issue 10 6
Miscellaneous One Parallel PCB Drawback 10 6
Miscellaneous AMOA Industry Standardization 10 6
Amplifone X-Y Replacement Flyback 10 7
Atari Tempest X-Y Modification 10 7
Capcom Bowling Power-Up Problem 10 7
Fabtek Dead Angle Thermal Failure 10 7
Merit Pub Time Program Update 10 7
Romstar Gold Medalist Panel 10 7
Sega Thunder Blade Liquid Spill Fix 10 7
Williams To Maintain Bally Pin Line 10 7
Williams Flipper Coil Failure Routine 10 7
Monitors Sharpness Can Be Restored 10 7
Miscellaneous AMOA Seminars Get Exc Ratings 10 7
Miscellaneous Intermittent Joystick Fix 10 7
Miscellaneous Red Baron-Taito-AAMA Update 10 7
Miscellaneous Game Documentation Discussion 10 7
Miscellaneous CoinCo Doors Security Problem 10 7
Miscellaneous AMOA Expo '88 Booth Space 10 7
Miscellaneous Understanding Static 10 7
Atari Final Lap Gear Shift Mod 10 8
Atari Final Lap Steering Upgrade 10 8
Atari Final Lap Power Supply Covers 10 8
Bally/Midway Party Animal Coil Follow-Up 10 8
Drew's Card Games Coin Return 10 8
Fabtek Dead Angle Volume Control 10 8
Fabtek Dead Angle Loss of Credit 10 8
Fabtek Dead Angle Arcade/Bar Opt 10 8
Konami WEC Lemans Steering Kit 10 8
Merit Pub Time Darts Monitor Dag 10 8

NSM Jukebox Capacitor Failure 10 8
NSM Jukebox Mechanism Switch 10 8
Sega Bull's Eye Technical Update 10 8
Williams Space Shuttle Drop Targets 10 8
Monitors Reduce Phosphor Burn 10 8
Miscellaneous Gameroom Appearance Tips 10 8
Miscellaneous CRT Analyzers/Rejuvenators 10 8
Miscellaneous Maytag Procedure for Drink Spills 10 8
Miscellaneous Parallel Case Reaches A Decision 10 8
Miscellaneous How To Stop Flipper Coil Burnup 10 8
Miscellaneous Drilling Plexis w/o Breaking Them 10 8
Atari Blasteroids Intermittent Sound 10 9
Data East Fuse Change 10 9
Drew's Tiger Paw Limit Switches 10 9
Drew's Tiger Paw Drive Belts 10 9
IGT Draw 80 2716 Adapter Mod 10 9
Leland Quarterback Springstick Action 10 9
Merit Pub Time Program Update 10 9
Taito Continental Circuit Design 10 9
Wico Trackball Installation 10 9
Williams Flipper Coil ID Chart 10 9
Miscellaneous Increase Claw Power Increase Revenues 10 9
Miscellaneous Video Interference Cure 10 9
Miscellaneous Route Tip 10 9
Miscellaneous Resourcefulness 10 9
Miscellaneous Parallel PCB Market 10 9
Miscellaneous Silkworm Idea for Mach 3 Sitdowns 10 9
Miscellaneous Location Fun 10 9
Atari Assault Leaf Switches 10 10
Atari Assault Stereo Spkr Hookup 10 10
IGT Draw 80 Poker Auto-Bet/Deal 10 10
SNK POW PCB Modification 10 10
SNK POW Credit Modifications 10 10
SNK POW Memory Substitutes 10 10
Sega Replies 10 10
Williams High Speed Bumper 10 10
Monitors Medium Resolution 10 10
Miscellaneous Control Panel Design w/Template 10 10
Miscellaneous AMOA Expo 1988: Out in Chicago 10 10
Miscellaneous Chicago SUG Conference 10 10
Miscellaneous Convention Time '89 10 10
Miscellaneous Winners! 1987-88 AMOA Games 10 10
Miscellaneous AMOA Approves New Logo 10 10
Miscellaneous Emergency Alert on Bill Changers! 10 10
Ardac MBA's Have Major Problems 10 11
Atari Rolling Thunder Audio 10 11
Drew's Tiger Paw Cranes Claw Adj 10 11

Drew's Software Versions 10 11
Drew's Joker Poker 54 Dix Conv 10 11
Hollywood Crane Potential Shock 10 11
Leland Coin Input Circuit 10 11
Mars MBA's Have Major Problems 10 11
Merit Pit Boss II & Super Video Mod 10 11
Rowe Training Dates Announced 10 11
Seeburg CD Box Code Changes 10 11
Sega Company Rebuilds Sega Motors 10 11
Wells Gardner 19K7901 Int'mt Fix 10 11
Wico Switching Supply Repair 10 11
Monitors Width Size Change 10 11
Miscellaneous Conversions Made Easy - 24 Steps 10 11
Miscellaneous Build Your Own Test Equip Project 10 11
Miscellaneous Sounding Off I - Taito Quality 10 11
Miscellaneous Sounding Off II - Media Watch 10 11
Miscellaneous Mfg Customer Service Gets Thumbs Up! 10 11
Miscellaneous Big Ops Middle Ops & Little Ops 10 11
Arachnid 6000 Monitor Cures 10 12
Arachnid Coin Credit Card PCB 10 12
Atari Star Wars Color Modification 10 12
Bally/Midway Truck Stop Modifications 10 12
Bally/Midway Black Water 100 Ball detect 10 12
Coin data Turbo Poker Upgrade 10 12
Data East Robo Cop Free Play Fix 10 12
Merit Premier Video Dart Resistor Mod 10 12
Micro Prose Enters Coin-Op 10 12
Namco Shoot Away Rifle Repair 10 12
Nintendo VS Hum Bars 10 12
Rowe News Service Hotline 10 12
Sharp 19 Monitor Retrace Lines 10 12
Wells Gardner 19K7901 Solder 10 12
Miscellaneous New Duralink Replaces Alumilink 10 12
Miscellaneous AMOA Adds Two Standardizations 10 12
Miscellaneous Operator Game Performance Charts 10 12
Miscellaneous Winter CES Show: New Type Joystick 10 12
Data East Breakthru Test Mode 8 11
Arachnid 6000 Scrambled Video 11 1
Capcom Bowling Resetting Check 11 1
Data East XR-7 Flipper Link 11 1
Data East Laser War Coil Burnout 11 1
Hantarex Monitors Stable Sync 11 1
LeLand Coin Input Ckt Clarification 11 1
MMI Bill Changer ID & Cure 11 1
Rowe ShowMax 448E Update 11 1
SNK POW Background Scenery 11 1
Seeburg CD Intermittent Problems 11 1

Sega Controls Maintenance 11 1
Taito Chase H.Q. Monitor Problem 11 1
Taito Chase H.Q. Cabinet Upgrade 11 1
Wells Gardner 19K4600 Keystone 11 1
Miscellaneous Lock-Tite & Prevent Maintenance 11 1
Miscellaneous Motorola Semiconductor List BBS 11 1
Miscellaneous Diode/Coil Tester Modification 11 1
Miscellaneous Troubleshooting Hi Tron Supplies 11 1
Miscellaneous Servicing Fluorescents:Marquees 11 1
Miscellaneous Ten Commandments of Safety 11 1
Bally/Midway Rampage Roll Video 11 2
Merit Pubtime Cricket Power Supply 11 2
Premier Hot Shots Ball Launch Eject 11 2
Romstar Arkanoid Rotary Joysticks 11 2
Romstar Power UpYour Bubble Bobble 11 2
Rowe Hotline Phonos - MBAs 11 2
Rowe CD 100 Field Feedback 11 2
Sega Out Run Gear Shift Box 11 2
Toei Monitor Vertical Deflection 11 2
Toei Monitors - Symptoms/Fixes 11 2
Williams King Tut Bowler Displays 11 2
Williams Switch Matrix T'Shooting 11 2
Monitors Video Monitor Capacitor Types 11 2
Miscellaneous Hi-Tron Switch Power Up 11 2
Miscellaneous Dynamo Cabinet Ground Noise 11 2
Miscellaneous Industry Standards & Compliance 11 2
Miscellaneous ACME '89 Game Watch 11 2
Miscellaneous ACME '89 Reno Exposition 11 2
Atari Tempest Resurrection 11 3
Atari Tetris Random Lock-Up 11 3
Bally/Midway Centaur Speaker Hum Fix 11 3
Electrohome GO7 Keystone Prob 11 3
LeLand Super Off Road Notes 11 3
Merit Pub Time Display Blanking 11 3
Premier Goldwings Intermittent Start 11 3
Rock Ola 474 Faulty Credits 11 3
Sega Afterburner Reset Fix 11 3
Sega Wrestle War Harness Kit 11 3
Sega Hang On Cable Service 11 3
Taito Thunderbolt Aux Power 11 3
Taito Chase H.Q. Steering Mod 11 3
Wells Gardner 19K4914 Sizing 11 3
Williams Jokerz Aux Power Driver 11 3
Monitors Understanding How CRTs Work 11 3
Miscellaneous Rotation Don't Duplicate Titles 11 3
Atari 720 Faulty Steering Tip 11 4
Capcom Bowling Overheating 11 4

<http://www.startechjournal.com>

LeLand Super Off Road Settings 11 4
Micrologic Review of 4-Play 11 4
Rock Ola #52255A Battery Pack 11 4
SNK Tradewest Video Interference 11 4
Sega Hang On Input Caps 11 4
Sega Outrun Parts Non-Availability 11 4
Sirmo Bingo Bulbs 11 4
Taito US Classic Ram Clear 11 4
Taito Superman Memory Hardware 11 4
Taito Renegade Audio Noise 11 4
Williams Zero-Ohm Resistors 11 4
Williams Earthshaker! Notes 11 4
Miscellaneous Increase Revenues: Multi-Game 11 4
Miscellaneous How to Add a Coin Meter Circuit 11 4
Miscellaneous Peter Chou Power Regulation 11 4
Miscellaneous Customer Service Survey Results 11 4
Atari Pole Position Disco Monitors 11 5
Atari Gauntlet Joystick Problem 11 5
Data East New Solid State Flipper 11 5
Data East Playboy Kicker & RFamp 11 5
Electrohome Shifting/Expanding GO-7 Monitors 11 5
Gottlieb CPU Board Trade-Ins 11 5
NEC VS Nintendo Home Games 11 5
Nintendo Vs NEC Home Games 11 5
Rowe R-86 Intermittent Play 11 5
Seeburg SHP Amps 11 5
Sega Turbo Outrun Conversion Kit 11 5
Taito Operation Wolf Gears 11 5
Taito US Classic Track Ball 11 5
Wells Gardner K4600 Neg Sync 11 5
Williams Fluorescent Lamp Mod 11 5
Williams Taxi Flipper Power 11 5
Williams 4-Part Pinball Test 11 5
Miscellaneous Industry Standards Compliance 11 5
Miscellaneous Coin Mechs Survey 11 5
Miscellaneous ACME '90 at the Chicago Hyatt 11 5
Miscellaneous The Area Code Secret D'Coder 11 5
Atari Asteroids X-Y Monitor Fuse 11 6
Bally/Midway 125VA Power Supply Reset 11 6
Happ Rx for Trackballs 11 6
Rock Ola 478 Intermittent Lock-Up 11 6
Seeburg SMC-1 & SMC-2 Tips 11 6
Sega Power Drift Throttle Gear 11 6
Taito Big Event GolfI/O Error 11 6
Williams Arch Rivals Installation 11 6
Williams Narc Software Versions 11 6
Miscellaneous AMOA Standards Compliance 11 6

Miscellaneous AMOA Standards Compliance List 11 6
Miscellaneous Rescue Damaged Video Discs 11 6
Miscellaneous Survey: Game Themes & Marketing 11 6
Miscellaneous Customer Service Poll Response 11 6
Miscellaneous Red Baron Case 11 6
Miscellaneous Pins: 50 Cent Play at 5 Balls 11 6
Arachnid 6000 Dart Monitors 11 7
Atari Testris Eprom 11 7
Atari Hard Drivin' Seat Screech 11 7
Bally/Midway Blasted Non-Jamma 11 7
Capcom Bowl Static Reset 11 7
Data East Time Machine Mods 11 7
Happ Spring Action Joystick 11 7
Happ Ultimate Pushbutton 11 7
Hollywood Monster Crane Sw Short 11 7
Mars VFM4-R1 Bill Acceptors 11 7
MicroProse Arcade Technology 11 7
Sega Hang On Cables Fraying 11 7
Sega Super Monaco Options 11 7
Taito Double Dragon Back to Court 11 7
Williams Jokerz Lamp Bus Failures 11 7
Monitors Kristel Monitor Vertical Foldover 11 7
Miscellaneous East Coast Design UV-19 & UV-25 11 7
Miscellaneous STAR*TECH Journal BBS 11 7
Miscellaneous Conversions That Save Time & \$\$ 11 7
Miscellaneous Marquees in the Sun 11 7
Miscellaneous Industry Survey:Failure- Parts 11 7
Atari Pole Position Microswitch Mod 11 8
Electrohome GO7 Vertical Defl 11 8
Electrohome GO7 Replace Cap 11 8
Nintendo PlayChoice-10 Dip Switch 11 8
Nintendo PlayChoice-10PCB Mod 11 8
Sega Save Your Afterburner 11 8
Miscellaneous AMOA Standardization Committee 11 8
Miscellaneous Compatible PCB's Interchanging 11 8
Miscellaneous As the Court Turns 11 8
Miscellaneous Comments on Service 11 8
Miscellaneous AMOA Expo '89 Las Vegas 11 8
Miscellaneous State of the Industry: AMOA '89 11 8
Atari Crime Fighters into Gauntlet 11 9
Atari Gauntlet Conversion for V-Ball 11 9
Bally/Midway Elvira: A New Bally Pin 11 9
Capcom Bowling Coin Meter Ckt 11 9
Data East Pin:Solid State Flippers 11 9
Drews Eprom Versions 11 9
Fabtek Toki Add Player Control 11 9
Hantarax Herringbone Pattern Fix 11 9

<http://www.startechjournal.com>

Konami Crime Fighters Prog Bug 11 9
Konami Crime Fighters into Gauntlet 11 9
Merit II Plus 2 ricket Kit Update 11 9
SNK Extended Customer Service 11 9
Sega Super Monaco New Wheel 11 9
Showcase Quicksilver Problems 11 9
Taito Gauntlet Conversion for V-Ball 11 9
Techno WWF Superstars Update 11 9
Wells Gardner 7900 Horiz Collapse 11 9
Miscellaneous New Industry Seminar Program 11 9
Miscellaneous 1988-89 AMOA Game Winners 11 9
Miscellaneous Recycling Those Unused Parts 11 9
Miscellaneous Recommended Disk Head Cleaners 11 9
Atari Cyberball 2072 Tournament 11 10
Atari Assault Trigger Switch Mod 11 10
Atari Cyberball 2074 Update Tip 11 10
Data East Speed Buggy Opto 11 10
Hantarex MTC 9000 Current Ltd 11 10
LeLand Viper & Quarterback Freez 11 10
Merit Pub Time Jumpy Video 11 10
Merit Pub Time Scoring Problems 11 10
Merit Pub Time Misc Solutions 11 10
Sega Super Monaco GP Handle 11 10
Showcase Gameco Responds Quicksilver II 11 10
Williams Black Knight 2000 Door 11 10
Williams Elvira Contest Mode 11 10
Williams Black Knight 2000 Plexi 11 10
Monitors Disco Monitor Sync Lock 11 10
Miscellaneous Mfg Board/Chip Reference List 11 10
Coin Controls Door Credits 11 11
Coin Controls Sharp Vaults 11 11
Data East MonNite Football Q54 11 11
Data East Solid State Flipper 11 11
Data East Pin Special Solenoid 11 11
Hantarex Replacement Xsistors 11 11
Konami NinjaTurtle Stress Relief 11 11
Konami NinjaTurtle Adj 11 11
Sega Super Monaco GP Play 11 11
Taito US Classic Memory Loss 11 11
Williams Elvira Ball Trough Jam 11 11
Miscellaneous Control Panel Cleaning Tips 11 11
Miscellaneous Install a Bill Acceptor 11 11
Miscellaneous Blank Cabinet Evaluation 11 11
Miscellaneous Rapid Start Fluorescent Lamp 11 11
Arachnid 6300 Darts Sw Bounce 11 12
Data East Pinball: Dead Batteries 11 12
Hantarex MTC 9000 B+ Voltage 11 12

LeLand Team Qback Wiring 11 12
MicroProse F-15 Strike Eagle 11 12
Rowe VidJukes Pricing Precaution 11 12
SNK Beast Busters Gun Update Kit 11 12
Sega Afterburner Controls Check 11 12
Sega Preventive Maintenance 101 11 12
Strata Wheel of Fortune Trackwheel 11 12
Taito Steering Wheel Update Kit 11 12
Williams Memory Protect Ckt 11 12
Miscellaneous Looking for a Inclinometer? 11 12
Miscellaneous Open Forum: Tech Edge Controls 11 12
Miscellaneous Substitute Faulty Audio Amps 11 12
Miscellaneous Get the Most with What You've Got 11 12
Bally/Midway Tri-Sports Flicker 12 1
Bally/Midway Pins Switch Matrix 12 1
Electrohome Wells Gardner Fad 12 1
Konami Ninja Turtle Blues 12 1
Motorola New Cross Reference 12 1
Premier Boost Your Earnings System 80B Pins 12 1
Sega System 24 Floppy Memory System 12 1
Wells Gardner Fading 12 1
Wurlitzer Carnegie CD Juke Box 12 1
Misc Handy Storage Containers 12 1
Misc Remove Solder Flux Safely 12 1
Misc Open Forum:Game Adjustments 12 1
Misc Game Commercials 12 1
Misc Three Coins and a Counter 12 1
Misc Beware the Crystal Explosion 12 1
Misc Touchy Volume Controls 12 1
Atari Games Sweeps Mfg AAMYS 12 2
Bally/Midway Trough Mech 12 2
Betson Big Choice Voltage Spikes 12 2
Nintendo Dual Interference Cure 12 2
Sega Outrun Steering Base & Shifter 12 2
Williams Trough Mechanism 12 2
Misc Ozone Layer Update 12 2
Misc Open Forum:Home vs Arcade Games 12 2
Misc Technological Adv Warranty 12 2
Misc ACME Expo '90 New Games Review 12 2
Misc The Quick & Dirty Inclinometer 12 2
Misc Rebuild Old Truck or Buy New? 12 2
Atari Badlands Foot Pedal Mod 12 3
Hantarex MTC 9000 Sync Problem 12 3
Hantarex MTC 9000 Blank Screen 12 3
NSM City IV & Galaxy CD Pricing 12 3
Premier System 3 New Features 12 3
Skeeball Install a Keypswitch 12 3

<http://www.startechjournal.com>

SNK Beast Busters Gun Calibrate 12 3
Wells Gardner 19K4604 Collapse 12 3
Wells Gardner Picture Width 7601 12 3
Williams Earthshaker Display/Sound 12 3
Misc Open Forum:Kit Versions-Toll Free Service 12 3
Misc Open Forum:Formica Cabinets-Game Manuals 12 3
Misc Parts Suppliers:National Houses 12 3
Misc Panel Overlay Adhesive Remover 12 3
Ameri Corp Ameri Darts Vol Mod 12 4
Atari Hard Drivin' Steering/Brake 12 4
Bally/Midway Galaga Older WG Pix Tube 12 4
California Coin Inside King Arthur's Round Table 12 4
Dynamo Air Hockey Coin Mech 12 4
Electrohome GO7: Dead Monitor 12 4
Electrohome GO7: Power Supply 12 4
Electrohome GO7: Curved Picture 12 4
Electrohome GO7: Blank Screen 12 4
Electrohome GO7: Bright Pix 12 4
Electrohome GO7: Vertical Line 12 4
Fabtek Toki Dip Switch Bypass Mod 12 4
Seeburg Extends Technical Help 12 4
Wells Gardner 4600 - 4900 Tips: Keystoned Picture 12 4
Wells Gardner 4600 - 4900 Tips: Horizontal Line 12 4
Wells Gardner 4600 - 4900 Tips: Jumpy Video 12 4
Wells Gardner 19K4914 Intermittent Fix 12 4
Williams F-14 Tomcat Tilting 12 4
Misc Skydiver Simulator 12 4
Misc Time for Higher Commissions 12 4
Misc Heavy Duty Power Supply Source 12 4
Data East Time Machine Lock-Up 12 5
Data East Wacky Gator Dividers 12 5
Data East Wacky Gator Program 12 5
Dynamo Testing Power Plus 12 5
Happ Controls' Super Joystick 12 5
Premier System 80B Bad Displays 12 5
Seeburg Laster Lens/Disc Cleaning 12 5
Sega System 24 Games Floppy 12 5
Tecmo Ninja Gaiden IC Pin Sealing 12 5
Technos Ram Problems WWF Superstars 12 5
Williams Black Knight Switch 12 5
Williams Whirlwind LED Fade Out 12 5
Williams System II Solenoids 12 5
Williams Whirlwind Ball Lock 12 5
Williams Rollergames Error Dot 12 5
Misc Cassette Entertainment Center 12 5
Misc Peter Chou Clears the Record 12 5
Misc Long Distance Phone Access Codes 12 5

Misc Answers to Operator Split 12 5
American Sammy DJ Boy Logic Board Lock-Up 12 6
Atari Hard Drivin' Substitute Pot 12 6
Atari Notes for Hydra Kits 12 6
Data East Speed Buggy Sensor 12 6
Merit Pub Time II Plus 2 New Eprom 12 6
MicroProse Games F-15 Update 12 6
Williams Black Knight Opto 12 6
Williams Black Knight Lock-Up 12 6
Williams Rollergames Rubber Ring 12 6
Williams Rollergames Deep Freeze 12 6
Williams Rollergames Diverter 12 6
Misc New Utility on S*TJs BBS 12 6
Misc National Technical Seminar 12 6
Misc Piggy Back PCBs - CPU Sockets 12 6
Misc WG Med Res - Surface Mount Caution 12 6
Misc CRT Blaster - Wms Test Rom- Cabinet Alert 12 6
Bally/Midway Pool Sharks AC Relay 12 7
Bally/Midway Games By System 12 7
Dynamo Air Hockey Coin Mech 12 7
Hantarex MTC 9000 Pix Width 12 7
Premier Silver Slugger Orbit Shot 12 7
Rowe Show Off Your Rowe Laser Star 100 12 7
Sega Audio Problems: System 16B 12 7
SMS Poker Roll Coining 12 7
Williams System II Changes 12 7
Williams Reset Problem 12 7
Williams Games By System 12 7
Misc Equipment Clean-Up Tip 12 7
Misc New Cross-Reference Utility 12 7
Misc Heavy Duty Power Supplies 12 7
Misc Formica Your Cabinet 12 7
Misc Using a Router for Plexi 12 7
Betson Big Choice Test Jig 12 8
Capcom Pang Security Alert 12 8
Data East Back to the Future Lamps 12 8
Dynamo Power Plus Supply Notes 12 8
Intermark Games Basketball Fix 12 8
SNK Ops In Neo-Geo Home Mkt 12 8
Taito US Classic Encoder Mod 12 8
Wells Gardner 13K7801 No Raster 12 8
Williams Smash TV Slam Switch 12 8
Williams Flipper Replacement Kit 12 8
Williams Pinball Power Supply Fix 12 8
Williams Diner Playfield Mod 12 8
Misc Opto & LED Electronics Source 12 8
Misc Pinball Plastics & Temperature 12 8

<http://www.startechjournal.com>

Misc Q&A: Solid State Flippers 12 8
Atari Afterburner Throttle Sub 12 9
Bally/Midway Squawk & Talk Audio Fix 12 9
Cinematronics Baseball II Reset 12 9
Data East Power-Up & Audio Hum 12 9
Data East Pinball Parts Kit 12 9
Data East Status: Solid State Pins 12 9
Nintendo VS System Conversions 12 9
Premier Silver Slugger Sw Software 12 9
Rowe Jukes OBA Compatibility 12 9
Sanwa Monitor Sync Problem 12 9
Sanyo Monitor Video Raster Shift 12 9
Taito Chase HQ Steering Parts 12 9
Misc Another Power Supply Source 12 9
Misc AMOA Expo '90 In Review 12 9
Misc AMOA Expo '90 Best & Worst Video 12 9
Misc De-zapping CRT High Voltages 12 9
Arachnid Dart Spiders 12 10
Drew Deuces Wild Video Fix 12 10
Leland Ataxx Kits Volume Control 12 10
Nintendo Playchoice-10 Rom Mod 12 10
Nintendo Coin-Op New Hotline 12 10
Nintendo PP-1200 Supply Fix 12 10
Nintendo R-Type Audio Problem 12 10
Romstar Sky Shark Lock-Up Fix 12 10
Romstar Top Speed Optic Steering 12 10
Rowe BC-25 Coin Changer Problems 12 10
Sega Galaxy Force Bad Welds 12 10
Wells Gardner 7000 Vertical Roll 12 10
Williams Police Force Display 12 10
Williams Drop Target Optos 12 10
Misc Electronic Tech Security Outlook 12 10
Misc Electronic Tech Salary Report 12 10
Misc 1989-90 AMOA Award Winners 12 10
Misc Area Code Decoder 12 10
Misc Parallels To Be Legal In One Year 12 10
Misc Selecting a Conversion Cabinet 12 10
Atari Pole Position Switcher Sub 12 11
Betson Big Choice Door Problems 12 11
Data East Simpson's Ball Jump 12 11
Data East Simpson's Gnd Fault 12 11
Taito Chase HQ Low Power Fix 12 11
Wells Gardner 4900 Vertical Fold 12 11
Williams Pins Intermittents 12 11
Williams Opto Target Complaint 12 11
Williams Pinball Display 12 11
Williams Flipper Checklist 12 11

Misc AMOA New Standard #28 12 11
Misc Circuit Chilling Techniques 12 11
Misc FCC Public Access Link 12 11
Misc Video Game Sales for 1991 12 11
Misc The New Year: Our Year? 12 11
Misc AMOA Ok's Contract Dollar Coin 12 12
Data East Pinball Promotions 12 12
Data East Simpson's Ball Trap 12 12
Data East Flipper Assy Improves 12 12
Merit Scorpion Target Software 12 12
NSM Title Display Jamming 12 12
Sega Thunder Blades Garbled Video 12 12
Sega Hang On Break Cable Mod 12 12
Taito Chase HQ Foot Pedal Switch 12 12
Wells Gardner 4600 Screen Cont 12 12
Williams Rollergames Display Fix 12 12
Misc General Service Order Form 12 12
Misc Build a Monitor Test Station 12 12
Atari Hard Drivin' Brake 13 1
Atari Badlands Pedal Conversion 13 1
Data East Monday Nite Slam 13 1
Data East Simpsons Targets 13 1
Data East Simpsons Lost Balls 13 1
Dynamo Overhead Displays 13 1
Microprose F-15 Software Revision 13 1
SNK Installing SNK's Neo Geo Kit 13 1
Williams Funhouse Head Mod 13 1
Williams Funhouse Multiball 13 1
Misc World According to Beck Part II 13 1
Misc Volume 12 Index: 1991 13 1
Misc Cutting Your T'shooting Time 13 1
Bally Vs Williams Flippers 13 2
Betson Crane Claw String 13 2
Data East Pin Spring 13 2
Data East Robocop Gate 13 2
Hantarex MTC9000 Flybacks 13 2
Konami Hand Video 13 2
Premier Silver Slugger T'shooting The Matrix 13 2
Taito Chase HQ Static Prone IC 13 2
Williams Vs Bally Flippers 13 2
Williams Funhouse Part #2 13 2
Williams Funhouse GI 13 2
Williams Funhouse Plunger 13 2
Williams Replacement Semis 13 2
Williams Hit the Ice Harness 13 2
Wurlitzer CD Disc/Arm 13 2
Misc Coin Door Kick-Out Switch 13 2

<http://www.startechjournal.com>

Misc ETA wages Statistics 13 2
Misc Aerial Combat Simulators 13 2
Misc Perfect Billiards Micro 13 2
Misc A Tool For The 90's 13 2
Misc CRT Alignment 13 2
Bally & Stern Pinball Tester 13 3
Microprose F-15 Connections 13 3
Rowe CD-100 Scratched CDs 13 3
Rowe CD-100 & CD-51 Play 13 3
Rowe OBA-2 Bill Transport Repair and Maintenance (Part 1) 13 3
Sanyo Monitor Vertical Lines 13 3
Sega Enduro Racer Steering Stop 13 3
Stern/Bally Pin Tester Review 13 3
Williams New Playfield Coating 13 3
Williams Flipper Power Coils 13 3
Williams Intros New Technology 13 3
Williams Funhouse Plunger 13 3
Misc So Ya Like the ACME Show? 13 3
Bally Two Bit Score MPU Test Set 13 4
Capcom Street Fighter II Button 13 4
Namco Final Lap 2 Volume Pot 13 4
Nintendo Baseball Stars Rom 13 4
Nintendo Monitor Retrace Lines 13 4
Rowe Jukebox Lid Prop 13 4
Rowe OBA-2 Bill Transport Repair and Maintenance (Part 2) 13 4
SNK Neo Geo Kit Installation 13 4
Sega Thin Steel Construction 13 4
Sega Chassis Movement Problem 13 4
Stern Two Bit Score MPU Test Set 13 4
Taito Chase HQ Static Response 13 4
Wells Gardner K4600 Vert Defl 13 4
Williams Funhouse Switch 13 4
Misc 1991 ACME Show Tech Notes 13 4
Misc Series/Parallel Flipper Conv 13 4
Misc Perfect 360 Joystick System Report 13 4
Atari Centipede Distorted Audio 13 5
Bally Gilligan's Island Popper 13 5
Betson Reel Poker Meter Pulsing 13 5
Data East Desert Assault Mod 13 5
Data East TMNT Ball Shooter Fix 13 5
Data East Simpsons Progress 13 5
Hantarex MTC9000 Horiz Width 13 5
Nintendo Monitor Tear 13 5
Nintendo Monitor Bars 13 5
Redemption The Ticket Bypass Circuit 13 5
Rowe R-89 Juke Backwards Play 13 5
Rowe CD-51 Disks 13 5

Rowe CD-100 AC Noise 13 5
Wells Gardner Output Xsistors 13 5
Williams Pinball Display 13 5
Williams High Impact Language 13 5
Misc New Analog Flipper 13 5
Misc Quality Conversion Parts List 13 5
Misc Bozo's Grand Prize New Pails 13 5
Atari Tempest Shorting Pins 13 6
Atari Road Riot Is UL Listed 13 6
Betson Crane Diodes 13 6
Greenwald Coin Chutes 13 6
Merit Pie Segments 13 6
Midway Dr. Dude Heart Target 13 6
Midway Gilligan's Island Ramp 13 6
Redemption Install Ticket Advance Pushbutton 13 6
SNK Evaluating Neo Geo 13 6
Williams Slugfest Pitching 13 6
Williams Funhouse Rubber 13 6
Williams Programs Out Failures 13 6
Williams Rejectors 13 6
Williams System II Diagnostic 13 6
Misc Cellular Telephone Static Cures 13 6
Misc Use Circuit Breakers Instead of Fuses 13 6
Misc AMOA Nominations 13 6
Misc Series/Parallel Flipper Conversion 13 6
Misc Industry's Worst Cue 13 6
Misc Data East Pin 5th Anniversary 13 6
American Technos Technos Wrestlefest Freeze Up 13 7
Atari Tempest Low High Voltage 13 7
Data East Pin Improves 13 7
Midway Gilligan's Island Lock 13 7
Nintendo PP-1200A Supply Cap 13 7
Peter Chow Troubleshooting 13 7
Pioneer CD Juke Hex 13 7
Redemption Make An Old Video Into Redemption 13 7
Rowe AMI CMOS Credit Com 13 7
Sega Time Traveler Bracket 13 7
Sega Time Traveler A Review 13 7
Williams Funhouse Bracket 13 7
Williams Funhouse Trap Door 13 7
Williams Funhouse Door Hinge 13 7
Williams Lost Memory 13 7
Williams System II Response 13 7
Williams Slugfest Card Dispenser 13 7
Misc One Stop Parts House 13 7
Dynamo HS-4 Cabinet 13 8
Gottlieb System 80B Display 13 8

Gottlieb System 80 Power Up 13 8
Konami Teenage Mutant Ninja Turtles Audio 13 8
Matsushita Monitor Brite Raster 13 8
Redemption Ticket Dispenser For Skill-O-Bingo 13 8
Rowe AMI Mech Control 13 8
Sanyo Monitor Problems and Solutions 13 8
Sega Time Traveler Mod 13 8
Wells Gardner K7000 No Raster 13 8
Wells Gardner 19K6101 Low B+ 13 8
Williams Pinbot Relay 13 8
Williams The Machine Matrix 13 8
Williams Terminator 2 Cannon 13 8
Williams Terminator 2 Stock Part 13 8
Williams System II Error Clear 13 8
Misc Tech Supply Review AMOA '91 13 8
Misc AMOA '91 Game Review 13 8
Misc AMOA '91 Awards 13 8
Capcom Street Fighter II Copies 13 9
Data East Simpsons Upkicker 13 9
Data East Pins Outhole Kicker 13 9
Data East Batman Shooter 13 9
Electrohome GO-7 Brightness 13 9
Gottlieb System 80B Piggyback 13 9
Gottlieb System 80B No Displays 13 9
Konami Converting Main Event Harness 13 9
Leland Dragon Lair 2 Correction 13 9
Matsushita Sync Problem 13 9
Midway Super High Impact Te Templtes 13 9
Nintendo Monitor Bad Pix 13 9
Redemption Install A Pinball Ticket Dispenser 13 9
Rowe R-92 Phono Shut Down #39 13 9
Sega Time Traveler Controversy 13 9
Taito Continental Circuit Steer 13 9
Williams Terminator 2 Kickback 13 9
Williams Terminator 2 Stuck Ball 13 9
Williams Early Pins Power-Up 13 9
Williams Terminator 2 Targets 13 9
Williams System 11B Display 13 9
Misc Konami's Chairman Speaks 13 9
Misc New 4-Player Kit Considerations 13 9
Misc Procedures For Repairing PCBs 13 9
Misc How to Test for a Faulty Flyback 13 9
Atari Cyberball No Sound 13 10
Atari Centipede Power Up 13 10
Bally Williams Lamp Solenoids 13 10
Capcom Street Fighter II Freeze 13 10
Data East Wico New Rubber 13 10

Data East Pin Part From Wico 13 10
Dynamo 150W Supply Min Load 13 10
Dynamo HS-13 Cabinet Notes 13 10
Electrohome GO-7 Horiz Width 13 10
ICE Putting Challenge Mod 13 10
Pioneer CJ-V55 Laser Vires 13 10
Redemption Who's Who of Games w/Tickets 13 10
Wells Gardner Vertical Height 13 10
Wells Gardner Vertical Collapse 13 10
Wico/Data East New Rubber 13 10
Williams Super High Impact Wiring 13 10
Williams System II Diagnostics 13 10
Williams Terminator 2 Gun Bind 13 10
Williams Terminator 2 Ball Run 13 10
Williams/Bally Lamp/Solenoids 13 10
Williams Terminator 2 Cannon 13 10
Misc 6800 CPU Free Play Eprom 13 10
Misc New Black Pinball Rubbers 13 10
Misc Moving Out! 13 10
Misc Super Duper Fantastic Cleaner 13 10
Bally Midway Spy Hunter Blues 13 11
Data East Star Trek Program 13 11
Data East Pinball Service 13 11
Data East Ramp Up Mechanism 13 11
Deltronics O Rings & Brakes 13 11
Disco Monitors Failed Caps 13 11
Disco Monitor Capacitor List 13 11
Electrohome GO-7 Poor Filtering & Vertical Collapse 13 11
Hantarex MTC9000 Flyback 13 11
Hantarex MTC9000 Comp Sync 13 11
Hantarex MTC9000 ECG Parts 13 11
Jaleco Cisco Heat Seat Shaft/Bearings 13 11
Konami T'Shooting Double Dragon Enabl 13 11
Midway/Bally Spy Hunter Blues 13 11
Smart Industries Cranes Get Smarter 13 11
Williams Gen Illum Funhouse 13 11
Misc Avoid Blowing Supplies w/Static 13 11
Misc AMOA Approved Standards 13 11
Misc Area Code Decoder 13 11
Atari Steel Talons Steering 13 12
Atari T'shooting Tempest XY Monitor for Missing XY Signal 13 12
Bally Midway T'hoooting Spy Hunter For Speaker Hum 13 12
Bally Williams Bad Links 13 12
Gottlieb System 80 Driver Gnd 13 12
ICE Putting Challenge Ball Opto 13 12
Kristel Monitor No High Voltage 13 12
Kristel Monitor Raster Loss 13 12

Midway/Bally T'shooting Spy Hunter For Speaker Hum 13 12
Namco Starblade Warning 13 12
Rowe BC-35 Fork Guard 13 12
Stern Missing Speech On Stern Pins 13 12
Williams Slugfest Card Mechs 13 12
Williams/Bally Bad Links 13 12
Williams Terminator 2 Ball Shooter Bracket:Tighten for Income 13 12
Yamate W4 8-Line Broken Video 13 12
Misc Konami President Sizes Industry 13 12
Misc Proper Care & Feeding of Pinball Flippers & Components 13 12
Misc AMOA Approves Additional Game Mfg Standards 13 12
Arachnid 6000 Monitor Missing Hi Volts 14 1
Bally Addams Family Thing Takes a Shot 14 1
Bally Midway Spy Hunter Programs 14 1
Bally Williams Party Zone Access Problem 14 1
Betson Mad Dog McCree Heat & Grnds 14 1
Hantarex MTC9000 Squeal Off 14 1
Merit Pub Time Darts Vertical Height & Linearity Problems 14 1
Midway Bally Spy Hunter Problems 14 1
Rowe Precaution: Is Your Bill Changer Taking Bogus Bills? 14 1
Smart 4-Player Jackpot Update 14 1
SNK Taito Op Wolf & SNK Mech Attack Optos 14 1
Taito Op Wolf & SNK Mech Attack Optos 14 1
Wells Gardner K7000 Hi Volts Shutdown 14 1
Wells Gardner K7000 Blown Safety Caps 14 1
Wells Gardner 79XX No Shadows No Pix Blown Fuse 14 1
Wells Gardner 79XX No Reg No Horiz Sync 14 1
Williams Bally Party Zone Access Prob 14 1
Williams Pinball Display Flashing 14 1
ACME Expo How to Use ACME '92 to Your Benefit 14 1
Misc Control Panel Flexi Wire Source 14 1
Misc Drop That Battery off the Board 14 1
Atari Race Drivin' Repair Notes 14 2
Bally Williams General Illum Mod 14 2
Bally Williams Low Solenoid Voltage 14 2
Gottlieb System 80 Driver Board Mod 14 2
Gottlieb Premier Catastrophic Failures 14 2
Hantarex MTC9000 Excessive Width 14 2
Hantarex MTC9000 Synch Compat 14 2
Namco America Starblade Warning 14 2
Premier Gottlieb Catastrophic Failures 14 2
Rowe OBA II Control Unit Repairs:Breaker Trips 14 2
Rowe OBA II Control Unit Repairs:Wrong Number Credits 14 2
Rowe OBA II Control Unit Repairs:Motor Will Not Reverse 14 2
Rowe OBA II Control Unit Repairs:Bill Transport Starts and Stops 14 2
Rowe OBA II Control Unit Repairs:Transport Rejects Bills 14 2
SNK Neo Geo Intermittent Graphics 14 2

Wells Gardner K4914 Horizontal Tear 14 2
Williams Plastic Ramp Side Protectors 14 2
Williams New Flipper and Gold EOS 14 2
Williams Electronic Flipper Notes 14 2
Williams Bally Low Solenoid Voltage 14 2
Williams Bally General Illum Mod 14 2
Zenith 9-277-01 Vertical Foldover 14 2
ACME Expo '92 What's New Review 14 2
Misc Tips for Removing Glue Residue 14 2
Misc Cross Reference Utility on Floppy 14 2
Misc S*TJ's Article Index Data Disk Ready 14 2
Misc Adding A Mechanical Coin Meter Pins 14 2
Misc S*TJ's BBS Takes a Tech Breather 14 2
Capcom Buster Bros Security Scheme 14 3
Capcom CPS Board Heartaches 14 3
Data East Wacky Gator Sensor Board 14 3
Electrohome Temporary Capacitor Fix 14 3
Electroport Poker II Self Credit Fix 14 3
Gottlieb System 80 Grounding Cure 14 3
Matsushita Monitors Dim Screen 14 3
NSM ESIV-CD Remote Control 14 3
Seeburg CD Mistracking Cure 14 3
Sharp XM-2001M Horizontal Problems 14 3
Wells Gardner 13K7842 Vert Collapse 14 3
Wells Gardner 4600 Vertical Centering 14 3
Williams Cyclone General Illumination 14 3
Williams Comet Speech Adjustment 14 3
Williams Quick Fix Video Power Supplies 14 3
ACME Expo '92 Highlights & Observations 14 3
ACME Expo '93 Moves Dates to Weekend 14 3
Misc 4 Play Modification Eliminates Button 14 3
Misc Matching Cabinet Paint Tips 14 3
Misc How to Attend a Game Auction 14 3
Misc Factoring the Variables of Pricing 14 3
Misc Wells Gardner New Phone System 14 3
Betson Proper Care & Feeding of Big Choice Crane 14 4
Coin Controls Ticket Dispenser CTD10 Operation 14 4
Electroport Gaming Video No Credits 14 4
Gottlieb Solenoid Blown Fuse Mod 14 4
Konami X-Man Power Up Problem 14 4
Mars New Software For Mars Bill Acceptors 14 4
Rowe Adding Helpers to Jukebox Lid Support Struts 14 4
Taito D3BOS Leasing For Events 14 4
Williams Diamond Plate Playfield Cleaner 14 4
Video Card Games GTI Video White-Out Condition 14 4
AMOA Expo '92 Exhibit Sold Out 14 4
Misc T'shooting Monitors with an Audio Generator (Part I) 14 4

Misc Alternative Coin Door Lamp Power 14 4
Misc About Video Lottery Terminals 14 4
Atari Relief Pitcher Software Updates 14 5
Data East Wacky Gator Sensor PC Board Modification 14 5
Hantarex MTC9110 Intermittent Video 14 5
Konami X-Men Power Up Problem 14 5
Midway Addams Family F112 Fuse 14 5
Midway Addams Family Blown Fuses 14 5
NSM ESIV-CD Title Holder Stack Notes 14 5
Rowe CD100 Noise Pickup 14 5
Sega Time Traveler Video Problems Caused by Rejected Videodiscs 14 5
Williams Pennant Fever Throws A Curve 14 5
Williams Flipper Control Board 14 5
Williams New Pivoting Playfield Design 14 5
Misc T'shooting Monitors with an Audio Generator (Part II) 14 5
Misc Repairing Scratched and Damaged CDs 14 5
Arachnid Galaxy Dart Software Update 14 6
Coin Controls Enhanced Metal Kit Parts Add Versatility 14 6
Data East Pinball: No Display 14 6
Dynamo Cabinets Power Supply Switch 14 6
Gottlieb Weak Drop Targets 14 6
ICE Putting Challenge Player Advance 14 6
Wells Gardner Black Monitor Plague 14 6
Williams Getaway Up/Down Ramp 14 6
Misc FCC Video Game Labels 14 6
M +5 Volt Adjustment Modification for Computer type Supplies 14 6
Misc New Dollar Coin: Pros and Cons 14 6
Misc Repairing Audio Amplifiers (Part 1) 14 6
Misc Checking/Changing Switching Supplies 14 6
Capcom Street Fighter II Lockup 14 7
Catalina Games Cool Pool Top Problem 14 7
Data East Phantom Speech Low Music 14 7
Data East Playfield Coating Maint 14 7
Data East Pin Hook Erratic Play 14 7
Data East Lethal Weapon 3 Weak Flippers Alignment 14 7
Jaleco Big Run/Cisco Heat Horn Button 14 7
Merit Pub Time Scorpion Dart Matrix Scoring Modification 14 7
Williams Getaway Opto Assembly 14 7
Williams Early Shuffle Alley Survival Kit 14 7
Misc S*TJ BBS Takes a Hit 14 7
Misc Infrared Detector Probe for T'shooting 14 7
Misc Repairing Audio Amplifiers (Part II) 14 7
Misc Capacitor Data Sheet for Monitors 14 7
Data East Lethal Weapon 3 Schematic 14 8
Data East Wacky Gator Frame Mod 14 8
Data East Lethal Weapon 3 Lane Sw 14 8
Hantarex New Polo Monitors High Speed Diodes 14 8

Lock America High Security Locks 14 8
Midway Williams Mortal Combat Dipswitch Coinage 14 8
Rowe CD100 Fuzzy Distortion Fix 14 8
Wells Gardner 79XX Cap Upgrade 14 8
Williams Early Shuffle Alley (Part II) 14 8
Williams Midway Mortal Combat Dipswitch Coinage 14 8
Video Card Games Drew Kramer or SMS Pokers White Screen Condition 14 8
Misc Retractor Reduces Line Cord Damage 14 8
Misc New Software Installed S*TJ BBS 14 8
Misc Service Procedures and Approaches (Part I) 14 8
Bally Williams Pins Cutting Out 14 9
Dynamo Cabinet Harness Colors 14 9
Leland Super Off Road Eprom ID 14 9
Rockola Jukebox Background Hum 14 9
Wells Gardner 25 Monitor Dim Display 14 9
Wells Gardner #7131 Out of Focus 14 9
Williams Bally Pins Cutting Out 14 9
Video Card Games Cherry Bonus Video Trash In Double Up 14 9
AMOA Expo '92 14 9
AMOA Expo Award Winners 14 9
AMOA Expo What's New '92 14 9
Misc S*TJ BBS Logon Tips & Hints 14 9
Misc Operator Friendly: Another Feature for Standardization 14 9
Misc Video News: Sega-Sony-Nintendo 14 9
Misc Video News: Fiber Optics-Cable & The \$\$ Coin 14 9
Misc Return to Factory PCB Procedure 14 9
Misc Service Procedures/Approaches (Part II) 14 9
Misc Properly Powering Your Equipment 14 9
Misc AP 110 Series Vendors Low Power 14 9
Arachnid English Mark Monitor Cap 14 10
Data East Wacky Gator Play Option 14 10
Data East Batman Stuck Ball Tip 14 10
Data East Lethal Enforcer Fuzzy Video 14 10
Dynamo Air Hockey Stuck Puck Cure 14 10
Fabtek Heated Barrel Free Credits 14 10
Merit CRT-200 Coinage Problems 14 10
Williams Power Board Fuses 14 10
Williams Addams Family Volt Sensitive 14 10
Williams Addams Family Hand Bracket 14 10
Williams System II Coil Plunger Problems 14 10
Video Card Games Cherry Bonus Top Third of Video White Out 14 10
AMOA Expo More '92 Show Hits 14 10
Misc Novus Polish Follow Up 14 10
Misc National Semiconductor Data Books 14 10
Misc Modifying Medium to Standard Res 14 10
Misc Pinball Precautions & Maintenance 14 10
Atari Space Lords Joystick Problem 14 11

<http://www.startechjournal.com>

Data East Star Wars Pinball 14 11
Hantarex MTC9000 Raster Lines 14 11
Hantarex MT 3000 Common Failures 14 11
Hollywood Crane Source for Motors 14 11
Merit Premier Darts Monitor Problems 14 11
Merit Dart Head Score Problems 14 11
Sharp Image 27 Monitor Purity Problem 14 11
Smart Jackpot Pendulum Tilt 14 11
Williams Coin Door Credits Smart Tilt 14 11
Video Card Games Cherry Bonus Middle Third White Out 14 11
Misc Eagle Lift E-Clips & Cable Inspection 14 11
Misc Cashbox Redesign? Mfg Suggestion 14 11
Misc Data East Vs Williams 14 11
Misc Electronic Flipper Button Replace 14 11
Misc Dollar Coin Forecast 14 11
Misc What's New for 1993 14 11
Misc New 1993 Parts & Controls Catalog 14 11
Misc Operating Diesel Trucks Cold Weather 14 11
Atari Atari Hard Drivin' Steering Pot 14 12
Bally Dr. Who Indefinite Play Mode 14 12
Data East Lethal Weapon 3 Multi-Ball 14 12
Hantarex Polo Horiz Out Failure 14 12
Konami Lethal Enforcer Eprom 14 12
Matsushita Vertical Hold Capacitor 14 12
Rowe Jukebox CD Packaging Tip 14 12
Strata Time Killers Stereo/Mono 14 12
Wells Gardner Part # Upgraded Cap 14 12
Williams Hot Shot Ball Agitator Adjust 14 12
Williams Getaway Ball Hangup Bracket 14 12
Williams Addams Family Flipper Retro Fit 14 12
Williams Addams Family Longevity Suggestions 14 12
Video Card Games Cherry Bonus Bottom Third White Out 14 12
Misc More Dollar Coin News 14 12
Misc Game Security Tips: Padlocks-Keys-Dos & Don'ts 14 12
Misc Printed Circuit Board Repair: In Shop? 14 12
Misc Video Game Power Supply Substitutes 14 12
Arachnid Dealing With Dart Head Debris 15 1
Bob's Space Racers Deluxe Bowler-Roller LEDs 15 1
Data East Hop-A-Tic-Tac-Toe Switch 15 1
ICE Meltdown Cable 15 1
Kristel Monitor Wavy Video 15 1
Kristel Dart Monitor: No Video 15 1
Leland Indy Heat Service Tips 15 1
Lock America Security late 15 1
Video Card Games Cherry Bonus Video Scramble 15 1
Misc Pinball Flipper Kit 15 1
Misc Technicians in US Work 15 1

Misc World Game Pricing 15 1
Misc Choosing the Right Eprom Programmer 15 1
Misc Volume 14 Index 15 1
Misc Problems with Flippers 15 1
Arachnid Darts Unstable Monitor 15 2
Arachnid Omni Vision Reduced Video 15 2
Atari Tetris No Pix-Test OK 15 2
Atari Tetris No Pix-Test Ok 15 2
Atari Hard Drivin' Steering Pot Source 15 2
Bay Tek Roll Down No Attract Mod 15 2
Data East Time Machine No Display 15 2
Mighty Power MP-3089C Failure 15 2
Rowe Acceptors:Fast Fixes for the Field 15 2
Video Card Games Cherry Bonus Video Screen O's 15 2
Williams Whitewater Ball Popper 15 2
Williams Whitewater Mini Ramp 15 2
Williams Flipper Link Update 15 2
Misc Securing Your Games (Part 2) 15 2
Misc Joystick Maintenance 15 2
Misc ACME '93 Trade Show 15 2
Misc Audio Innovations CD Repair Kit 15 2
Ardac Fast Fix: MBA Bill Units 15 3
Atari Pole Position Fuse Meltdown 15 3
Bromley Wheel'M In Adjustments 15 3
Coin Controls CTD Ticket Dispenser 15 3
Data East Star Wars Adjustments 15 3
Data East Lethal Weapon 3 Coil Sub 15 3
Dynamo New Cue Ball Separator 15 3
Dynamo Installing Kits into Cabinets 15 3
Hantarex P919 Monitor Test Pattern 15 3
Sharp XM1801N Monitor Double Image 15 3
Strata Time Killers Reset Problem 15 3
Tekbilt Power Supply Noise 15 3
Video Card Games Cherry Bonus Dip Switches 15 3
Williams NBA Jam Software Glitch 15 3
Misc New Improved BAMScan for BBS 15 3
Misc New Features for Index Database 15 3
Misc Testing Coin Door Switches 15 3
Misc ACME '94 Dates Set 15 3
Misc Diamond Liqui-Tool Cleaning lube 15 3
Atari Pole Position Fuse Holder Mod 15 4
Bromley Wheel'M In Ticket Jam 15 4
Eagle Lift Activation Lever Problem 15 4
Konami Martial Champion Glitch 15 4
Merit Scorpion Darts Auto Player 15 4
Merit Pub Time Darts Software Rev 15 4
Mighty Power Power Supply Mfg Responds to Article 15 4

NSM CD Jukebox:Symptoms/Solutions 15 4
PEE Flip N Win Inaccurate Meter 15 4
Perfect 360 Controls Joystick Review 15 4
Rowe CBA2 Bill Unit Fast Fixes 15 4
Unisys Unveils Cutting-Edge System 15 4
Video Card Games Cherry Master Random Credits 15 4
Williams NBA Jam Hidden Players 15 4
Misc Testing Microswitches w/o a Meter 15 4
Misc Sharper Video Screens Breadthrough 15 4
Misc Flipper Links Statistics 15 4
Misc Downloading CDs 15 4
Misc More about Flippers 15 4
Atari Stun Runner Steering Problem 15 5
Data East Jurassic Park T-REX Inop 15 5
Lazer-Tron Spin to Win Wheel 15 5
Mighty Power Supply Feedback 15 5
Rowe Juke Amps Repeat Failures 15 5
Rowe OBA2 Credit Problem 15 5
Sega Title Fight Handle Grip Mid 15 5
Sega Virtua Racing Steering Failure 15 5
Video Card Games Cherry Master Input/Output 15 5
Williams Hot Shot Carrier Jam 15 5
Misc Poor Quality Coin Switches 15 5
Misc The Game Operator vs The Cable 15 5
Capcom Super Bank It Free Tickets 15 6
Data East Jurassic Park Non Credit 15 6
Data East Jurassic Park Dino Kit 15 6
Lazer-Tron Spin to Win Resetting 15 6
Rowe Amplifier Overload Check 15 6
Video Card Games W-8 8-Line Video Garbage 15 6
Video Card Games Eldorado Input/Output Pinouts 15 6
Williams B.5 Histogram 15 6
Misc Gold vs Silver Coin Switches 15 6
Misc Super Cleaner Try It! 15 6
Misc Advancing Game Costs for the Op 15 6
Misc Flipper Link Failure Solution 15 6
Misc Standards Needed for Cabinets 15 6
Atari World Rally w/25 Monitor 15 7
Data East Jurassic Park Pinched Wires 15 7
Midway NBA Jam Special Payers 15 7
Midway NBA Jam Battle ZoneMode 15 7
Midway NBA Jam Secret Power-Up 15 7
Mighty Power Revisited 15 7
Namco Nightmare on Namco Street 15 7
Video Card Games W4 Small BD Switches Lamps & Triacs 15 7
Wells Gardner K7000 Washed Out 15 7
Williams Dracula Ball Ejuct 15 7

Misc Flipper Preventive Maintenance 15 7
Misc 1993 AMOA Game Award Nominees 15 7
Misc Gray Area to Redemption 15 7
Gottlieb SFII Replay Percentage 15 8
Konami Lethal Enforcers Pitiful Design 15 8
Merit Pub Time Darts Sound Volume Mod 15 8
Midway NBA Jam Players Guide 15 8
Motorola New Motorola Cross Reference 15 8
Rowe Bill Acceptance Problem 15 8
SNK Neo Geo Mixed Languages 15 8
Video Card Games Cherry Master Board: Remove Girl 15 8
Wells Gardner K7000 No Hi Volts 15 8
Wells Gardner 4900 Vert Foldover 15 8
Williams Addams Family Volume 15 8
Williams Board Security Suggestions 15 8
Misc Pinball Designs too Complex? 15 8
Capcom Bowlind Anti Lock-Up Mod 15 9
Konami Lethal Enforcer Discrepancy 15 9
McO'River Aero Fighters Intermittent 15 9
Namco Suzuka 8-Hours Preventative Maint Modifications 15 9
Rowe CD 100 Background Music Mod 15 9
Video Card Games Cherry Master No Sound 15 9
Misc S*TJ BBS Installs Hi-Speed Modem 15 9
Misc New AMOA/AAMA Standards 15 9
Misc New Electronics Catalog Free! 15 9
Misc AMOA 1993 The Best & Worst 15 9
Misc AMOA '93 The Good Bad & Not So 15 9
Misc Manufacturers' Numbers 15 9
Data East To Pay Williams Royalties 15 10
Data East Jurassic Park Dino Fails 15 10
Deltronics Bench Testing DL-1275 15 10
Hantarex MTC 9000 Shut Down Test 15 10
ICE Full Court Frenzy Moving Basket 15 10
Merit Scorpion/Stinger Darts Power Failure 15 10
Namco Cracky Crab Ticket Drive 15 10
Taito Secret Bubble Bobble Tricks 15 10
Video Card Games Cherry Bonus III No Sound Adjust 15 10
Williams Data East to Pay Royalties 15 10
Williams Reducing Pin Service Calls 15 10
Williams Operation Manual Review 15 10
Misc Global Catalog Intern'l Numbers 15 10
Misc AMOA Game Winners at Expo'93 15 10
Misc Video Game Messages 15 10
Misc New Computer Chip Power PC 15 10
Misc Anaheim's AMOA Expo '93 15 10
Atari World Rally Into Pole Position 15 11
Data East Jurassic Park Control Room 15 11

<http://www.startechjournal.com>

Data East Bill Launch Problems 15 11
Deltronics Bench Testing Controls 15 11
Dynamo UL Cert Cabinet Security & RGB Convert 15 11
Dynamo RGB Conversion TV 15 11
Konami Lethal Enforcer Gun Response 15 11
Midway Mortal Kombat II Secret Codes 15 11
Video Card Games Cherry Master Scrambled Bonus Video 15 11
Williams Indiana Jones Target Error 15 11
Misc Video Game Violence Concerns 15 11
Misc ASC Intros RGB to NTSC Converter 15 11
Misc 1993 Review 15 11
Misc Violence in Video Games 15 11
Misc Game Truck: Cargo Tie-Downs 15 11
Arachnid Dartman II DOS 6 Backup 15 12
Data East Jurassic Park Matrix Prob 15 12
Data East East Pinball Progress 15 12
Midway Mortal Kombat II Software Revision 15 12
Midway Mortal Kombat V2.1 Secrets 15 12
Seeburg Blast Lands a Convert 15 12
Video Card Games Cherry Master Random Video Fix 15 12
Wells Gardner 25 Color T'shooting 15 12
Williams Flipper Link Adjustment 15 12
Williams Dip Switch Vs CMOS Coinage 15 12
Williams Star Trek:TNG Weak Flipper 15 12
Misc Coin-Op News 15 12
Misc Winter Game Moving Precaution 15 12
Misc PCB Ripoff Alert 15 12
Misc Violence in Video Games 15 12
Misc Movie Theme Pinball Games 15 12
Misc Telephone Call Restrictors 15 12
Bally Twilight Zone Harness Problem 16 1
Bally Twilight Zone Proximity Sw Adj 16 1
Cherry Master Scrambled Video 16 1
Data East Jurassic Park Problems 16 1
Data East Jurassic Park Lockup 16 1
Midway Mortal Kombat II Rev 3.1 16 1
Monitors Building an Observation Monitor 16 1
Monitors New RGB-NTSC Converter Board 16 1
Redemption Game Meter Add-On 16 1
Rowe Ultimate BC-25 Rejection Fix 16 1
William Weak Flipper Solution 16 1
Misc Intel Unveils Faster Chip 16 1
Misc \$25000 Pinball Championships 16 1
Bally Wins Injunction 16 2
Cherry Master Clearing the RAM 16 2
Midway Mortal Kombat II Moves 16 2
Midway NBA Jam II Players 16 2

Monitors High Definition TV 16 2
Monitors Repair WG7000 16 2
National Sports Games NSG Service Takes a Back Seat 16 2
Redemption Adding a Meter to Ticket Dispenser 16 2
Sega Sega on-Namco off 16 2
Wico Floating Actuator 16 2
William Star Trek:TNG Lug Note 16 2
William Star Trek:TNG Optics 16 2
Misc Kansas Site for ETA Seminar 16 2
American Laser Amiga Board 16 3
Cherry Master Setting Credit/Coin 16 3
Hantarex MTC 9000 Clicking 16 3
Hantarex MTC 9000 Shut Down 16 3
Midway NBA Jam II Tip Sheet 16 3
National Sports Games Responds NSG Responds 16 3
Nintendo Announces 64-bit System 16 3
William Twilight Zone Clock 16 3
William Star Trek: TNG 16 3
William Demolition Man Triggers 16 3
Misc New 1994 Happ Controls Catalog 16 3
Misc ACME '94 Trade Show 16 3
Misc Mfg Customer Svc Phone & Fax Numbers 16 3
Bally MPU Erratic Symptoms 16 4
Big Electronics New Game Cabinet 16 4
Capcom Qsound Stereo Q & A 16 4
Cherry Master Bonus III Picture Flip 16 4
Data East Wacky Gator Opto Wires 16 4
Dynamo Solitaire Challenge Missing Credits 16 4
Electrohome GO7 Full Beam 16 4
Electroport Poker Blue Lines 16 4
Hantarex MTC 9000 Shut Down 16 4
Konami Use of Sony technology 16 4
Midway Twilight Zone Blown Fuse 16 4
National Sports Games NSG Comes Through 16 4
Taito Two Minute Drill Service 16 4
Misc ETA Convention & Seminar 16 4
Misc AMOA Interactive Arcade Project 16 4
Misc S*TJ's Index Database Upgrade 16 4
Division LTD Releases Virtual Reality System 16 5
Dixie Narco Validator Latch in NSM Jukes 16 5
Dynamo Solitaire Challenge Credit Problem 16 5
Electroport Poker Video Lines 16 5
Holden The Wizard Tells All Prints 16 5
Irem Hill Climber Clutch Installation 16 5
Merit Stinger Darts Cable Routing 16 5
Merit Super Touch 30 Calibration 16 5
Namco Merge with US Arcades 16 5

Nintendo & Williams Get Together 16 5
William Opto Test 16 5
Misc Volume 15 Index (Mar93-Feb94) 16 5
Advance Games Snack Attack Claw 16 6
Atari Merge with Time Warner 16 6
Bally World Cup Ball Lock Magnet 16 6
Bally World Cup Right Ramp Exit 16 6
Bally World Cup Upper Eject Hole 16 6
Data East Wacky Gator Option 16 6
Data East Wacky Gator Update 16 6
Electroport Poker No Functions 16 6
Konami Lethal Enforcer Delicate 16 6
William Weak Flipper Opto Test 16 6
Misc Most Popular Leisure Activities 16 6
Misc 1994 Game Awards Nominees 16 6
Misc Standard JAMMA for Conversions 16 6
Misc Burning TI27C040 Eproms 16 6
Data East Flipper Coil Specs 16 7
Dynamo Solitaire Challenge Lockup 16 7
Electroport Poker Ram Clear 16 7
Hantarex Polo Monitor Capacitor Change 16 7
Konami Lethal Enforcer Accuracy 16 7
Mars VFM-4 Bill Acceptor Workhorse Rehab 16 7
Nintendo Infringement Lost 16 7
Redemption Reducing Ticket Jams 16 7
Rowe Jukebox Decoder Prints 16 7
Rowe Link on CBA-2 Bill Acceptors 16 7
Sega Sega & MGM Get Together 16 7
William Popeye Upgrades 16 7
William Mega Links 16 7
William Testing Optical Switches 16 7
Generic Maintenance Gun Game Failures: A Suggestion 16 7
Generic Maintenance Weak Flipper Solution 16 7
Misc Fast Fax Mini Survey 16 7
Misc New Industry Standard 16 7
Misc Electronic Technician of the Year 16 7
Misc Fast Fax Mini Survey 16 7
Atari Final Lap Upgrade 16 8
Catapult Game Modem Network 16 8
ICE Putting Challenge Field Reports 16 8
Kortek Monitor Parts Source 16 8
Rowe CD Phono Amplifier Test 16 8
Rowe Bill Changer Reject Codes 16 8
William Star Trek:TNG Proximity 16 8
William Optical Switch Reliability 16 8
Generic Maintenance Opto Testing Precautions 16 8
Generic Maintenance Bill Transports 16 8

Misc Bring Back Ms Pac? 16 8
Misc Videogame Security Standards 16 8
Misc Pinball Expo/Flip-Out Tourney 16 8
Misc AMOA Expo '94 Report (Part 1) 16 8
Misc Videogame Security Standards 16 8
Misc Pinball Expo/Flip-Out 16 8
Atari Road Riot Credit Problem 16 9
Data East Pinball SCR Subs 16 9
Fabtek Raiden DX Upgrade 16 9
Rowe Link CBA-2 Bill Acceptor 16 9
Rowe MBA Transport Maintenance 16 9
Wells Gardner Horizontal Cap 16 9
Generic Maintenance Switch Matrix Opto Switch 16 9
Generic Maintenance Videogames: Get 'em Ready 16 9
Misc New BBS Movin' On Up 16 9
Misc AMOA Expo '94 Game Review 16 9
Misc Electronic Technicians Assoc '95 Site 16 9
Misc AMOA Expo '94 Game Review 16 9
Atari Primal Rage Moves 16 10
Data East Regroups 16 10
Meltec Big Mouth Air Ball Notes 16 10
Nintendo Bose Develop Audio 16 10
Pentranic Monitor Blooming 16 10
Sega Virtual Racer Shifter Problems 16 10
Sega Pinball Gun's 'N Roses Shooter Lane Ramp 16 10
Sega Pinball Maverick Display Dot Matrix Intro 16 10
SNK Neo Geo Samurai Showdown II 16 10
Taito New F3 Package System Hardware 16 10
Misc S*TJ Bulletin Board Adds Off-Line Reader 16 10
Misc Committee Sites New Standards 16 10
Misc New Happ Controls Catalog 16 10
Misc Yogi Ticket Dispenser Driver 16 10
Atari Primal Rage Version 2 16 11
Data East Guns 'N Roses Poor Ball Launch 16 11
Merit Scorpion & Stinger Darts Interference 16 11
Midway The Shadow Playfield 16 11
Midway Resuscitating Ms Pac 16 11
Planet Earth Dinoscree Ticket Dispenser Fix 16 11
Rowe BC-1200/BC-1400 Updates 16 11
Sega Pinball Service Numbers 16 11
Sega Daytona Replacement Shifter 16 11
Sega Virtual Cop Pricing 16 11
Sega Daytona USA Secret Tricks 16 11
Wells Gardner Horizontal Out Mod 16 11
Wells Gardner FET Failures 16 11
William Nintendo Connection 16 11
Misc Index V2.0 and V3.0 Owners 16 11

<http://www.startechjournal.com>

Misc Flawed Pentium Chip 16 11
Misc Sega & Atari Settle 16 11
Baytek Clown Rolldown Ticket Jackpotting 16 12
Konami Lethal Weapon Gun Replacement Update 16 12
Lazer-Tron Pogger Upgrade Kit 16 12
Lazer-Tron Updates Cure Problems 16 12
Lazer-Tron Pirate's Gold Update Kit 16 12
Nintendo Ultra 64 is Coming 16 12
Nintendo Ultra 64 Dream Team Profiles 16 12
Planet Earth Dinoscore Tix Dispenser Addendum 16 12
Sega Technical View of Pinball Maverick Opto's 16 12
Sega Pinball Short-Hop Opto GaAIAs Theory 16 12
William Price Block on Pinball 16 12
Misc Consumer Electronic Show Scares Nevada Vendor 16 12
Misc Coin Slots Upgraded to Revision 1.1 16 12
Misc Honk Kong Circulates New Coin 16 12
Misc Asian Amusement Expo Set 16 12
Atari Road Riot Giving Free Credits & No Settings 17 1
Atari Primal Rage Latest Software 17 1
Atari Primal Rage Color Impedance 17 1
Atari T-Mek New Version Software 17 1
ICE Flintstones Pinball Flipper Fuse Underrated 17 1
Sega Pinball Frankenstein Creature Tech Overview 17 1
Sega Pinball Maverick Ball Trap Adjustment 17 1
MarketPlace Classified Buy and Sell Ads 17 1
Miscellaneous No Retrofit For Older Williams Pinball Optos 17 1
Miscellaneous Version 2.3 Installed on STJ Bbs New Features 17 1
Miscellaneous Skee-Ball Intro Two New Retrofit Kits 17 1
Miscellaneous Adding An Auxiliary Monitor To Your Videogame 17 1
Miscellaneous Volume 16 Index of Articles March '94 - Feb '95 17 1
Miscellaneous The Future of Videogames Stacking Up Home Mkt 17 1
Miscellaneous New Version 1.1 For Coin Slots Index Database 17 1
Miscellaneous Happ Announces Con-Op Driving Cabinet 17 1
Atari Race/Hard Drivin' Calibration Symptom 17 2
Bromley Rock & Bowl Locked-Up Game 17 2
Dynamo 50 TV Monitors Auto Power Up Program 17 2
Rock-Ola Phono Audio Distortion Mod 17 2
Rock-Ola 6000 Legend Coin Deflector Bracket 17 2
Sega Daytona USA Loose Steering Wheel 17 2
Sega Pinball Gas Plasma Displays T of O 17 2
Taito Super Sonic Blastman Safety Recall 17 2
Williams Black Knight 2000 Playfield Tilt Troubles 17 2
Williams Indiana Jones Drop Target Manual Error 17 2
Wurlitzer Joins USPS for Stamp and Licensing 17 2
MarketPlace Classified Buy and Sell Ads 17 2
Miscellaneous STAR*TECH Journal' Bbs Adds Buy/Sell Board 17 2
Miscellaneous And Then There Were Three Mortal Kombat 111 17 2

Miscellaneous Rash of Pinball Cracked Displays Not! 17 2
Miscellaneous SMS/Coastal Amusement Pop A Ball No Coin Up 17 2
Miscellaneous Reader Disputes Munday's Future of Videogames 17 2
Miscellaneous AMOA Expo '95 in New Orleans this September 17 2
Dixie-Narco Fixes Bill Acceptor Problems 17 3
Imonex Coin Acceptors Point/Counterpoint 17 3
Konami Locked N' Loaded With Happ Gun 17 3
Lazer-Tron Customer Service Policy 17 3
Midway Adv Campaign For Mortal Kombat 111 17 3
Nintendo & GTE To Create Game Network 17 3
Rock-Ola Legend Phono Poor Bill Acceptance 17 3
Rock-Ola CD Phonos Early Cancel Symptom 17 3
Sega Pinball's New Portal's Service Menu 17 3
Sega Nintendo Hit With Monopoly Investigation 17 3
Two-Bit Score Intros Change Machine Kit 17 3
Williams/Bally Lockdown Bar Breakdown 17 3
Williams New Upgraded Flipper Coils 17 3
Miscellaneous ACME's Tech Fest Gets Mixed Reviews 17 3
Miscellaneous Dollar Coin Runs Into Opposition 17 3
Miscellaneous Program Description STJ on CD-ROM 17 3
Miscellaneous Build A Williams Intermittent Opto Test Jig 17 3
Miscellaneous ACME '95 Observations - Increase Video Gross 17 3
Gottlieb Cue Ball Wizard 17 4
ICE Full Court Frenzy 11 Eratic Scoring 17 4
Jamma Standard Video Game Pinouts 17 4
NTE Quick Cross Database V3.1 Order Form 17 4
RGB Video Inverter Circuit Schematic 17 4
Rock-Ola 6000 Legend Keyboard Mounting Brkt 17 4
Sega Quick Tip-Testing Dot Matrix Display Glass 17 4
SNK Bust-A-Move Mother Board Confusion 17 4
Two Bit Score New Credit Accumulator Kit 17 4
Wells-Gardner Vertical Output Device U5000 17 4
Williams Twilight Zone Troubleshooting The Clock 17 4
MarketPlace Coin-Op Products & Services 17 4
Miscellaneous Family Entertainment Center Industry Survey 17 4
Miscellaneous World News - Intergrated Circuit Pkg Mfg Ups Price 17 4
Miscellaneous STAR*TECH Journal Intros Internet Web Site 17 4
Miscellaneous How Much Are Coin Jams Costing You? 17 4
Miscellaneous 16 Years of S*TJ Available on CD-ROM 17 4
Miscellaneous Flipper Coils Used in Williams & Bally Pins 17 4
Data East Solid State Flippers Clamping Diode 17 5
Gottlieb Cue Ball Wizard Lock-Up Update 17 5
Hantarex MTC-9000 Pulsing Hi-Frequency Sound 17 5
ICE Flinstones Pinball Flipper T'Shooting Update 17 5
Lazer-Tron Ring Toss Update Kits Available 17 5
Midway Help!My car is missing 17 5
Rock-Ola 5500 Rocket Replacement Keyboard 17 5

Sega Daytona USA Floor Cracks Update 17 5
Sega Virtua Racer Twin WG Monitor Failures 17 5
Sega Pinball CPU Blanking Ckt Theory of Operation 17 5
Sega Pinball CPU Power-Up Self Tests Explained 17 5
Miscellaneous Electronic Technicians STJ & The Games Biz 17 5
Miscellaneous Pinball Games Supplied With Soft Balls? 17 5
Miscellaneous One Player's Videogame Cheat Methods 17 5
Miscellaneous Pinball Preventive Maintenance Checklist 17 5
Atari Moto Frenzy Deluxe Excessive Wear Mod 17 6
Data East End-of-Stroke Switch Discussion 17 6
Hytron Switching Power Supply T'Shooting Tip 17 6
Merit Video Driver Failure on Touch Screens 17 6
Midway Mortal Kombat 3 V2.0 Changes 17 6
Midway MK3 Eprom Update Versions 1.0 & 2.0/2.1 17 6
NSM Jukebox Opto assembly Check Procedure 17 6
Rock-Ola Phonographs Loss of Audio 17 6
Sega Pinball CPU Power-Up Self Test (Correction) 17 6
Two Bit Score Coin Doubler Design Change 17 6
Williams Indiana Jones Mini Playfield Motors 17 6
Williams Fish Tales button Replacement 17 6
Miscellaneous Falling Prices on CD-ROM Drives 17 6
Miscellaneous 3D TV Monitor For Amusement Games Announced 17 6
Miscellaneous Top 3 Revenue Sources in FECs 17 6
Miscellaneous AMOA 1995 Game Award Nominees 17 6
Miscellaneous Fun Merchants Watch Box and Candyman Cranes 17 6
Miscellaneous Suggestion to Pinball Manufacturers 17 6
Gottlieb/Premier Street Fighter Pinball Coining 17 7
Lazer-Tron Pogger Turntable Burnout 17 7
Lazer-Tron Ring Toss Sticking Rinks-Bottle Replacement 17 7
Midway Killer Instinct Control Lock Up 17 7
Midway Mortal Kombat 3 Version 2.1 Changes 17 7
Midway Mortal Kombat 3 Free Update Kit 17 7
Rock-Ola Servicing 52280A & 54510A Amplifiers 17 7
Sega Pinball Diagnostic Display Messages 17 7
Taito Refocuses Efforts on Coin-Op 17 7
Wells Gardner Series 7000 Half Deflection 17 7
Williams Dracula Ball Loading Problem 17 7
Williams Star Trek TNG Rotating Gun Failure 17 7
Miscellaneous The Dollar Coin Debacle-Still on Quarter Play? 17 7
Miscellaneous President Clinton Opposes Dollar Bill Coin 17 7
Miscellaneous National Sports Games Super Shot Premature Time Out 17 7
Miscellaneous Keeping It Together-Organized Game Servicing 17 7
Miscellaneous Family Entertainment Center Survey:Pricing 17 7
Atari Moto Frenzy Deluxe Part Number Correction 17 8
Data East Lethal Weapon 3 Loud Hum 17 8
Dynamo Air Hockey Sensor Problem 17 8
Merit Scorpion 9000 Update Chip Package 17 8

Merit Touchscreen Drifting Calibration Procedure 17 8
Midway/Wms WWF Software Updates 17 8
Midway/Wms Cruisin' USA Replacement Motor Brush 17 8
Rowe 4900 Communication Error 17 8
Sega Rally Deluxe Missing Control Panel Drawing 17 8
Williams T'Shooting T2 Pinball Switch Matrix via 'Net 17 8
Miscellaneous Schematics:Worth Their Weight in Gold 17 8
Miscellaneous Great Selection and Mixed Bag at AMOA Expo 17 8
Miscellaneous Helpful Service Tips for T'Shooting Videogames 17 8
Miscellaneous To: Star Tech Journal From: Randy Fromm 17 8
Miscellaneous The Return of the NOP (NO-OP) Troubleshooter 17 8
Miscellaneous It's Showtime! Didn't Make AMOA Expo? Visit Distrib 17 8
Dynamo Air Hockey Playfield Costs Up 17 9
Electrohome GO7 Monitor Deflection Problem 17 9
Lazer-Tron Ribbit Racin New Bubbles Material 17 9
Lazer-Tron Spin to Win and Junglerama Payout Option 17 9
Rowe Technical Services: New Numbers 17 9
Sega Batman Forever New Format Service Menu 17 9
Williams Long Term Thinking 17 9
Williams World Cup Pin Display Freeze 17 9
Miscellaneous Coming Soon to an Arcade Near You:3-D Sound 17 9
Miscellaneous You Talkin' to Me? EconoCorp Seeks Advice 17 9
Miscellaneous Running the Shop: Essential Tools-Variac & Iso Xfrmr 17 9
Miscellaneous Test Rigs:Deltronic Ticket Dispenser/Merit Pit Boss 17 9
Miscellaneous A New Angle Intro'd on the Information Highway 17 9
Miscellaneous Winners:1994-1995 AMOA Games Awards 17 9
Miscellaneous Don't Give Your Product Away!!! 17 9
Capcom CPS11 Audio Volume Procedure 17 10
Dynamo Responds to High Cost of Playfields 17 10
Merit Countertop Games Burnt PCB 17 10
Merit Megatouch Blown Monitor Fuse 17 10
Rowe CBA-2 Bill Acceptor Problems 17 10
Sega Batman Forever Pin Premature Ball Drain 17 10
Universal Shuffleboard Scoring Unit Fuse 17 10
Williams Sticky Flippers Modification 17 10
Williams Cruisin' USA Monitor Vertical Output 17 10
Williams Twilight Zone Pin Ultimate Clock Fix 17 10
Miscellaneous ACME '96 What Where & When 17 10
Miscellaneous Pinball Graphics Offends Player 17 10
Miscellaneous Good Idea! Piano Wire From Hobby Shop is Handy 17 10
Miscellaneous The Truth About Locks Locksmiths and Lock Picks 17 10
Miscellaneous Pin Expo '95 New Game Comments 17 10
Miscellaneous Reader Response to Williams' Marketing Strategy 17 10
Bally Theatre of Magic Opto Sensor Adjustments 17 11
Lazer-Tron Ribbit Racin Stuck Switches and Resets 17 11
Rowe BC-100 Changer Erratic Operation 17 11
Rowe Diamante Ill-Fitting Doors 17 11

Sega Pinball Apollo 13 Magnet Interface 17 11
US Games Superduper Countertop Power Supply 17 11
Williams T'Shooting Star Trek TNG Blown Fuse 17 11
Miscellaneous Common Flipper Troubles Symptoms and Solutions 17 11
Miscellaneous Good Idea! T'Shooting with Ckt Breakers 17 11
Miscellaneous Monitor Repair Without Schematics (Part 1) 17 11
Miscellaneous One Price Arcades: A Discussion 17 11
Capcom Marvel Super Heroes Game Difficulty Settings 17 12
Gottlieb Strikes N' Spares Game Prom Update 17 12
Lazer-Tron Pharaoh's Fantasy Coin Jam Causes 17 12
Midway Mortal Kombat 3 Eprom Update 17 12
Rowe Diamante Door Security Reader Notes 17 12
Sega Securing Happ Steering Wheel to Daytona 17 12
Sega Pinball Presents the New White Star Board System 17 12
Sega Pinball Apollo 13 System Circuit Protection Mod 17 12
Miscellaneous S*TJ Offers Index Database Credit 17 12
Miscellaneous Standardization:Coin Mech Improvements 17 12
Miscellaneous Is Pinball Becoming Too Confusing for Players? 17 12
Miscellaneous Monitor Repair Without Schematics (Part 2) 17 12
Miscellaneous Display Similarities Between Simpsons and Rollergames 17 12
Sega Pinball White Star System I/O Power Driver Board 18 1
Williams Dirty Harry Game Slope Adj for Steep Ramp 18 1
Williams Dracula Lightning Flippers: Replace 'Em! 18 1
Williams WPC Power Driver CPU Reset Symptom 18 1
Service Misc The Toolbox (Part 1) Organization and Selection 18 1
Pinball Misc The Liz: Flattening Your Playfield Plastics 18 1
Video Misc Conversion Tips Make the Most of Your Kits 18 1
Miscellaneous AMOA Expo '96 to be Held in Dallas Sept 26 - 28 18 1
Miscellaneous Common Cents Coin Mechs Operators Demand Change 18 1
Miscellaneous Volume 17 Index of Articles March '95 - February '96 18 1
Miscellaneous Cash Flow is King Keep It Positive! 18 1
Bally First Electronic Sound Board Repair Source 18 2
Dynamo Air Hockey Anti-Cheat Retrofit Kit 18 2
Dynamo Solitaire Challenge Tatung Monitor Foldover 18 2
Premier Shaq Attaq LED Display Board 18 2
Sega Pinball White Star System I/O Power Driver (Part 2) 18 2
Williams Jack Bot & Congo Loss of Battery Voltage 18 2
Williams Johnny Mnemonic Blowing Fuses 18 2
Service Misc Unique T'shooting Procedure: Use a VCR! 18 2
Service Misc The Toolbox (Part 2) Organization and Selection 18 2
Miscellaneous STJ Tech Topic Index Online 18 2
Miscellaneous 1996: A Banner Year for the Video Game 18 2
Miscellaneous ACME '96 Expo Notes Reports & Rumors 18 2
Miscellaneous Best Pinball Games of 1995 Internet Poll 18 2
Miscellaneous Too Many Pins? Can Operators Keep Up 18 2
Capcom Making Life Harder by Capcom 18 3
Happ Controls Adds Toll Free Numbers 18 3

IREM Grand Summit Hill Climber Modifications 18 3
Sega Cut The Cheese: How to Adjust Your Ticket Payout 18 3
Sega Apollo 13 MultiBall Freeze Condition 18 3
Sega Pinball White Star System I/O Power Driver (Part 3) 18 3
Wells Gardner 7000 Over-Voltage Protection 18 3
Williams Star Trek: TNG Gun Accuracy 18 3
Williams Johnny Mnemonic Blowing Fuses Intermittently 18 3
Service Misc Component Values: Reading the New Labels 18 3
Service Misc A Short Course in Terminology: Say What You Mean 18 3
Jukebox Misc Good Idea! Fix Up a Nice Older Juke 18 3
Pinball Misc Here's a TIP No I Mean a FET TIP! 18 3
Miscellaneous STJ's Website Expands Article Index 18 3
Miscellaneous Lots of Video Game Opportunities 18 3
Miscellaneous ACME '96 Closes Ten Years as Spring Expo 18 3
Bally/Williams Current Pinball Software Revisions 18 4
Midway Releases Killer Instinct 2 Software Revision 18 4
Premier Freddy Pinball Furnace Door 18 4
Rowe CD Jukes Skipping Disk & Lense Cleaning 18 4
Rowe CDM-12 Skipping Problems Help 18 4
Rowe CD-100F Title Page Assembly Breakage 18 4
Rowe Protective Molding & Door Brace Kit 18 4
Rowe CD Jukes Intermittent Symptom 18 4
Rowe CD-100F Reduction Gear Failure 18 4
Rowe Releases CDM-12 Eprom Revision 18 4
Sega Pinball New Flipper Design No Flipper Board! 18 4
Williams Pinball Playfield Troubleshooting Checklist 18 4
Williams Williams/Bally Current Pinball Software Revisions 18 4
Service Misc Good Idea! Little 35mm Film Canisters 18 4
Service Misc Parts Substitution & Using Standard Parts 18 4
Miscellaneous Do Perfectly Working Pin Games Affect Earnings? 18 4
Rowe CD Juke Animation Assembly Stall 18 5
Sega Pinball White Star System I/O PwrDvr Lamp Matrix 18 5
Standard Change Maker C-500 Conversion to the \$2 Coin 18 5
Williams Official Sticky Flipper Update Kits 18 5
Williams Safe Cracker Intermittent Tokens 18 5
Service Misc Good Idea! Use Saved Magnets for Screw Saver 18 5
Service Misc Repairing Broken PC Boards: Fixing Physical Breaks 18 5
Jukebox Misc CD Jukeboxes: Skipping Disk Problem 18 5
Pinball Misc Replace Broken Flipper Links Without Swearing 18 5
Miscellaneous STJ Releases Newest Monitor Update Tech Report 18 5
Miscellaneous Do We Really Need All These Trade Shows? 18 5
Miscellaneous Standardization Committee Approves New Standard 18 5
Hantarex Parts and Service Available From DK Monicor 18 6
Merit 11-UP Update Kit for all Megatouch III Games 18 6
NSM Shut Down US Assembly Facility 18 6
Premier Shaq ATTQ and Stargate Reset on CPU 18 6
Rowe CDM-12 Player Failure and Exchange Program 18 6

Sega Manx TT Deluxe Improperly Torqued Hardware 18 6
Sega Pinball White Star System: CPU/Sound Board 18 6
Williams Reduce Pinball Operations 18 6
Williams Move Atari Assembly Lines to Chicago 18 6
Service Misc Low-Tech Tips for Technical Efficiency 18 6
Service Misc Switching Power Supplies and Bill Acceptors 18 6
Service Misc Good Idea! Gently Turn Screws Backwards 18 6
Video Misc Bowling for Dollars! Repairing Older Monitors for Profit 18 6
Miscellaneous Coin-Op Manufacturers Skinny Up or Go Bye Bye 18 6
Miscellaneous Pinball News...Top 15 Pinballs (Jul) 18 6
Miscellaneous AMOA 1996 Game Award Nominees 18 6
Dynamo Air Hockey Coin Setup Procedure 18 7
Merit Touchscreen Controller Modification 18 7
Micro Mfg Magical Touch Lock-Up Symptom 18 7
Midway Killer Instinct Reset Problem 18 7
Rowe CDM-12 CD Player Final Factory Fix 18 7
Rowe CD-100F Jukeboxes Title Page Protection 18 7
Rowe CD-100 Sagging Doors Field Tip 18 7
Rowe CDM-12 Random Thoughts and Observations 18 7
Rowe Infra-Red Remote Interface Modification 18 7
Sega Indy 500 Input Calibration Procedure 18 7
Sega Pinball Technical Support: 7 Segment Displays 18 7
Williams Tales of the Arabian Nights Magnet Cable 18 7
Service Misc Good Idea! Buy in Bulk When You Can 18 7
Service Misc S.O.S. Save Our Switchers: (Pt 1) 18 7
Miscellaneous Pinball News: Top Rated Pins (Aug) 18 7
Miscellaneous In Support of the Operator: Read with an Open Mind! 18 7
Dynamo Air Hockey Delaminated Playfield Repair 18 8
Nintendo New Home System is Delivered to US Retailers 18 8
Premier Stargate Burning Outhole Coil Prevention 18 8
Rowe BC3500 Mystery (Problem Solved) 18 8
Sega Videogame Medium Res Monitor Matchups 18 8
Sega White Star Board System CPU/Sound PCB (Part 2) 18 8
Williams IGT in Court Slot Battle 18 8
Service Misc S.O.S. Save Our Switchers: (Pt 2) 18 8
Miscellaneous Pinball News: Top Rated Pins (Sep) 18 8
Miscellaneous Mechanical Switching Invention Has Coin-Op Applications? 18 8
Data East Hop A Tic Tac Toe Fix for Ball Bounce 18 9
Rowe CD-100F Adding Security Modification 18 9
Sega Gameworks Gunblade Deluxe Gun Site Adjustment 18 9
Sega Pinball White Star System CPU/Sound (Part 3) 18 9
Sega Pinball Adjustments Settings in CMOS Ram 18 9
Wells Gardner 7000 Series Horizontal Range Mod 18 9
Williams Terminator 2 Pinball Wire Form Change 18 9
Service Misc S.O.S. Save Our Switchers: (Pt 3) 18 9
Pinball Misc Pinball Fix-It Hints & Adjustments 18 9
Pinball Misc Pinball Cleaning Tips 18 9

Miscellaneous AMOA Expo '96 Delivers a Disappointing Message 18 9
Miscellaneous Winners of 1996 AMOA Game Awards 18 9
Miscellaneous Pinball News: Top Rated Pins (Oct) 18 9
Miscellaneous Two-Bit Intros Coin-Op Internet Browser Kit 18 9
Bally Reset/Lockup Problems on Bally/Williams WPC System 18 10
NSM ESIV CCU Resetting or Flashing Display 18 10
Premier Streetfighter & Stargate Coil Burning 18 10
Rock-Ola SyberSonic Bass Response Notes 18 10
Sega Virtua Oh Troubleshooting Checklist 18 10
Sega Daytona No Feedback From Steering Motor Adj 18 10
Sega Pinball New Reed Switch Ball Sensor 18 10
Sega Pinball Showcase Backbox on Space Jam 18 10
Williams Reset/Lockup Problems on Bally/Williams WPC System 18 10
Service Misc Setting Up a Coin-Op Service Bench (Part 1) 18 10
Service Misc Magical Touch Counter Top Losing Power When Hot 18 10
Pinball Misc Preventive Maintenance & Hints 18 10
Miscellaneous Pinball News: Top Rated Pins (Nov) 18 10
Miscellaneous Virtuality Brings Back Pac-Man in Virtual Reality 18 10
Merit Touch Screen Eygo Monitor Power Supply Fix 18 11
Nintendo Monitor 20-EZV(R-C) Symptoms/Solutions 18 11
Rock-Ola T'shooting SyberSonic Electronics 18 11
Sega Pinball Twister Magnet Processor Board Updates 18 11
Sega Pinball MOSFETs in the White Star Board System 18 11
Seidel Smokin' Token LED Alignment Fix 18 11
Wells Gardner 7000 Series Monitor Black Corner 18 11
Williams Junkyard Wrecking Ball Wire Cable Replacement 18 11
Service Misc Setting Up a Coin-Op Service Repair Bench (Pt 2) 18 11
Service Misc Common Electronic Parts Substitutions 18 11
Miscellaneous Operator's Comments: Home Game Ads on Coin-Ops 18 11
Miscellaneous Pinball News: Top Rated Pins (Dec) 18 11
Miscellaneous STJ to Release Pinball V2 Manual Update 18 11
Miscellaneous WD-40 Spray Lubricant Warning & Precaution 18 11
Bally/Williams General Illumination Modification 18 12
Bally/Williams Scared Stiff Playfield Modification 18 12
Bally/Williams Scared Stiff: Solving Mechanism Problems 18 12
Capcom Pinball Goes Bye Bye Closes Chicago Plant 18 12
Rock-Ola SyberSonic System Balancing External Speakers 18 12
Sega Pinball Space Jam I/O Power Driver Heat Sink 18 12
Wells Gardner 33 Monitor Pincushion Problem 18 12
Bally/Williams General Illumination Modification 18 12
Bally/Williams Scared Stiff Playfield Modification 18 12
Bally/Williams Scared Stiff: Solving Mechanism Problems 18 12
Service Misc Setting Up a Coin-Op Service Repair Bench (Pt 3) 18 12
Service Misc The Secret Art of Buying Parts Reasonably 18 12
Jukebox Misc Older Jukebox Tube Substitution Chart 18 12
Miscellaneous New Pentium with MMX Technology Released 18 12
Miscellaneous Pinball News: Top Rated Pins(Jan) 18 12

Miscellaneous Area Codes - A List of Every Code and Its Region 18 12
ICE Home Run Derby Safety Issue 19 1
MarketPlace Listing of Coin-Op Products and Services 19 1
Rock-Ola SyberSonic:Audits Accounting &Disc Changes 19 1
Rock-Ola SyberSonic:Make an Up/Down/Cancel Control 19 1
Sega Goldeneye Ball Save Magnet Fix 19 1
Sega Pinball/Data East Motor Spec Table 19 1
Williams Playfield Problems with Star Trek:NG 19 1
Williams WPC-95 Power Driver General Illumination Mod 19 1
Miscellaneous Pinball News: Top Rated Pins For Earnings 19 1
Miscellaneous Setting Up a Coin-Op Bench (PT 4) Selecting a DMM 19 1
Miscellaneous Volume 18 Index 19 1
Bally Scared Stiff Game ROM 19 2
Bally/Williams Theatre of Magic Mis-Labeled Magic Trunk 19 2
Nintendo Put Up a Sign in the Arcade We Fix Nintendo 19 2
Rowe Why and How to Clean CBA-2 Bill Acceptors 19 2
Sega GameWorks Daytona LE Input Control Problems 19 2
Sega Pinball Dot Matrix Display Board 4X Spacer Addition 19 2
Sega Pinball Flipper Alignment Spot and Height Adjustment 19 2
Miscellaneous ATEI '97 London Expo Facts and Figures 19 2
Miscellaneous Atlanta To Host AMOA International Expo '97 19 2
Miscellaneous Identifying Diodes in Electronic Pinball Games 19 2
Miscellaneous Impressions of '97 ASI Show & Rock-Ola's 2-Way TeleComm 19 2
Miscellaneous Pinball News: Top Rated Pins For Earnings 19 2
Miscellaneous Playfield Restoration Tips and Good Ideas! 19 2
Miscellaneous Setting Up a Coin-Op Bench (PT 5) Selecting an O'Scope 19 2
Gottlieb/Premier Street Fighter 2 Outlane Switch Symptom 19 3
Rock-Ola CD Jukebox SyberSonic Software Update 19 3
Rowe BC-3500 Bill & Coin Changer Intermittents 19 3
Sega GameWorks Super GT Deluxe Proper Connections 19 3
Sega GameWorks Super GT Deluxe & Twin Shipping Note 19 3
Sega GameWorks Super GT Link Kit Factory Defaults 19 3
Sega Pinball Star Wars Special Edition Skill Shot Card 19 3
Star Tech Journal Communicate with Star Tech's Writers 19 3
Star Tech Journal Readies New Internet Website 19 3
Miscellaneous New JAMMA Edge Connector Due in 2000 19 3
Miscellaneous On the Internet:Beware of the Cookie Monster 19 3
Miscellaneous Peter Chou Power Supply Shut Down Repair 19 3
Miscellaneous Setting Up a Coin-Op Bench (PT 6) Power Supplies 19 3
Miscellaneous VideoGame Degaussing Procedure 19 3
Atari Badlands Error Code Deciphering 19 4
Bally Attack From Mars Strobe Alert & Modification 19 4
Bally/Williams Scared Stiff:Terror in the Crate 19 4
MarketPlace Coin-Op Products and Services for the Industry 19 4
Mars IntelliTrac Coin Changer T'Shooting Guide 19 4
Phillips CDM-3 Laser Servicing for CD Jukeboxes 19 4
Premier Nightmare on Elm Street GI Back Board Problem 19 4

Sega Pinball Glass Dimensions for Widebody Pins 19 4
Star Tech Journal New CD-ROM Releases 19 4
Miscellaneous AMOA/AAMA Standardization Committee New proposals 19 4
Miscellaneous Pinball News: Top Rated Pins For Earnings 19 4
Miscellaneous Setting Up a Coin-Op Bench (PT 7) Video Pattern Generator 19 4
Miscellaneous Shop Quiz: You Have to Hire a New Technician 19 4
Rock-Ola BGM Input Loss Check the Program 19 5
Sega GameWorks Super GT Deluxe & Twin Socket Head Screw 19 5
Sega Pinball/Data East PCB Compatibility Charts 19 5
Sega Pinball Retrofit Wire Loop Actuator VUK 19 5
Sega Pinball Space Jam New Backboard Decals 19 5
Sega Pinball Star Wars Trilogy Redesigned Drop Target Lift 19 5
Sega Pinball Star Wars Trilogy Reset Alignment Bracket Kit 19 5
Sega Power Drift Sit-Down Vibration Motor Mod 19 5
Star Tech Journal Introduces New Message Center 19 5
Wells Gardner U5000 Symptom: Dead Monitor 19 5
Miscellaneous Pinball Fast Becoming a Viable Investment Again 19 5
Miscellaneous Pinball News: Top Rated Pins For Earnings 19 5
Miscellaneous Setting Up a Coin-Op Bench (PT 8) The Dremel Tool 19 5
Miscellaneous Troubleshooting the SyberSonic Computer and Keyboard/Disp 19 5
MarketPlace Coin-Op News Arcade Ops Opt For Conversions 19 6
Midway Mace Software Fixes for Difficulty and Secrets 19 6
Namco Suzuka 8 Hours Resetting Problem 19 6
Nintendo So You Really Want to Get Into Nintendo Repair 19 6
Planet Earth Pirates Revenge Sensor Adjustments 19 6
Sega GameWorks Top Skate Loose Skateboard Mod 19 6
Sega Pinball Solid State Flipper Board Conversion 19 6
Wells Gardner U5000 Monitor Horizontal Tear 19 6
Williams NBA Max Hangtime Free Player Condition 19 6
Miscellaneous Dollar Coin Update: AMOA in Washington 19 6
Miscellaneous Pinball News: Top Rated Older Pins For Earnings 19 6
Miscellaneous Top Earning Game Polls: Video Pins & Redemption 19 6
Atari Hard Drivin' Intermittent Loading Errors 19 7
ICE Super Chexx Power & Audio Modifications 19 7
IGS Lord of the Gun Voice EPROM Programming 19 7
Incredible Technologies World Class Bowling ROM Revision 19 7
Rock-Ola SyberSonic Page Errors & New Amp Heatsink 19 7
Rowe CD-100F Phonos Noisy Color Tubes 19 7
Seeburg Blast Jukebox New Title Display Kit 19 7
Sega GameWorks Top Skater Broken Screw Mounts Fix 19 7
Sega GameWorks Top Skater Loose Hardware Advisory 19 7
Williams Junk Yard Game ROM Revisions 19 7
Williams Medieval Madness Game ROM Revisions 19 7
Miscellaneous Coin-Op News: Disney to Join Mega Arcade Movement 19 7
Miscellaneous L-E-A-R-N-I-N-G: Keeping Technically Informed 19 7
Miscellaneous Pinball News: Top Rated Pins Based on Earnings 19 7
Miscellaneous The Importance of Proper Grounding (Arcade Tales) 19 7

Miscellaneous Top Earning Game Collections: Video Pins & Redemption 19 7
Bally NBA Fastbreak Right Ramp Ball Hang-up 19 8
Capcom Pinball Buzzing Coils Modification 19 8
Rock-Ola 6000X Legend Lamp Replacement 19 8
Rock-Ola Using SyberSonic Self Diagnosis Features 19 8
Sega GameWorks Manx TT Seat Cowl Stickers 19 8
Sega GameWorks Super GT Deluxe Cooling Fans 19 8
Sega Pinball Semiconductor IC and Relay Cross Reference 19 8
Miscellaneous IBM Introduces New process For More Powerful CPUs 19 8
Miscellaneous Pinball: Dead or Alive: 100% Alive! 19 8
Miscellaneous Pinball News: Top Rated Pins Based on Earnings 19 8
Miscellaneous Silicone: The Wonder Goop Versatile Repair Aid 19 8
Miscellaneous Top Earning Game Polls: Video Pins & Redemption 19 8
Capcom Breakshot Ejects Two Balls into Shooter Lane 19 9
Electrohome GO7 Distortion: Ringing in Picture 19 9
Merit Megatouch XL R3B CD-ROMs Update 19 9
Rock-Ola Older Amplifier Symptoms/Solutions 19 9
Sega Pinball Opto Alignment Tool: Easy & Cheap 19 9
Smart Industries Major Crane Problems 19 9
Williams Uses Friendly Shifter Keeps Downtime Low 19 9
Miscellaneous Everything You Always Wanted to Know About Locks 19 9
Miscellaneous Pinball News: Top Rated Pins Earnings Poll 19 9
Miscellaneous Return of the Silver Ball: Preventive Maintenance 19 9
Miscellaneous Top Earning Game Collections: Video Pins & Redemption 19 9
Miscellaneous Troubleshooting Gun Games: Gun Problems/Solutions 19 9
Bally CirQus Voltaire ROM V1.1 Revisions 19 10
Happ Controls Responds to Star Tech Gun Repair Article 19 10
Midway Mortal Kombat 4 Version 2.0 Play Improvements 19 10
Rock-Ola Older Jukebox Symptoms/Solutions 19 10
Sega GameWorks Motor Raid Calibration Settings 19 10
Sega Pinball Playfield Switch Opto 'Long Hop' Boards 19 10
Wells Gardner U2000 Weak Video Image Test 19 10
Wells Gardner U2000/5000 Fire Prevention Mod 19 10
Wells Gardner U3000 High Voltage Shutdown 19 10
Williams Touchmaster Faulty Screen Replacement Kit 19 10
Miscellaneous Everything You Always Wanted to Know About Locks (PT 2) 19 10
Miscellaneous Pinball News: Top Rated Pins Earnings Poll 19 10
Miscellaneous Return of the Silver Ball: Flippers Causing Resets 19 10
Miscellaneous Saving Those Old Daytona Steering Wheels & Gearboxes 19 10
Miscellaneous Senate Approves Dollar Coin House Expected to Agree 19 10
Miscellaneous Top Earning Game Collections: Video Pins & Redemption 19 10
Capcom Trouble With Pinball Magic and Breakshot Displays 19 11
Premier Strikes N' Spares Bowler Updates & Adjustments 19 11
Rock-Ola Connecting a Paging Mic to SyberSonic Amps 19 11
Sega GameWorks Model 3 Game Boards Shipping Precaution 19 11
Sega Pinball The X-Files Playfield Update Kit 19 11
Star Tech Journal To Release Updated CD-ROMs for '98 19 11

Wells Gardner Expanding the Horizontal Range of K7000 19 11
Miscellaneous Operator's Lament: Is There No Reliable MedRes Monitor? 19 11
Miscellaneous Pinball News: Top Rated Pins Earnings Poll 19 11
Miscellaneous Return of the Silver Ball: Manual Ball Shooters 19 11
Miscellaneous Simple Switch Matrix Fixes and Troubleshooting 19 11
Miscellaneous Top Earning Game Collections: Video Pins & Redemption 19 11
Miscellaneous Wire Joining Splicing and Termination (PT 1) 19 11
Happ Controls New Universal Optical Gun PCB 19 12
Rock-Ola SyberSonic Telecommunications EPROM Upgrade 19 12
Sega GameWorks Top Skater Mandatory Modification 19 12
Sega Pinball New Style Flipper Part Rebuild Kits 19 12
Williams Crank Assembly for Star Trek: Next Generation 19 12
Miscellaneous How to Adjust Your Electronic Roll Down Acceptor 19 12
Miscellaneous Pinball News: Top Rated Pins Earnings Poll 19 12
Miscellaneous Pot Problems! Steering and Accelerator Tips 19 12
Miscellaneous Top Earning Game Collections Reports 19 12
Miscellaneous Wire Joining Splicing and Termination (PT 2) 19 12

VOLUME 20

March 1998 - February 1999

Sega Style" & "Data East Style" Flipper Rebuild Kits 7
About the Wells-Gardner U5000 Monitor... Enough! 3
Atari Picks Cyrix for New Site 4 Arcade Game 9
Atari SF Rush Motor Drive Board ID'ing the Op Amps 8
Atari Site 4 Intermittent Reset Solution 12
Atari Surf Planet Link Option Adjustment 3
Atari's Hard Drivin' or Race Drivin' Resets Controls 3
Atlus/Namco Bust A Grove at the Arcade 12
Autumn Tokyo Game Show Details 6
Bally Champion Pub Game ROM Revisions 6
Bally Safe Cracker Pinball Recent Software Changes 4
Bally White Water Pin with "Check Fuses" Error Message 2
Battery Reference Chart: Size, Type, Volts, Capacity 10
Capacitor Reference Charts: Values, Tolerance & Math 12
Resistor Reference Chart: Values, Tolerance & Math 11
Capcom Kit Marvel Vs Capcom Number 1 in Earnings 5
Capcom's Pinball Magic Stage Ramp and Wand Problems 4
Checking Game Controls: How to Test Potentiometers 11
Classics on Tap at World of Atari Show 7
Daytona 2 USA Deluxe Cabinet Movement & Break Wiring 7
Daytona 2 USA No Music During Game Play 7
Discussing Pinball Playfield Angles & Protective Coatings 8
Electronic Technicians Assoc Announces Convention 9
Eprom Removal Tool from Happ Controls 9
GreyStone Premier XS-G, a New PC Based Real-Time Video 2
Happ Controls Flexible Coin Door System 6

<http://www.startechjournal.com>

Happ Controls Gun PCB Modifications 7
Happ Controls Responds to Optical Gun PCB Mods 8
Hey, Game Manufacturers! Can You Say, QA? 12
ICE Super Chexx Weird Problems 12
Incredible Technologies 3D Golf Defective Trackballs 10
Industry Equipment Poll: Namco Time Crisis on Top 6
Installing the STJ Brightener on Happ Controls' Monitors 11
Leisure Time Pot-O-Gold Security Notes 6
Mandatory Sharpshooter EPROM Update to v1.7 5
Merit Megatouch XL 6000 Upgrade Kits 12
Merit Megatouch XL CD-ROM Drive Premature Failures 8
Merit Megatouch XL Loose I/O PCB Problems 12
Merit Megatouch XL Removing Security Key 12
Merit Monitor Found Dead (Eygo Monitor Repair) 2
Midway Shows California Speed Arcade Racer for Home 11
Midway & Nintendo NFL Blitz Interacts with Blitz '99 8
Midway Blitz 99 Kit Highlights and Notes 12
Midway Gets Ready for 1999: New games Home & Arcade 11
Midway Hyperdrive Software Update 10
Midway NFL Blitz '99 Kits Installation Clarification 11
Midway Presents Arcade's Greatest Hits for PlayStation 4
More on Wells Gardner Infamous U5000 Monitor 2
Neo-Tec NT27 Colour Monitor for Atari San Francisco Rush 12
New \$20 Bill: Mars and CashCode Conversions 9
New Innovations at Sega Pinball: Backbox, Magnets & Optos 6
New Internet Coin-Op UK Newsgroups Formed 2
New Optical Gun Products from Happ Controls 10
New Sega Arcade Offerings at Fall Expo 9
New Style Flipper Assembly Replacements to Older Pins 2
Notes on Tommy Lift and Eagle Lift Gates 1
Number One Service Call: Coin Jams... Choosing a Mech 2
Old Arcade Games are Scoring a Comeback 11
Operation Thunder Hurricane Gun Problems Software Fix 7
Operators Respond to Reliable Monitor Question 1
Ordering Sega Pinball Individual Stand-Up Targets 10
Pinball Ball Shooters High Failure Rate 10
PowerVR Series2 3D Graphics Chip Powers New System 10
Preventing Pinball Battery Corrosion and Maintenance 11
Quantum3D Launches Computer System for Coin-Op 4
Quick Fixes for 25" Kortek/Sharp Image Monitor Chassis 5
Repairing Older Rock-Ola Jukes S-4 through S-6 Computers 5
Repairing Scratched CDs with Plastic Polish 4
Restoring Worn Pinball Machine Playfields (pt 2) 5
Restoring Worn Pinball Machine Playfields (pt 3) 6
Restoring Worn Pinball Machine Playfields 4
Rock-Ola Color Tube Change and Coin Return Mod 9
Rock-Ola Jukebox Operating System Software Updates 9

Rock-Ola Noisy Motors in SyberSonic Jukeboxes 3
Rowe Adds New Switching Power Supply to Changers 4
Rowe BC-25: New Money, New Update? 12
Rowe Bill Acceptors: Accepting the New \$20 US Notes 12
Rowe CD 100G Starlight Power Plug Precaution 3
Rowe CD-100 Philips Player Upgrade 12
Rowe CD-100G Title Rack Motor Noise Modification 4
Rowe RBA-7 Software Revision 2.0 Fixes Shutdowns 3
Rowe Starlight Cabinet Problems 6
Rowe Title Rack Driver Part Replacement 3
Schofield First Target for Virtual Reality Game 5
Sega BassFishing Control Panel Support Bracket 9
Sega Daytona Handle and Shift Lever Maintenance 11
Sega Enterprises Gets Coin-Op Div from Sega GameWorks 8
Sega GameWorks Driving Games Cable Routing 1
Sega GameWorks Harley Davidson Bracket Installation 5
Sega GameWorks Harley Davidson DLX Steering Notes 4
Sega GameWorks Harley Deluxe Main Frame Retrofit Bracket 12
Sega GameWorks Safe Handling of Video Monitors 8
Sega GameWorks Videogame Power Ratings and Cautions 5
Sega GameWorks Wave Runner Handle Holder Assembly 5
Sega Harley Davidson & LA Riders Calibration 10
Sega Lost World Reclaims Top Spot In Earnings Poll 4
Sega Pinball Large Dot Display Cable Harness Update Kit 3
Sega Pinball Opto Cross Reference Chart 6
Sega Pinball Part Numbering System -Madness? 9
Sega Pinball Plastic Part Color Chart for Target Tops 10
Sega Pinball Preventative Maintenance Tips 4
Sega Pinball Shipping Bracket Screw & Playfield Glass 2
Sega Pinball Software Codes for Games from '94 to '98 11
Sega Pinball South Park Expanded Speech Capabilities 12
Sega Pinball Starship Troopers Playfield Terminal Strips 1
Sega Pinball T'shooting White Star Coils & Drivers 8
Sega Pinball White Star Benchttop Test Fixture 8
Smart Candy/Beanie Baby Crane Facelift & Makeover 9
So, You Want to be a Game Designer? Here's Advice 7
Spring Expo to be Held March 10 - 12 in Vegas 11
STJ Releases New Version STJ on CD-ROM V.3 1
Substitution Parts for Data East Solid State Pins 1
Taito Ice Cold Beer Motor Source 11
The New Universal Arcade Standard? 10
TicketFlex: A Ticket Dispenser Control Interface 10
Time to Swap Out the Infamous Wells Gardner U5000 9
Top Skater Fiber Optic Cables Needed for Link Play 7
Top Skater Replacement Bearings Excessive Wear 7
Top Skater Swing Base Shaft Attract Mode Precaution 7
Upgrading Monitors for the Right Games 3

<http://www.startechjournal.com>

Video Camera E-Beams You Into This New Game 1
Volume 19 Index: March 1997 - February 1998 1
Warranty on Wells-Gardner 5000 Monitors 3
Wells Gardner 2000 Monitor No Horizontal Width 4
Wells Gardner Announces Acquisition of Coin Controls 5
Wells Gardner K7000 Monitor Flickering Screen 4
Wells Gardner K7000 Troubleshooting Chart 6
Wells Gardner K7000 Troubleshooting Flow Chart 11
Wells Gardner K7000 Troubleshooting Reference Guide 11
Wells Gardner K7200 High Voltage Shutdown Guide 7
Wells Gardner Monitor for Blitz CRT Type 1
Wells Gardner Over and Under Door Change 11
Wells Gardner Releases Four New Flat Panel Displays 9
Wells Gardner U2000 Troubleshooting Guide 8
Wells Gardner U5000 Monitor Jittery Picture 4
Wells Gardner U5000 T'Shooting Power Supply 7
Williams Monster Bash Software Revision Changes 8
Williams Pinball Circus Voltaire Disappearing Jet Bumper 1
Williams Pinball Upgrade Kit for Circus Voltaire 1
Williams/Bally WPC ROM Information and Upgrades 2
Wms Circus Voltaire Adjustments to Ensure Longtime Earnings 3
Wms Game ROM Revisions: Champ Pub, Circus & Gofers 3

VOLUME 21 INDEX

March 1999 - February 2000

Title/Page/Issue#

Arachnid Black Widow Right Side vs Left Side Area 20/5
Arachnid Black Widow Status Indicators 6/5
Arachnid Dartman w/Windows Desktop Icon 5/9
Arachnid Dartman Upgrading to Galaxy V7.X EPROM 18/8
Arachnid Flashing Bill Acceptor Modification 4/4
Arachnid Modems Approved for Black Widow 12/9
Arachnid Tech Tips: A T'shooter's Toolbox 16/1
Atari Gauntlet Legends New Software Update 8/1
Atari Receives Japanese Patent on Steering Technology 4/2
Atari Rush the Rock Incorrect Fuses in Sit-Down 8/6
Atari SF Rush the Rock Flashing Video Symptom 4/1
Atari SF Rush the Rock game Reset Modification 19/2
Atari SF Rush the Rock Reset Problem CPU Modification 5/12
Atari Surf Planet Control Panel Precaution 7/2
Atari War: Final Assault Software Update Available 13/4
Atari/Midway Operator Friendly Rush 2049 Features 13/9
Bally Cactus Canyon Game ROM Revisions 9/5
Bally Champion Pub Arm Breakage Modification 15/3
Bally Flash Gordon Playfield Switch Problem 11/5
Black Lite with Happ Competition Buttons 17/5

Capcom Power Stone Gets Arcade Release 15/1
Data East World Cup Futbol Tune-up Notes 15/2
Deltronics Dispensers Made Easier: Tilt Mod 6/9
Deltronics DL 4SS Troubleshooting Guide 17/9
Deltronics DL-1275 Troubleshooting Guide 8/2
Deltronic Ticket Dispenser DL1275 Maintainance 9/6
Deltronics Ticket Eater Troubleshooting 10/2
Dynamo Solitair Challenge CMOS Battery 16/7
Happ Controls Durable Control Panel Overlay 10/10
Happ Controls Gun Hose Harness and Plate 9/3
Happ Controls Introduces Over/Under Validator Door 18/2
Happ Controls Releases 1999/2000 Coin-Op Catalog 5/2
Konami Guitar Freaks 3rd Mix Released to Arcades 7/12
Mars Revamps Web Site to Provide More Information 4/1
Merit Blue Maxx Cheap Flash Card Solution 16/9
Merit Maxx Floating Calibration Precaution 4/8
Merit MegaTouch History of the XL Tournament CD 16/5
Merit MegaTouch Maxx Missing Spacer for Hard Drive 10/5
Merit Megatouch XL Dim Ducksan Monitor 13/12
Merit Megatouch XL 6000 has Unique Y2K Fever 7/12
Merit Megatouch XL Upgrade Match the Rev to the PCB 20/2
Merit Megatouch XL Upgrade Match the Rev to the PCB 20/4
Merit MegaTouch XL6000 Kit RAM SIMM ID 7/5
Merit Touchscreens Most Common Failure 12/12
Merit XL Date/Touchscreen Controller Failure 6/12
Midway Carnevil Pump Handle Replacement Kit 5/8
Midway Games Inc. Reports Third Quarter Earnings 4/3
Midway Hydro Thunder Won't Accept \$2 or \$5 Bills 10/11
Midway HydroThunder Won't Accept \$2/\$5 Bills 4/8
Midway Mortal Kombat Gold's Arcade Perfection 5/7
Midway Releases Q2 Fiscal Results 20/12
Midway's Spy Hunter and Moon Patrol Ships to Retail 5/4
Namco Time Crisis II Gun Maintenance 11/9
Namco Time Crisis II Theft Deterrent 10/1
Rock Ola Legend Lower Coin Chute Deflector Mod 12/4
Rock-Ola Relubricating SyberSonic Gripper Unit 7/11
Rock-Ola SyberSonic Jukebox Paging Mic Signal Added 13/7
Rock-Ola Won't Repair CDM-3 and CDM-4 Players 12/7
Rowe BC-100 & BC-200 \$10 Software Update 13/11
Rowe CD-100 and WP-100 Selector Software Change 15/4
Rowe CD-100 Player Upgrade Question and Response 6/2
Sammy Super Sports Arena Security Modification 15/6
Seeburg Jukebox Resource List Parts and Updates 20/10
Seeburg Story: A Repair Ordeal 7/8
Sega Bass Fishing Deluxe 220v to 120v Conversion 12/6
Sega Bass Fishing Upright Cabinet Handle Retrofit 16/12
Sega Brave Firefighters Damaged Nozzle Assembly Fix 11/11

<http://www.startechjournal.com>

Sega Brave Firefighters Failing Hose Replacement Mod 10/8
Sega Crazy Taxi Foot Pedal Assembly 6/6
Sega Crazy Taxi Rain Coat Position 7/6
Sega Daytona Maintenance & Adjustments 18/7
Sega Derby Owners Club in Japanese Arcades 7/9
Sega Enterprises Star Wars Replacement Joystick 8/5
Sega F355 Challenge Loose Speed Shift Knobs 6/8
Sega GameWorks Zombie Revenge Wire Harness Layout 7/4
Sega Konami Try New Game Technology 15/1
Sega Naomi Kit Universal Wiring Diagram 8/12
Sega Pinball Code Library Download Site Coming 19/5
Sega Pinball Low Line Voltage Modification 16/4
Sega Pinball: No Display? No Game Function? 18/6
Sega Pinball South Park Adj 56 (Adult Speech) 7/1
Sega Pinball South Park Up & Down Coil Power Adj 18/3
Sega Pinball South Park Update Kit Supports Characters 16/2
Sega ROM Code Library Page www.segapinball.com 15/7
Sega/Stern Y2K Pinball Games Compliant? 20/9
Sega Toy Fighter 3D Arcade Title Screen 17/10
Sega Virtua Striker 2 Version 2000.1 5/11
Sega Zombie Revenge Kit Installation and Monitor Info 10/3
Sega Zombie Revenge Securing Joystick Knob 6/4
Smart 6th Gen Cranes Adjusting Claw Strength 10/7
Smart Industries Improved Steel Motor Gear 9/7
Stern Buys Sega Pinball A Word From Tech Support 19/9
Stern Pinball Harley-Davidson Motor Relay Alert 18/12
Stern Pinball Harley Davidson Switch Membrane 15/8
Stern Pinball Harley-Davidson Update Kit 16/11
Taito Chase HQ The Car is Missing Again 10/11
TicketFlex Maximizer FAQ Frequently Asked Questions 16/10
TicketFlex Maximizer New A2 Interface PCB 12/3
TicketFlex Maximizer Older Machines Produce 8/9
TicketFlex Maximizer Operate Smarter 19/4
TicketFlex Maximizer Reducing Ticket Payout 11/7
TicketFlex Maximizer Smart Board Increases Cashbox 24/5
TicketFlex Maximizer Solves Any Ticket PayOut Problem 10/12
Touch Tunes Signs Capitol Records for Digital Juke 9/11
Virtual Games Inc Picks Up the Pieces and Thrusts On 20/4
Wells Gardner Releases 1999 Catalog 11/3
Wells Gardner U3000 Vertical Roll Modification 18/9
Wells Gardner U5000 Monitor Swap with K7500 9/11
Wells Gardner U5000 Sync Problem Advice 9/1
Wells Gardner U5000 Vertical Picture Problems 8/11
Wells Gardner Video Wall Troubleshooting Guide 5/1
Williams Electronic Games Exits the Pinball Business 18/10
A Day in the Life of a Coin-Op Games Technician 6/3
A Note to Operators with Hard Drive Games 8/4

And Then There Was One... An Operators Viewpoint 19/10
Arcade Gun Games - Is a Ban on the Way? 12/12
ATEI News: A Look Ahead Into the Next Millenium 5/10
Burned Connectors on Pinball Games Solution 9/12
Dreamcast Gauntlet Legends Version Confirmed 5/9
Easy Removal Method for Touch Screen Glass 7/2
How an Operator Decided Enough is Enough! 10/6
How to Program Benchmark's Drill-O-Matic 8/7
How to Test Transistors Basic Theory and Other Tidbits 7/3
Intel to Launch Pentium III Will Run at 450 - 500 MHz 15/1
Japan's JAMMA Show Highlights 8/8
Keeping Your Pinball Machines Clean & Earning 20/1
Microsoft Gets Into The Game w/Console 8/8
Midwest Amusement Selects Computer Assoc PC Games 6/1
Mint Begins Producing Sacagawea Dollar Coins 4/10
Namco Amusement Profits Dip Blame Cell Phones 9/10
New Demand Sparks Reissue of Susan B. Anthony Dollars 9/4
News From Japan... New Releases/New Ports 4/5
Pac Man Back in the News WSJ Quotes Operator 17/6
Pinball T'Shooting Tips: Flippers Multiball Matrix Blanking 12/2
Problems With 5101 CMOS RAMS? 10/9
Re-Evaluating Equipment Lift Gates 13/10
Replacement Techniques for Common Components 12/5
Servicing Gun Games: Report on New Gun Cable System 8/3
South Carolina's High Court Disallows Video Gambling 4/9
T'shooting Steering Problems in Driving Games 8/10
Tech Tools Auto List Server for Test Equipment 9/10
Test Reports and Switch Test in WPC System Machines 10/4
Sega Reveals Plans for Camera & New Arcade Titles 4/7
US Mint Begins Shipping New Golden Dollar Coin 4/12
US Mint Releases Samples of New 'Golden Dollar' Coin 4/11
Video Game Sales Soar Play Up 21% in 2 Years 17/6
Volume 20 Index: March 1998 - February 1999 12/1
What Shall Become of All the WPC Security Pins? 19/10
Why is the US Mint Producing a New Dollar Coin? 4/6
Y2K: Coming to a Desktop Near You! 16/3

VOLUME 22 INDEX

March 2000 - February 2001

Title, Page, Issue

AAMA, AMOA and IAMO Challenge IN Law 4 Oct
Addams Family Reboots During Play Goes Into Test 6 Nov
American Laser Gun Games A Sub for Infrared LED 8 May
Amusement Has Shock Value at Dave & Buster's 5 Aug
Arachnid Darts Cap Kits Amber Monitors 10 Jun
Arachnid: Problems with Black Widow Monitors 8 Jan

<http://www.startechjournal.com>

Arachnid Series 6000 Dart Games Lock Up 7 Nov
Arcade Games and Home Consoles Together? 5 May
Arcade Games from the Inside Out: Pinball Switch Matrix 10 Jan
Arch Rivals Sega and Namco Unite in Japan 5 Jan
Ardac MBA Control Doesn't Give Credits 11 Mar
Atari Area 51 Reset Problem Not the Hard Drive 9 Mar
Atari Area 51 Site 4 Lock-Up Solution 10 May
Atari Area 51/Maximum Force No Display 6 Jun
Atari Race Driving Control Problems 17 Jan
Atari RoadBurners Throttle Problem 12 Nov
Atari Rush the Rock Vibrating Steering Symptom 10 Aug
Atari San Francisco 2049 Broken Belt Replacement 9 Sep
Atari San Francisco Rush Flagstaff System Mods 8 Jul
Atari SF Rush and Rush 2049 Stand Alone Diagnostics 11 Mar
Bally Revenge From Mars Intermittent Switches 7 Jun
Benchmark Big Haul Dispenser Runs Constantly 6 Aug
Bromely Colorama Intermittent Play Solution 8 Sep
Bushnell Responds to New Arcade Project Article 4 Dec
Bushnell's Latest Arcade Project Aimed Upscale 9 Nov
CashCode Bill Acceptor Eating Currency 6 Oct
Cashless Peripheral Device Intro'd by Coinless Systems 5 Mar
CDM3 Players Mech and Decoder Problems 6 Sep
CDM4 Player Laser Setup Procedure 12 Nov
Changer Upgrades for New Bills and for the Future 13 Sep
Cherry Master Anti-Cheat Security Measures 8 Nov
Chuck E Cheese Manager Designs Wheelchair Ride 6 Jan
Coin Op International CD Player Update 15 Mar
Conquest Has Landed New Touchscreen Technology 5 Sep
Crystal Ball on Coin-Op 2001 Industry Forecast 4 Feb
Extended Life for General Illumination Light Bulbs 20 Dec
Firebird Bill Acceptor Credit Problem 12 Jun
Full Court Frenzy II Alarm and Program Options 7 Oct
Game Copies Becoming a Problem Once Again 5 Jan
Game Makers That No Longer Make Games 8 Dec
Gas Discharge Displays in Pinball Machines 10 Dec
Going Forward by Going 'Backward' Systems Retro 4 Jan
Golden Dollar: Boom or Bust? Opinions 20 Jul
Golden Tee Trackball Repair and Replacement 16 Jan
Hantarex 25" Colour Monitor Shaky Picture 10 Aug
How to Convert a Merit XL 5000 to a 6000 8 Apr
IAAPA Show: Not Much Thunder in Artic! 6 Dec
ICE Cyclone Erratic Operation Symptom/Solution 6 Oct
ICE Cyclone Heat Related Precautions 20 Jan
Indianapolis to Ban Violent Arcade Games 4 May
Jukebox Conversion: Go From Vinyl to CD's! 16 Dec
Konami Crisis Zone Gun Inoperative 18 May
Laser Tron Super Solar Spin Monitor Problems 15 Oct

Leisure HSV300 Upgrade to New 5's and 10's 13 Aug
Let's Make More Money! Return on Investment 6 Feb
Lights Out for Interactive Light Video Company Folds 4 Jul
London Show Reflects Global Marketplace 4 Mar
Mars AL4 Units Exhibiting Symptoms 20 Aug
Merit Blue Maxx Lock Up Problem/Solution 7 Sep
Merit Countertop Ducksan Monitor Jitters 17 Nov
Merit Megatouch Monitor Horizontal Problem 6 Sep
Merit XL Hard Drive Conversion Procedure 11 Aug
Merit XL Line Add Conditioner Precaution 20 Apr
Midway Cruisin' Exotica Calibration Problems 9 Jun
Monitor Terminology by Wells Gardner Electronics 15 Sep
MTV Invades the Arcades Intros New Game 15 Jul
Namco Designs System 246 Hardware Based on PS2 19 Oct
Namco Motocross Go! System 23 Game Board Assembly 10 Sep
Namco Point Blank 2 Conversion Tips 8 Aug
Namco Tokyo Wars Warped Picture Big Screen Fix 19 May
Nanao Monitor Horizontal Bars Symptom 7 Sep
Neo Tech Monitor Symptom White Screen 18 May
Neo-Tec Monitor Bowed or Oversized Picture 9 Jul
New Addams Flipper Hold Coil Problem 16 Nov
New Arcade Game Content Measure Passes 4 Aug
New Distributor of Williams Pinball Parts 7 Nov
New Family-Themed Entertainment Center 17 Apr
New Konami Arcade Titles Includes Free Racing 4 Apr
New Solder in the Works for Electronics Industry 20 May
No Steering or Accelerator Initialize the Inputs? 15 May
NSM Display Segment Missing Problem 17 Nov
Old GO7-CBO Electrohome Monitor High B+ 9 Oct
Ops Reply: Regarding the New Dollar Coin 7 May
Opto Interrupter Operation and Diagram 7 Jul
Opto Isolated Switch Inputs Illustrated 6 Jul
Pinball Preventative Maintenance Inspection 16 Oct
Problems With Black Widow Monitors 11 Nov
Rapture Technologies Developing Games 4 May
Rock-Ola SyberSonic Rocket III, Model 7500 Title Pages 11 Jun
Rowe AMI CD Juke Intermittent Volume Control 10 Apr
Rowe AMI Starlight Plug Compatibility Update 11 Apr
Rowe BC3500 Bill Changer Not Accepting Bills 17 Jan
Rowe CD-100 Amp Mute Circuit from Happ 15 Jan
Rowe CD100H Audio Hissing Problem 18 Jun
Rowe CD51 with CDM-4 Player Reset Solution 9 May
Rowe CDM Players and Disk Cleaning 10 Jul
Rowe CDM4 Motor Rebuild Procedure 11 Oct
Rowe Free Software Upgrades for \$5 and \$10 Bills 13 Jul
Rowe Jukebox Faulty CBA-2 Troubleshooting 21 Jan
Rowe WP-100 Title Rack Mods and Upgrades 17 Mar

<http://www.startechjournal.com>

Sammy USA Deer Hunting Gun Calibration Problems 7 Aug
Sega 18 Wheeler Horn Button Shaft Modification 7 Dec
Sega 18 Wheeler Intermittent Reset Problem 18 May
Sega Arcade Classic Ships for the PS2 4 Nov
Sega Bass Fishing Handle Screw Causing Problems 20 Mar
Sega Bass Fishing Static Discharge Modification 16 Mar
Sega Caution: NASCAR Raincoat Can Block Vents 15 Dec
Sega Changes Slots to Fit New Dollar Coin 5 Jun
Sega Crazy Taxi SD Rain Coat Precaution 7 Apr
Sega Debuts First Online-Only Arcade 19 Oct
Sega Gun Games Shooting and Tracking Fixes 8 Mar
Sega Hopes Rentals Will Revitalize Arcades 5 Nov
Sega Lost World Video Gun Component Damage Situation 10 Mar
Sega Manx TT Symptom No Motion 13 May
Sega Naomi Crediting Problems Solution 10 Jun
Sega NAOMI2 New Arcade System 5 Oct
Sega NASCAR Heat Buildup and Game Freeze 12 Dec
Sega Outrunner Sitdown Twin Missing or Slow Objects 18 Jul
Sega Pinball Batman Forever Low Power Supply Voltage 19 Apr
Sega Pod Racer Speed Lever and Brake Lever Update Kit 15 Feb
Sega Scud Racer Symptom No Motion 12 May
Sega Star Wars Racer Website Launched 5 Sep
Sega Strike Fighter Deluxe Important Joystick Notice 14 Feb
Sega to Release WWF Royal Rumble for Arcades 4 Jun
Sega Triple Wide Coin Door Security Hasps 13 Jun
Sega WaveRunner T'shooting Tips and Error Codes 18 Mar
Sega's Business Woes Continue w/Restructuring 15 Jun
Sega's Next Generation Arcade System Ready 12 Jul
Sharp Image 19KTE Vertical Deflection Problem 19 Jan
Smart Ticket Center Chronological Updates List 18 Nov
Smart Ticket Redemption Center Reputation 12 Sep
SNK to Continue Successful Arcade Business 5 Jul
Sony's PlayStation 2 Compatible Arcade Board 5 Mar
Special Notice for All Sega Naomi Kits 6 Mar
SRS Labs Debuts Circle Surround Technology 4 Jun
Stanford University Report Stands Up for Industry 18 Feb
Stern Links with Former Williams Designers 7 Jan
Stern Pinball Diagnostic Aids Operator Alerts 11 May
Stern Pinball Harley-Davidson Auto Percentaging 17 May
Stern Pinball Little Known Facts: Did You Know? 15 Nov
Stern Pinball Mod Motor Failure on Harley Davidson 16 Apr
Stern Pinball Sharkey's Shootout Game Adjustments 13 Oct
Stern Pinball to Start Email Technical Bulletins 19 Jul
Stern Pinball Wacky Switch Problems 18 Feb
Stern Sharkey's Shootout Magnet Fuse Fatigue 18 Jan
Stern Striker Xtreme Pinball Increase Your Revenue 16 Jun
Stern Titanic Redemption Game Potential Revenue Loss 16 Jul

Stern's Targets Striker Extreme & Sharkey's Shootout 18 Sep
SternPinball.Com Continues to Grow 10 Oct
Suzuki 8 Symptom: Eats Power Supplies 12 Sep
Switch Matrix Problem: Is It the CPU Board at Fault? 10 Feb
Taito Makes Changes, New Prez Eyes Internet 4 Aug
Tech Tip: Cooling IC's (add years to their life!) 19 Mar
Techmo's DOA3 on Namco's New 246-PS2 20 Oct
Telco TV Merit Megatouch & Arachnid Blk Widow 8 Oct
Time Crisis Gun recognition Problem 17 Nov
Tips on Leadership from an Industry COO 20 May
Troubleshooting Intermittent Problems in Arcade Games 8 Jun
Twilight Zone Intermittent Sound Troubles 12 Jun
Understanding and Repairing the Switchmode Power Supply 12 Apr
Video Violence - Prohibition Official in One State 4 Sep
Videogames Promote Violence in Congressional Hearing 5 Apr
Violent Video Ordinance On Hold in Indy 4 Nov
Volume 21 Index: March 1999 to February 2000 12 Mar
Warning: D.K. Monicor Has Disappeared 11 Jun
Welcome to the Cyber Prohibition Era 12 Oct
Wells Gardner 25K7401 Horizontal Jitter 7 Jan
Wells Gardner K7500 Troubleshooting Guide 12 Aug
Wells Gardner Monitor Startup Problems 11 Jun
Wells Gardner U2000/5000 Series Vertical Collapse 16 May
Wells Gardner U5000 Chassis Replacement 7 Apr
Wells-Gardner Launches Digital Replacement 19" Monitor 5 Nov
Wells-Gardner U2000/U5000 Ground Connection 20 Nov
Whatever Happened to Wico? Buyout News 12 Feb
Williams Black Knight Lock Up Problem 10 Nov
Williams Pinbot General Play and Tech Questions 16 Nov

VOLUME 23 INDEX

March 2001 - February 2002

Title, Page, Issue

Namco's New Vampire Nights - A Sleeper? 4 Mar
Midways Launches New Coin-op Internet Site - Sort Of... 5 Mar
Stern Pinball High Roller Casino Roulette Wheel Ass'y 6 Mar
Sega To Introduce New Dynamic Golf After Several Tries 8 Mar
Nanao 29" Monitor Losing Sync Symptom 9 Mar
Stern Pinball Harley -Davidson Support Plate Kit 10 Mar
Volume 22 Index Of Articles March '00 - February '01 12 Mar
Word Puzzle: Find This Month's Prize Vendors 14 Mar
Exploring Built-in Test In Wms/Bally Wpc & Wpc 95 16 Mar
Happ Controls 3" Trackball Upgrade Program 20 Mar
Rowe 3500 Bill Acceptor Problem Codes 21 Mar
Marketplace: Listing Of Coin-op Sales And Services 22 Mar
Capcom Denials Coming From All Directions 4 Apr

<http://www.startechjournal.com>

Midway Up For Grabs? Company Streamlines 5 Apr
Megatouch Monitor Arcing Problems 6 Apr
Wg K7000 & Hantarex Mtc 9000 Jitters 7 Apr
Rush The Rock Force Feedback Problem 8 Apr
Wells Gardner U5000/K7500 Conversion 8 Apr
Wells Gardner K49xx Shrinking Screen Problem 9 Apr
Troubleshooting Video Game Inputs 10 Apr
Word Puzzle: Find This Month's Sports Games 14 Apr
Stern Sharkey's Shootout Replay Bug Fix 16 Apr
Sega Strike Eagle Analog Joystick 18 Apr
Nsm Remote Control Inop Symptom 19 Apr
Repairing Pcb Male Edge Connectors 19 Apr
Merit Xl Cd-rom Drives & Reboot Problem 20 Apr
Replacing Capcom Drop Targets Source 20 Apr
The Changing World Of Coin-op... 21 Apr
Treasure Falls Accessing Extra Options 4 May
Bubba's Excavation Lock Up Prevention 4 May
Korea Moving Ahead Becoming Major Coin-op Player 4 May
Rowe 3500 Bill Acceptor Feedback & Response 5 May
Stern Pinball Display Troubleshooting 6 May
Ticket Problems With Bubba's Excavation 9 May
Sega Air Trix Deluxe Stopper Modification 10 May
Word Puzzle: Find This Month's Video Games 14 May
Ohm's Law In Practice With Coin-op Servicing 16 May
Nsm Jukebox Remote Control Substitution Source 20 May
Interactive Light Kick It Jr. Sensor Source 20 May
Ticket Counter Display Troubleshooting Aid 21 May
As Time Marches On... What They Don't Know 21 May
Marketplace Listing Of Coin-op Products And Services 22 May
Increased Coin-op Sales Encourage Optimism 4 Jun
Valley Dynamo New Site And Contact Numbers 4 Jun
Sega To Bring Sports Titles To Microsoft Xbox 5 Jun
Merit Industries Double Diamond A No - No 5 Jun
Promax C5000 Chassis Red Screen Symptom 6 Jun
Sega Wild Riders Verify Input Control Operation 7 Jun
A Response To Rumors From Down Under 8 Jun
Troubleshooting: Four Steps Towards The Solution 10 Jun
Williams Wpc Series Pinball Random Reset Symptom 12 Jun
Ps2, Xbox, Gamecube Enter Console War 13 Jun
Word Puzzle: Find This Month's Pinball Games 14 Jun
Backing Up Your Killer Instinct Hard Drive 16 Jun
Wells Gardner Monitors Cross Reference Midway - Namco 19 Jun
Rumours Of Big Operator Going Down The Tubes 20 Jun
Sega's Brave Firefighter Hose Parts Replacement 21 Jun
Marketplace Listing Of Coin-op Products And Services 22 Jun
Looking In Other Directions Sega Diversifies 4 Jul
Midway Exits Coin-op Videogame Market 4 Jul

Atari Name Is Back, Consumer Game Mfg Seeks Recognition 5 Jul
Wms Industries Louis Nicastro Steps Down 5 Jul
Bromley Colorama Solution For Intermittent Switches 7 Jul
Skee-ball Super Shot Basketball Backboard Problems 8 Jul
T'shooting Pinball Intermittent Switch Problems 10 Jul
Stern Austin Powers Pinball Stuck Ball Modifications 13 Jul
Word Puzzle: Find This Month's Boppin' Games 14 Jul
Stern Pinball Switch Matrix Shorts In Trough Area 16 Jul
Wells Gardner 33k8113 With Two Horiz Width Coils 18 Jul
Centipede Videogame Looks Like An Oscilloscope 20 Jul
Capcom Vs Snk Release Into Arcade Market 4 Aug
Hong Kong Show/Online Games Pose Huge Problem 5 Aug
To: Star Tech Journal & Namco America 6 Aug
Rock-ola Sybersonic Self- Diagnostic Utility 7 Aug
Merit Telco Motherboards And Tournamaxx Operation 8 Aug
Daytona Twin Notes And Simplified Diagrams 10 Aug
Word Puzzle: Find This Month's Cranes/Rotaries 14 Aug
Bromley Rock N Bowl Shutdown After Powerup 16 Aug
Sega Harley Davidson Dead Power Supply 17 Aug
Sony Spends Big Bucks On New Internet Game Chip 17 Aug
Degaussing Your Monitor Step By Step Procedure 18 Aug
Midway Artic Thunder Seats Falling Apart 20 Aug
Sega's Brave Firefighter Hose Option 20 Aug
Merit Motherboard Megalink Identification 21 Aug
Arcade Planet & Yahoo! Team To Provide Online Games 4 Sep
Wall Street Notes Redemption Games Figures 5 Sep
Williams High Speed Error Message & System 11 Guide 6 Sep
Merit Elite Maxx Bill Acceptor Clamp Interference 7 Sep
Site 4 Resetting Symptom, Solution And T'shooting 8 Sep
Rowe Cd Juke Intermittent Service Record 9 Sep
Exploring The Sound System In Sega Rally Deluxe 10 Sep
Rock-ola Cd Jukebox Electronic Ass'y Part #'s 12 Sep
Merit Megatouch Continuous Rebooting Symptom 13 Sep
Troubleshooting No Sound Symptom On High Speed 16 Sep
Smart Industries Intermittent Ticket Center/Eater 17 Sep
Williams Star Trek Tng Power Failure Symptom 17 Sep
Rowe Cd100a Title Page Craziness 20 Sep
Nanao Monitor Curved Sides Symptom & Cap Source 21 Sep
We Stand United With All Americans 4 Oct
X-Box Our Pick 5 Oct
Stern Pinball Austin Powers™ Code Update 6 Oct
Sega Waverunner Troubleshooting Drive System Errors 8 Oct
Troubleshooting Electronic Coin Acceptors 10 Oct
Midway Games Executive Bails 13 Oct
Coin-Op Word Puzzle: Prize Vendors 14 Oct
Sega IR Tracking System LED Boards 16 Oct
Sega Pinout for IR Type Guns 17 Oct

<http://www.startechjournal.com>

Stern Pinball: The Bubble Level is Back! 18 Oct
Stern Striker Xtreme & NFL Plastic Stadium Flashlamp 20 Oct
Coin-Op MarketPlace: A Listing of Sales and Services 22 Oct
Microsoft & Sega to Develop Coin-Op System 4 Nov
NSM Jukebox Title Page Immobile Symptom 4 Nov
SNK Go Down... to Close & Liquidate 5 Nov
Stern Pinball Monopoly Playfield Mylar 6 Nov
Golden Tee Golf on the Big Screen 8 Nov
Sega Waverunner Pitch Cylinder Evacuation 9 Nov
Troubleshooting Link Games 10 Nov
Coin-Op Word Puzzle: Pinball Games 14 Nov
Telco Monitor No Picture Symptom 16 Nov
Valley Pool Table Jammed Coin Chutes 18 Nov
Rush the Rock Force Feedback System Problem 19 Nov
How to Make Vector Monitors Very Reliable! 20 Nov
Hantarex MTC 9000 Monitor Hiss Symptom 21 Nov
IAAPA 2001 Show Diary 4 Dec
Are Online Tournament Fees Competitive? 7 Dec
ICE Ball Coin Up Release Problem 8 Dec
The Shadow Pinball Magnet Problem 9 Dec
Common Flipper Problems and Solutions 10 Dec
Coin-Op Word Puzzle: Video Games 14 Dec
Slide-It Multi-Game Lock Up Symptom 16 Dec
Tekbilt Switching Power Supply Repairs 17 Dec
Wells Gardner 14K7302 No Vertical Deflection 17 Dec
Dr Face For Apple 17 Dec
Stern Pinball Monopoly® Tips & Tricks 18 Dec
Are Online Fees Competitive (part 2)? 4 Jan
Japan in Decline - Revenue Figures 4 Jan
Park Sales Down - Omen? 5 Jan
Problem with Rowe 100C Volume 6 Jan
Marvel vs Capcom Video Lockup 7 Jan
ICE Cyclone Fuse Problem 8 Jan
Constructing a Power Up and Power Down Reset Circuit 9 Jan
This Month's Coin Game Puzzle 14 Jan
Let's Start Out the New Year Right! (Pinball Checklist) 16 Jan
Sanyo 20EZ Horizontal Hold & Odd Video Symptoms 18 Jan
Hard Drive Backups - Options 20 Jan
Coin-Op MarketPlace: A Listing of Sales and Services 22 Jan
Betson and State Sales Saga 4 Feb
Betson Laughing, but Few Others Are! 5 Feb
... Lots More to This Story (pt 2) 6 Feb
Sharp Image Dual Sync 27" Monitor Burnt Part 6 Feb
Xbox Users Complain About Defects 7 Feb
Alpine Racer / Alpine Surfer Locking Mechanism 8 Feb
Stern Electric Company Sign Harness Re-dress 12 Feb
This Month's Coin Game Puzzle 14 Feb

Sega Brave Firefighter Nozzle Assembly Parts Advisory 16 Feb

Tommy Liftgate Aluminum Model 17 Feb

Digital Micro CD Player Inop 17 Feb

Irregular Magnetic Cue Balls Common? 18 Feb

Turbo Outrun Motor Switch 19 Feb

ICE Spacey Racer Runaway Moonbeam 20 Feb

Coin-Op MarketPlace: A Listing of Sales and Services 22 Feb

STAR TECH Journal
Volume 24 Index
March 2002 - February 2003

Title / Issue Number

2003 is The Year! 12
Adios Game Machine? 5
Advice Golden Tee Trackball 9
Are You Protected? Sega Gun 8
ASI 2002 Reports Attendance 2
Atari Area 51 Site 4 Locking Up 6
Bench Testing GTI Motor Drive 1
Bench Testing Guns 6
Bestech 29CE Monitor Slo Video 8
California Speed Control Probs 5
Caution: Protect Your Passwords! 1
Cba Meets Oba - a Sad Story 12
CD-100 with CDM-3 Player Probs 9
Chexx Hockey and ICE Fast Track
Air Hockey Maintenance 8
Children's Games Puzzle 10
Coin Drop Game Puzzle 5
Coin-Op Salary Question 3
Connectors - Fixing and Testing 11
Crompton's Replacement Motor 11
Crompton's Soccer Shot Notes 7
Data East Star Trek Lock Up 6
Dealing With Intermittent Probs 9
Digital Micro Jukebox Replacement
CD Player Update 5
Discussing Touch Tunes System 4
Ducksan Monitor - No Picture 5
Ducksan Monitor Shrunk Pix 5
Fisherman's Bait Hardware Errors 8
Fun and Games in Afghanistan 11
Game Industry's Own ENRON? 7
Get Familiar With Your Machines 12
Golden Tee 2003 Impressions 3

Golden Tee Fore Startup 8
Golden Tee Power Failures 4
Golf 2k Upgrade to Golf 4 System
Monitor Width Problem 7
Great Deals? 5
GT Fore Freeze and Reboot Prob 3
Happ Controls Continues Growth 5
How to Start Prize-Based Tourney 11
ICE Chocolate Factory Reliability 7
ICE Chocolate Factory Trap Door 9
Identifying Bridge Rectifiers 10
Improvements to Happ Optical
Guns Increase Reliability 2
Initializing CDs 4
IT & Merit Don't Protect Ops 1
JVL Concorde 3 #0 Error 7
Konami Amusement To Exit USA 6
Konami Dark Silhouette Silent Scope
2 Sighting Problem 9
Konami Fishermans Bait CD 12
Konami Wants In on Triforce 4
Kudos for Merit Tech Support 5
Lethal Enforcer Gun Problems
Troubleshooting 2
Lethal Enforcers Gun Problem 1
Mars Coin Changer Won't Collect 11
MARS Validator LEDs Flash 6x 5
Megatouch Maxx Touchscreen
Double Touch Problem 8
Merit Blue Mega Touch Maxx Power
Supply Start Up 11
Merit Industries Dart 10
Merit Megatouch Fan Noise Kit 2
Merit Megatouch & MAXX Problems
with MARS Bill Acceptors 4
Merit Radion Coin Jam 3
MGC: Longer Charge Life & Eliminates
Acid Damage 1
Midway Touch Screens 7000/8000
Capacitor Warning 10

Midway Touchmaster Flaw 9
Mitsubishi Monitor Adjustment 3
Namco Quick & Crash Sensors 3
Namco Race On Freezing or Not
Powering Up 4
Nanao 27 Daytona Dark Monitor 12
Neotec NT-2702 Horizontal Hold
Symptom/Solution 6
New Life for Your Videogames? 2
New Pinball for Home Market 11
New Touch Monitor from 3M 4
New Wells Gardner Digital 8
O.K. Mfg Gravity Hill Balls 7
Offroad Thunder Blank-Out 4
Online Game Ctrs Zap Arcades 9
Online Oddities: AFL-CIO Arcade 6
Operation Wolf Gun Restriction 7
Pinball Game Puzzle 3
Pinball Game Puzzle 7
Pinball Resets on Location 7
Pool Magnet Cueball Hang-Ups 2
Prize Vendors Puzzle 9
Programming Microcoin S6 11
Quick & Crash Fiber Wire 10
Re: IT & Merit Don't Protect Ops 2
Redemption Game Puzzle 4
Remote Control Coin-Op 5
Replacement Coils Source 5
Replacing 4 x 2114 (VRAM) 5
Rowe BC3500 Quarter Chute 5
Rowe CD-100 Discs Falling Out 1
Rowe CD-100 HCD-1 Hidaway
Rowe-Link Problem 4
Rowe CD-100E Will Not Mute 8
Scud Racer, Manx TT Opto 3
Sega House of the Dead III Mech 12
Sega Initial D Games Steering 12
Sega Manx TT Deluxe Motor Conversion
to Molex Snake 6
Sega Maze of the Kings Sights 7

Sega Nascar Shifter Kit 6
Sega Rally Deluxe Motor Driver and
System Diagrams 12
Setting Up Your Pinball Machines 10
Show Enthusiasm Dissipated 9
Simulator Games Puzzle 11
Singing Monitor Symptom 8
Smart Ticket Center Display 9
Something's Going Down! 11
Sony Working on PlayStation 4
Sports Arena EL Error Display 10
Sports Game Puzzle 6
Sports Games Puzzle 12
Static Electricity Problems 2
Stern Early Production Playboy Pins
Sounds Cut Out 4
Stern Monopoly & Austin Powers
CPU Sound Mod 2
Stern Monopoly Mini Flipper 4
Stern Monopoly Ramp Cover Prevents
Ball Lofting 4
Stern Pin Revisited, Distribs Open
House and Far East Biz 3
Stern Pinball Austin Powers CPU
Game ROM v3.01Bug 6
Stern Pinball P.T.S. Pinball Tournament
System 7
Stern Pinball Playfield Glass Adj 3
Stern Pinball PM Inspection 8
Stern Pinball Tourney System 9
Stern Playboy and RollerCoaster
Tycoon Software Updates 9
Stern Playboy Audio Update 5
Stern Playboy Pinball Adjustable
Outlane Posts 1
Stuff It ? It's Time ! 10
Super Caps vs NiCad Batteries 3
Swapping Merit Monitor Chassis 3
Tales Arabian Nights Magnet Fuse 3
Tekken 4 Lock Up Symptom 5

The Bear Necessities: Bruno 12
The CDM-3 Player Can Be Fixed 11
This Month's Coin Game Puzzle 1
This Month's Coin Game Puzzle 2
Tornado Foosball Rod Lubrication 8
Toshiba Dynamic Convergence 5
Troubleshooting T2 Flipper 6
Updating Cigarette DBVs 6
Updating Cigarette DBVs Update 7
Upgrade VFM5 Stacker Worth It? 2
VirTra Systems Awarded Universe
Control Board Patent 6
Volume 23 Index: Mar '01 - Feb '02 1
Wells Gardner 19K7203 Warning 8
Wells Gardner 27 IT Golf Color 7
Wells Gardner 27D9200 Color 6
Wells Gardner D9200 Error Msg 5
Wells Gardner Type 67 Vertical Fit 12
Wells Gardner Monitors Blanking 10
Wells Garner 19K7 Shutdown 5
What Works for Ops These Days 2
Wico Monitor Buzzing Flyback 8
Williams WPC Flipper Activated
Reset Solution 2
Wonder Wheel Error Payouts 10
Yahoo! Launch Video Game Svc 8

**STAR TECH JOURNAL
VOLUME 25 ARTICLE INDEX
MARCH 2003 - FEBRUARY 2004**

March

Golf Games Face Legal Action 4
Seeburg USCI No Scan Symptom 5
Connectors Fixing and Testing 6
Benchmark Wheel Deal 12Vdc Supply 7
Sega House of the Dead 3 Gun Damage 8
Williams Bally WPC95 Pinball System 10
STJ Volume 24 Index (Mar 02 - Feb 03) 12
Quick Coin Games Puzzle 14
Stern Pinball New ToPS Feature 18
Coin-Op MarketPlace 22

April

Global VR Put Heat On Incredible Technologies 4
MiniDunx Will Not Release Ball Symptom 5
Stern Pinball Simpsons Pinball Party Technician Alerts 6
Problems with Rowe CD100 Sprag Wheel 9
Pinouts and Repair Tips for NRI Coin Mechs 10
Sega Crazy Taxi Rolldown Program Verification 12
Videogame Monitor Pinouts and Standardization 14
Cranes and Rotaries Game Puzzle 14
Midway Hard-Drive Videogames Resetting 15
Rowe Bill Changers BCxx00 Bucket Power On Errors! 16
Centipede/Millipede/Missile Command with Legs 21

May

Sega Merger with Namco? 4
Sega Derby Owners Club DBA Enclosure Mount 6
Stern Pinball Monopoly Fuse F21 Blows 9
Arcade Games from the Inside Out: Crimping Connectors 10
Merit Control Board Installation for MegaTouch Combo 13
Pinball Game Puzzle 14
Merit Blue Maxx Ruby Version Freeze-Up Symptom 15
Rowe Bill Changers BCxx00 Bucket Power-On Errors! (Pt 2) 16
Coin-Op MarketPlace 22

June

Industry News: Little Bits 4
Valleys Great 8 Lifts Interest in Speed Pool 5
Big Step to One US Coin-Op Show 5
Rowe BA-50 Acceptor Lubrication and Cleaning 6
The Bottom Line: Redemption Games 7
Jukebox: Adding an External Sound System 9
Motocross Go! DX System Diagram and Description 10
SMS Crane Claw Coil Replacement 13
Video Kit Game Puzzle 14
Arachnid Galaxy TopGun Dart Game Problem 16
Golden Tee Fore Lock-Up Condition 17
Sports Arena Commission and Win Percentage 17
Hantarex 9000 Monitor Missing Color 18
Williams Whitewater Dropping Memory 21
Coin-Op MarketPlace 22

July

Denials Only Stoke Speculation 4
Rowe CD-100 animation Motor Causing Errors 6
Daytona USA Weird Tracks 9
Stern Terminator 3 Gun Trigger Wiring 10
Wells Gardner D9200 27 Monitor Out of Range 12
Star Trek: NG Lost Ball Symptom 13
Novelty Game Puzzle 14
Aux Power Driver Board Wms / Bally Pinball System 11 16
Tshooting PIA Older MPU Problems 21
Coin-Op MarketPlace 22

August

Industry News: Little Bits 4
A Sad, But True Coin-Op Story 5
Wells Gardner D9200 Out Of Range Message 6
Wells Gardner U2000 / K7400 Changing Chassis 6
Wells Gardner 27D9202 Neck Board In IT Golf 9
American Changer AC2225 Stringing Dollar Bills 10
Rowe/AMI CD100K Main Door Lock 12
Wells Gardner 27 Monitor w/Hitachi CRT for IT Golf 13
Sharp Image Monitor Reversed Picture 13
Dedicated Video Game Puzzle 14

Scud Racer Motor Driver Board Circuitry 16
Rowe/AMI CD100 Replace Mech With MP3 Hard Drive 18
Troubleshooting Wells Gardner D9200 Monitor 21
Coin-Op MarketPlace 22

September

AMOA / Fun Expo Expectations 4
Related to Change... 4
Industry Loses Another Creative Manufacturer 5
Stern T3 Shooter Lane Actuator Adjustment 6
Super Chexx Puck Eject Arm Mod 9
Quick Chart for WPC System Tests Adjustments 10
Stern T3 Software Update Eliminates Reset Problem 12
Video Simulators Game Puzzle 14
Jukebox Discussion: The Legality of CD / HD Replacements 16
Electrohome Monitor Horizontal Cure Fix 21
Coin-Op MarketPlace 22

October

New PCB: State of the Art Platform 4
Rowe CBA-4 Bill Changer Afterlife 5
Time Zone Flipper Reset Problem 6
Coin-Op Observations ala Andy Rooney 7
Common Sense Air Filter Modifications 9
Troubleshooting Merit Megatouch 9
Stern Pinball T3 Auto Launch Wire or Coil Lug Breakoff 10
Golden Tee, Brio and CD Jukebox Tshooting Tips 12
NSM to Mfg and Sell Ecast Digital Juke 13
Rock-Ola Intros Digital Downloading Jukebox 13
Prize Vendors Game Puzzle 14
Rowe CD100A Fadeout Tshooting Checklist 16
JVL Concorde Touchscreen Problem 18
Best Digital Monitor for New Golf Games 19
Wells Gardner 25K7191 Monitor Foldover Symptom 21

November

Cranes Are a Success Story, Right? 4
ICE Soccer Shot Coin Spin Motor 6
Pool Table Rail Adhesive 6
Goldstar 1460 Dart Monitor No High Voltage 7

GT Fore 2003 Board Reset Problem 9
Stern Pinball T3 Software Update / Match Feature 10
Rowe BC-35 to BC-3500 Update Notes 12
Bopping Stomping Games Puzzle 14
Photo Reference Bally/Wms Playfield Switches 16
Rowe CD100A Fadeout Revisited 18
Valley Water Repellant Pool Cloth 21
MarketPlace of Coin Op Services 22

December

Coin-Op Newz: Mergers Not Done Yet 4
250 New Videogames for the Holidays 5
JVL Concorde 2 Countertop Memory Problem 6
Soccer Shot I.C. E. Coin Motor Problems 7
Andamiro Hammer Accuracy Problem 9
Electrohome GO7 Monitor Sync Symptoms 10
SF Rush w/Neotec Monitor Black Level Problem 12
Merit FORCE Fusion Monitor Replacement Procedure 13
Alleys Bowlers Word Puzzle 14
Photo Reference: Wms/Bally Playfield Switches (part 2) 16
MarketPlace of Coin Op Services 22

January

Sammy Backdoors Sega 4
New Parts Source for Jaleco and Taito 4
Terminator 3 Blowing Coil Fuse Fix 5
Lord of the Rings Spanish Display / Speech Available 6
MARS GL5 Bill Acceptor Magazine 9
Stern Pinball T3 Auto Launch Harness Install 10
Troubleshooting Capacitor Hum Symptoms 12
Rowe BC-3500 Bill Changer Fast Dump 13
Alleys Bowlers Word Puzzle 14
Photo Reference: Wms/Bally Playfield Switches (part 3) 16
Stern Pinball Lord of the Rings Tower Eject Learning Mode 18
CarnEvil Gun Calibration Problems 21

February

New Video Games Exercise More Than Thumbs 4
BC3500 Fastpay Bucket Power Error 5
Lord of the Rings Diverter Gate Adjustment Procedure 6

Valley Cue Ball Separator 2-Step Fix 8
Neotec NT2702 27 VGA Monitor Vertical Line 10
Cheap MR-16s Source for Levy Games 11
Happ Intros Universal Video Converter 12
Rowe OBA-2 Acceptance Problem / Solution 13
Coin Drop Games Puzzle 14
Photo Reference: Wms/Bally Playfield Switches (part 4) 16
Dartboard Coin Acceptor Jamming Solution 18
Lighthouse Prize Game Report 21
Medieval Madness Ball Eject Problem Fix 22

Volume 26 Index
March 2004 - February 2005
Title / Issue Number / Page

March

State of Arcade Industry 2004 1/4
Sharp Image Monitor Vertical Roll Symptom 1/6
Touch Tunes Jukebox Remote Repair Tips 1/7
Touch Tunes Jukebox Hard Drive Failure Symptom 1/11
Star Tech Journal Volume 25 March 03 - Feb 04 Index 1/12
Video Simulator Games Puzzle 1/14
Photo Reference: Wms/Bally Playfield Switches (part 5) 1/16
Stern Pinball Lord of the Rings Balrog LED Kit 1/18
Merit I/O Board Replacement FORCE EVO & Fusion 1/21
Sega Derby Owners Club 4 - Player Dimensions 1/22

April

Sega Has High-End Arcade Plan 2/4
Wells-Gardner K7203 High Voltage Squeal 2/5
NSM Conversion CDM 3 / CDM Pro Sound Symptoms 2/6
Component Inventory System Discussion 2/7
Capacitor Testing: Questions & Answers 2/10
Williams The Champion Pub Switch Matrix Problem 2/12
Bopping Stomping Puzzle 2/14
HSV300 Bill Acceptor Calibration Procedure 2/16
Stern Pinball Tournament Compatibility Table 2/18
Speaker Line Impedance Measuring Meter 2/22

May

Future of ASI ??? 3/4
Classic Arcade Games ROM Downloads 3/5
Merit FORCE 2004 Point 5 / Sapphire 2 Update 3/6
Surface Mount Rework Equipt 3/9
Drill-O-Matic Cheat Scheme Discussion 3/10
Bench Testing Dayton Twin Steering Driver Board 3/12
Cranes & Rotaries Puzzle 3/14
Rowe CD-100 Gripper Alignmt 3/17
Collection Tracking Software Discussion 3/18
Wells Gardner U5000 Vertical Deflection Failure 3/21
Wells Gardner Digital Color Monitor Horiz Lines 3/22

June

Sega Sammy to Integrate Operations 4/4
Rowe Starlink Hard Drive Notes 4/4
English Mark Darts Monitor 4/5
Pool Tables: Stretching Cloth 4/6
Electrohome GO7 Black Screen Symptom 4/9
Benchmark Games Offers Drill-OMatic Tips 4/10
The Sega Gun System: Testing LED Boards 4/12
Prize Vendors Games Puzzle 4/14
Police Trainer II Operator Friendly Feature 4/17
Stern Ripleys Believe It Or Not Potential Ball Trap 4/18
How to Read Merit Games Serial Numbers 4/21
Bottom Line: Coin-Op Today 4/22

July

Terrorist Take On The US: Light Gun Coin-Op 5/4
The Incredible Technologies Deal Is On The Nose 5/6
Operator Response To IT Announcement to Sell Direct 5/10
Arcade Game Troubleshooting: Trust Your Senses 5/12
Coin Drop Games Puzzle 5/14
Insertion/Replacement of EPROMS in Stern Pin Games 5/17
Benchmark Gold Zone Ticket Dispense Problem 5/21
Happ Controls Acquired by Pfingsten Partners 5/22

August

Best Gauge Wire For Low Impedance Speakers 6/4
Merit Industries Replacement Hard Drive Pricing 6/5
VendingMiser Savings Worth It? 6/5
Shuffleboards - Opinions 6/6
Ch - Ch - Changes... 6/7
AGE Challenger Candy Crane Instructions 6/9
Coastal Amuse Ghost Catcher 6/10
PGA Golf Monitor Brightness Problem 6/11
Lord of the Rings» Flipper & Magnet Fuse Fatigue 6/12
Video Simulator Games Puzzle 6/14
Nanao MS8-26xx Vertical Collapse Remedies 6/16
The Machines Deserve Better! 6/18

September

WG U5000 Wave Problems 7/4
Global BA NexGen \$20 Update 7/4
Taito Classics Coming From Ultracade 7/4
Treasure Chest Candy Crane Problem 7/5
Online Tech Forum Access 7/5
Daytona Game Board / Sound Board Serial Comm 7/6
Stern Pinball Flipper Evolution 7/12
Merit Dip Switch Settings In Force & Maxx Games 7/14
Telcovision KT-2003V Horizontal Line Symptom 7/16
Rowe BC3500 Fastpay Bucket Power Error 7/17
Kortec Monitors Purity Issue 7/17
Track Ball Problems Discussion 7/18

October

Police Move in on Beetles Game 8/4
Online Tech Forum Registration 8/4
Golden Tee Monitor Scratches 8/6
Cromptons Soccer Shot/Slam Jam Motor Source 8/7
Merit Security Key Chart 8/9
Dance Machines Preference & Maintenance 8/10
Stern Pinball Transformer Compatibility 8/13
Sloppy vs Effective Tshooting 8/14
Harley Davidson Reset Fault 8/16
Touchtunes Coin Jams 8/19

November

JCM American Unveils Landmark Product 9/4
Online Tech Forum Registration 9/4
Flipper Controller Fliptronic II 9/6
Neotec 2781 GT Fore Darkening Screen 9/9
Sega Derby Owners Club Security Notice 9/10
Pump It Up Power Up Symptom 9/11
Nanao MS826SG Colour Probs 9/13
NRI Coin Mech Repair 9/14
Downloading Jukes Discussion 9/16
Sega Universal Gun Kit Cable Pinouts 9/19

December

Rowe BC-35 Programming 10/4
Online Tech Forum Registration 10/4

PGA Golf Kortec Monitor 10/5
Kortex Vertical Deflection Prob 10/6
Rock-ola Bubbler Pages 10/7
Police Trainer Missing Mark 10/9
Pinball 2000/Star Wars Shield Switch 10/10
PGA Golf Trackball Problem 10/13
Sega Card Reader Premature Failure 10/14
Diagnose Old Data East CPU 10/15
Make a Game Popular? 10/19

January

Coin-Op Newz: Golden Tee Goes Live 11/4
STJs Online Tech Forum 11/4
A Push to Restrict Sales of Video Games 11/5
Happ Controls Trackball Used On GT Live 11/6
Wells Gardner 19k7302 Symptoms / Solutions 11/7
Real Coin-Op Game Industry Concerns 11/9
Ripleys Believe It or Not! Pinball Update 11/11
Build A Monitor Test Bench 11/14

February

Real Coin-Op Game Industry Concerns (cont) 12/4
STJs Online Industry Discussion Forum 12/7
Repair & Restoration of Old Damaged PCBs 12/9
Stern Monopoly Pinball Worn Saucer Hole 12/12
Merit Championship Edition Software Bug 12/13
Lighthouse Prize Game 12/14
Wonder Wheel Spin Problem 12/16
WG Coin Switches High Failure Rate 12/17
Killer Instinct Hard Drives 12/18
Nanao MS8-26SU Short HOT 12/19

Star Tech Journal

Post Office Box 35

Medford, NJ 08055 USA

email: info1@startechjournal.com

website: <http://www.startechjournal.com>

STAR TECH Journal

PO Box 35, Medford NJ 08055

<http://www.startechjournal.com>

moinfo@startechjournal.com

VOLUME 27

March 2005 - February 2006

March 2005

Namco and Nintendo Reveal Mario Kart

Rowe R-87 Jukebox Sprag Gear

Online Tech Forum

Lighthouse Prize Game Multi Vend Fix

Volume 26 Index March 03 - February 04

Lord of the Rings Post Upgrade Kit

Arcade Game Monitors vs TV

TouchTunes Makvision 5817ct250 No HiVolts

Wells U5000 Red Line Color Problem

April 2005

The Return of King Pong

Online Tech Forum

Neo Geo Cartridges Not Recognized

Merit Force 2005 & Jade Software Bug

Merit Amusement Game Books Software

Strange System 9 Display Problem

Wells Gardner U2000/K7400 Update Review

8 Valley Pool Table Odd Level Problems

Dance Dance Revolution Mix Mixup

Bally Dr. Who Side Kickers

Hantarex Polo 28 Color Problems

May 2005

Arcades Prosper, May Be Ruled Illegal

Online Tech Forum

Need For Speed GT

Stern Pinball Sopranos Lockdown Assy

Merit Force 2004 Interconnectivity License
New Rowe Download Discussion
Time Crisis Gun Problems
Scared Stiffs Bony Beast
Arachnid Super 6 Plus II Dart Game Freezes
First TouchTunes Installation Advice
Demolition Man Pinball Optics

June 2005

More to Dance Game Than Meets the Feet
Products Invade Games
Arcades Dwindling
Rock-Ola Amp Jack Corrosion
Wells Gardner Digital Monitor Retrace Lines
Restoring a Black Widow Hard Drive
Stern Pinball Sopranos Cabinet Flippers
Plush Palace Prize Sensor Board
Global VR PGA Golf Glass Display Fix
Ceronix Monitor Dangerous Problem
Golden Tee Fore Intermittent Resets

July 2005

First Video Game for Multi-Layer Display
Sega Universale Gun Pinout Instructions
Merit Texas Hold 'Em Installation Notes
PGA Tour/Madden NFL DBA Ground Error
Rock-Ola Speaker Lines to BGM Inputs
Wells Gardner Pinball Monitor Replacement
House of Dead/Lost World Gun Sense Board
Need for Speed Audio Amp/Game Freeze
Stern Pinball New Sound Operating System
Star Tech Journal on CD-Rom Latest Version

August 2005

Sega Lobbies MN on Arcade Horse Racing
Adult Gaming Machines Declared Legal
Tekken 5.1A Revision Hits the Arcades
JAMMA Pinout Harness Connections

Merit Switches from CD to DVD Software
Benchmark Ticket Station Woes
Silent Scope – The Scope LCD Display
Video Card, Edge Connector Cleaning
LED Sign and Logic Board Modification
PGA Golf/Need for Speed Power Plate Wiring
Wells Gardner Retrace Lines Cap Fix
Gottlieb Stargate System 3 Symptoms

September 2005

Sega Prez Comments on Coin-Op Industry
Sega New Arcade Lineup Shown At JAMMA
JAMMA 2005: Sega Chihiro Games
JAMMA 2005: Hands On w/Mario Kart
Terminator 2 U111 Bad ROM Warning
Kristal Monitor Pinouts & Geometry Adjusts
Lets Talk Golf Games
Arctic Thunder Steering Cal & Blown Fuses
Arachnid Bullshooter Darts HotButton Kit
What's Next For Coin-Op?
Pentranic Monitor Shutdown
Merit Has Your Back... Door

October 2005

The U.S. \$10 Bill Gets a Makeover
JCM Reveals Optipay BV At AMOA Tradeshow
Nintendo Mario Kart Arcade GP to America
Stern NASCAR Backbox Opto Connector
MARS Bill Acceptor Belt Replacement
Stern NASCAR T-Nut Cover & Foam Kit
Merit I/O Board Replacement in Ion Games
Neotec 2701 Power Up Troubleshooting
Wheel Em In Bad Ticket Vend
Stern NASCAR Pinball Setup Notes
Capacitor Sources and Notes
MEI 10 Helpful Hints VN-4510 Coin Changer

November, 2005

Beetle Mania Takes Hold
Merit Megatouch Champ I/O Board
Target Stores to Sell Arcade Games
Compatible Golden Tee LIVE DVD Drives
Wells Gardner K7200 Typical Voltages
Stern Pinball NASCAR Target
Rock-Ola Downloading Jukeboxes
Arachnid Comm Quick Reference
Merit Dip Switch Settings Ion, Force, Maxx

December, 2005

Sega Tries US Arcade Comeback
Game Infringement: Sega Takes on Taito
Merits New Serial Number Format
Sega Derby Club Security Notice
Wells Gardner 27 Losing One Color
ICE NASCAR Kiddie Ride Reset Fix
Merit I/O in Ion, Money Shoot & Megatouch
Rock Ola Version 2.4.2.7 Audio Configuration
Wells Gardner D9200 27 Out Of Range
Wells Gardner 27 Monitor CRTs For I.T. Golf
Sega Card Reader Premature Failure
Merit Ion & Force 2006 Slow Screens
Merit Ion & Force 2006 Software Upgrade

January 2006

Videogames: a Forecast
JCM Files Infringement Suit vs MEI
Arachnid Galaxy I No Video Symptom
Merit I/O Board Replacement Update
GlobalVR Online Cabinets Dial-Up Link
Rock-Ola 6000 Title Page Lights Burning Out
Stern NASCAR Scoop Mod & Bracket Update
IT: Hard Drive Handling Notice
Merit Platinum Reset Problem
Arachnid Dartman Fix for Template Issue
GT Fore 2005 Freezing After GT Update
Discussion: 90 Day Warranty

Discussion: Mfg Revenue Sharing

February, 2006

Using Plastic In The Arcade

Sega House of Dead 4 Top Earner

Sega Moves to New Modernized Offices

Ecast Abandons Countertops

Neotec 2701 Horizontal Width Control

Wells Gardner Pinball Monitor Replacement

Arachnid Darts Daewoo Monitor Deflection IC

Wells Gardner 7302 / Happ MTG-XX01 No Pix

Global VR Need For Speed Loose Seat Mod

Stern Pinball Generic Coil Chart

Stern Pinball Flipper Coil Chart

Stern Pinball Motor Spec Table

Rock-Ola Ballast Noise Problem

Claim Jumper w/Electronic Acceptors

Do Auctions Set Real Game Values?